



NUCLEAR REGULATORY COMMISSION
REGION III
755 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

June 18, 1979

Docket No. 50-483
Docket No. 50-486

MEMORANDUM FOR: Region III Files
THRU: R. C. Knop, Chief, Projects Section 1
FROM: W. A. Hansen, Projects Inspector
SUBJECT: CALLAWAY COOLING TOWER CONCRETE

On May 3 and on May 4, 1979, I contacted Mr. R. Powers, Site Quality Assurance Group Leader for Union Electric Company, to discuss the concrete work being performed on the Callaway Nuclear Plant Cooling Tower.

On May 3, he informed me that since the cooling tower was not safety related his staff was not following the work being performed. He stated that since the problem was identified that an engineer from the Union Electric engineering group was assigned to follow the progress of the work.

On May 4, 1979 I called Mr. Powers to ask if any inspectors either employed by Daniel International or Union Electric was involved with the concrete work being performed to build the cooling tower. Mr. Powers stated that Daniel International inspectors were at the concrete delivery point to test the concrete but that neither Daniel or Union Electric had QC inspectors following the work. Union Electric had assigned an engineer earlier in the week but had assigned no inspector.

W. A. Hansen, Reactor Inspector
Projects Section No. 1

8503040264 841119
PDR FOIA
VARRICC84-701 PDR