## ENCLOSURE 1

## NOTICE OF VIOLATION

Mississippi Power and Light Company Grand Gulf Docket No. 50-416 License No. NPF-29

The following violation was identified during an inspection conducted on October 21 - November 19, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 3.7.7.a requires a continuous fire watch be established on at least one side of an inoperable fire rated assembly within one hour of the assembly being determined inoperable.

Contrary to the above, on November 7, 1984, it was discovered that electrical raceways which did not have the proper fire barrier installed and in an area with inoperable fire detection, did not have a continuous fire watch. The missing fire barriers were discovered on October 15, 1984, and confirmed on November 2, 1984, by the plant's Nuclear Engineering Department.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

DEC 1 8 1984

Date:

DEC 1 8 1984

Mississippi Power and Light Company 2

cc w/encls: J. E. Cross, General Manager R. T. Lally, Manager of Quality Middle South Services, Inc. R. B. McGehee, Esquire Wise, Carter, Child, Steen and Caraway N. S. Reynolds, Esquire Bishop, Liberman, Cook, Purcell & Reynolds R. W. Jackson, Project Engineer

bcc w/encls: NRC Resident Inspector Document Control Desk State of Mississippi

See See



