

OCT 22 1984

ENCLOSURE 1

NOTICE OF DEVIATION

Florida Power Corporation
Crystal River Unit 3

Docket No. 50-302
License No. DPR-72

The following deviation was identified during an inspection conducted on September 1 - 27, 1984.

A letter to the Nuclear Regulatory Commission from Florida Power Corporation dated May 18, 1984, responded to the violation identified in NRC Inspection Report 50-302/84-09 and stated the applicable calibration procedures would be revised to include the cited computer points. This response concluded that these revisions would be completed by July 31, 1984.

Contrary to the above, procedure SP-113, which provides calibration for the reactor power computer point, was not revised until September 13, 1984 and procedure SP-112, which provides calibration for the RCS average temperature computer point, was not revised as of September 27, 1984.

Please provide, in writing within 30 days of the date of this Notice, a description of corrective actions regarding these deviations, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

8503050213 850205
PDR ADOCK 05000302
Q PDR