



Tennessee Valley Authority, Post Office Box 25, J. Saddy-Daisy, Tennessee 37379

J. L. Wilson
Vice President, Sequoyah Nuclear Plant

August 31, 1992

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Gentlemen:


TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - LICENSEE EVENT REPORT
(LER) 50-328/92007, REVISION 1

This submittal supersedes our submittal to you dated August 21, 1992, and
includes the revision bars that were inadvertently omitted.

The enclosed LER is being revised to update a corrective action
associated with this event. The LER concerns the entry into Mode 4
operation without two operable containment spray systems. The event was
reported in accordance with 10 CFR 50.73(a)(2)(i)(B) as an operation
prohibited by technical specifications and 10 CFR 50.73(a)(2)(vii)(D) as
an event where a single condition caused two independent trains of a
system designed to mitigate the consequences of an accident to become
inoperable.

Revisions to the LER are annotated by vertical bars in the right-hand
margin.

Sincerely,


J. L. Wilson

Enclosure
cc: See page 2

080127

9209140290 920831
PDR ADDCK 0500032B
S PDR

LEP
||

U.S. Nuclear Regulatory Commission
Page 2
August 31, 1992

cc (Enclosure):

INPO Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. D. E. LaBarge, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

NRC Resident Inspector
Sequoyah Nuclear Plant
2600 Igou Ferry Road
Soddy-Daisy, Tennessee 37379

Mr. B. A. Wilson, Project Chief
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323