

January 23, 1985

DMB 016

Docket No. 50-²⁸⁹302

MEMORANDUM FOR: Richard Starostecki, Director
 Division of Reactor Safety and Projects, Region I

FROM: Darrell G. Eisenhut, Director
 Division of Licensing

In response to TIA 84-73, dated September 11, 1984, TMI-1 Missing OTSG Plugs, we are enclosing our SER addressing items 1, 2, and 3 of the action plan therein, which are as follows:

1. Evaluate GPUN programs to identify and correct defective W rolled plugs.
2. Evaluate safety aspects of GPU plugs for operation with loose/missing W rolled plugs.
3. Preparation of NRR safety evaluation prior to restart.

This completes NRR action on this TIA. If there are any questions on this matter, please contact Harley Silver at 492-7900.


"ORIGINAL SIGNED BY:"

Darrell G. Eisenhut, Director
 Division of Licensing


Enclosure:
 As stated


DISTRIBUTION:


- Docket File
- NRC PDR
- L PDR
- HSilver
- JStolz
- GLainas
- TMI-1 Service List
- WJohnston
- LRubenstein



 ORB#4:DL
 HSilver;cf
 1/17/85

ORB#4:DL
 JStolz
 1/17/85


 AD:OR:DL
 GLainas
 1/17/85


 DE
 WJohnston
 1/17/85


 DSI
 BE
 LRubenstein
 1/17/85


 DE
 Eisenhut
 1/17/85

8502010796 850123
 PCR ADOCK 05000289
 P PDR