




GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775
AREA CODE 504 635-3237 387-4257

January 17, 1985
RBG- 19913
File Nso. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Martin:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-236

Gulf States Utilities Company (GSU) has completed its evaluation of DR-236 concerning gouges and linear indications on piston wrist pins in the standby diesel generator 1EGS*EG1B supplied by Transamerica Delaval, Incorporated. Since the structural integrity of the wrist pins is not impaired by this condition, GSU has therefore determined this condition is not reportable under 10CFR50.55(e). The wrist pins were replaced in accordance with Nonconformance and Disposition Report No. 6978.

Sincerely,

for L. G. England

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Liscensing
River Bend Nuclear Group

PJD
JEB/PJD/trp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8502040215 850117
PDR ADDCK 05000458
S PDR

IE-27 10