


POST OFFICE BOX 2951 · BEAUMONT TEXAS 77704


AREACODE 409 838 6631

January 23, 1985 RBG-19959 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:





An interim or final status report concerning uninterruptible power supply inverters supplied by Elgar Corporation will be provided by February 7, 1985.

Sincerely,

L.a. England

J. E. Booker

Manager-Engineering,

Nuclear Fuels & Licensing

River Bend Nuclear Group

JEB/PJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8502070123 850123 PDR ADDCK 05000458 S PDR