



Gilbert/Commonwealth engineers and consultants

GILBERT ASSOCIATES, INC., P. O. Box 1492, Reading, PA 19603/Tel. 215 775-2600/Cable Gilasoc/Telex 836-431

June 30, 1983

N. R. BARKER
Vice President and General Manager
Quality Assurance Division

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Washington, DC 20555

Attention: Mr. R. C. DeYoung

Re: Reportable Event
Automatic Restart of Chillers

Dear Mr. DeYoung:

Our April 29, 1983, letter to the NRC indicated that the P-47 chillers on the Perry Nuclear Power Plant do not have automatic re-start features after a loss of off-site power (LOOP). In that letter this item was considered potentially reportable. We have completed evaluation and have concluded that it is reportable under the provisions of 10 CFR Part 21.

Evaluation of applicability to other safety related systems on the Perry Project is being assessed during the continuing process of system finalization. Any similar instances identified in this process will be corrected.

If you require any further information on this matter, please contact me at (215) 775-2600, Extension 7545.

Very truly yours,

N. R. Barker
Vice President and General Manager
Quality Assurance Division

50-440,444

NRB:bmk

cc: H. Lorenz
T. M. Demers
R. C. DeYoung - 2
U. Potapovs - NRC Region IV
Document Management Branch

8307070001 830630
PDR ADDCK 05000440
S PDR

IE 19
/0