YES lack UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 789 COOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137 Docket No. 50-346 Centerior Service Company ATTN: Mr. Donald Sheltor Vice President Nuclear - Davis-Besse c/o Toledo Edison Company 300 Madison Avenue Toledo, OH 43652 Dear Mr. Shelton: This refers to the inspection conducted by Messrs. W. Levis, R. K. Walton, and J. A. Gavula of this office on August 4, 1992, through September 14, 1992, of authorized activities for your Davis-Besse Nuclear Power Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report. Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. No violations of NRC requirements were identified during the course of this inspection. In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room. We will gladly discuss any questions you have concerning this inspection. Sincerely, Reactor Projects Section 3A Enclosure: Inspection Report No. 50-346/92013(DRP) See Attached Distribution JE06. CC .,enclosures:
L. Storz, Plant Manager
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector, RIII
James R. Williams, State of Ohio
Robert E. Owen, Ohio
Department of Health
A. Grandjean, State of Ohio,
Public Utilities Commission