

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775 AREA CODE 504 635-3237 387-4257

> January 30, 1985 RBG-20010 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

FEB - 4 1985

Dear Mr. Martin:

RIVER BEND STATION UNIT I DOCKET NO. 50-458 FINAL REPORT/DR-208

Gulf States Utilities Company (GSU) has completed its evaluation of DR-208 concerning a pipe support clamp supplied by Bergen Paterson that was installed with a surface-to-surface C dimension of 1 inch instead of 7/8 inch as required by the vendor. Since the as-installed clamp would not have compromised the load capacity of the part, GSU concludes this condition is not reportable under 10CFR50.55(e). However, Nonconformance and Disposition Report No. 5835 was issued to install two 1/16-inch thick washers on the part.

Sincerely,

L. a. England

J. E. BOOKER Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

PJD JEB/PJD/cem

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8502110443 850130 PDR ADOCK 05000458

IE-27