

POST OFFICE BOX 2951 . BEAUMONT. TEXAS 77704

AREA CODE 409 838 6631

February 5, 1985 RBG- 20,081 File No. G9.5, G9.8.1.2

Mr. Harold R. Denton, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Denton:

River Bend Station - Unit 1 Docket No. 50-458

Provided below for your review is Gulf States Utilities Company (GSU) revised response to Confirmatory Item (30) of Table 1.4 of the Safety Evaluation Report. This letter provides revised information from our letter submittal dated November 30, 1984 from J. E. Booker to H. R. Denton (RBG-19600).

The surveillance of the Engineered Safety Feature Unit Coolers will be added to the operations daily log. The operator performing the surveillance will verify that the unit cooler is operating by ascertaining that there is air flow through the unit cooler. The bases for this type of surveillance is to detect failures which may have otherwise gone undetected. The surveillance will include the following units:

1HVC*ACU1A 1HVC*ACU1B 1HVC*ACU2A 1HVC*ACU2B 1HVC*ACU3A 1HVC*ACU3B 1HVR*UC1A, 1B 1HVR*UC2 thru 10 1HVR*UC11A, B

Sincerely,

fa J. E. Booker

Manager - Engineering Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/WJR/JEP/je

8502120170 850205 EDR ADDCK 05000458