TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

34 SEP 26ptemper 318, 1984

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - SUPPLEMENTAL RESPONSE TO VIOLATION 50-438/84-12-01, 50-439/84-12-01 - FAILURE TO FOLLOW PROCEDURES FOR HANGER INSPECTIONS

TVA is submitting this letter in response to a request for clarification made by NRC-OIE Inspector S. Weise on September 13, 1984 concerning our August 31, 1984 response to D. M. Verrelli's letter dated July 18, 1984. In Part (A) Section 3, Corrective Steps Taken and Results Achieved of the subject letter, TVA had stated "The disposition of the cited welds was documented on February 3, 1984 " Please note that although the cited welds were listed on an internal TVA memorandum on February 3, 1984, the revision of Nonconformance Report 1968, which documented the condition, was accomplished on July 12, 1984.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Licensing

oc: Mr. Richard C. DeYoung, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339