

ENCLOSURE 1

NOTICE OF VIOLATION

Tennessee Valley Authority  
Bellefonte Units 1 and 2

Docket Nos. 50-438 and 50-439  
License Nos. CPPR-122 and CPPR-123

The following violation was identified during an inspection conducted on May 1 - June 30, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criterion V, as implemented by Bellefonte FSAR Section 17, paragraph 17.1A.5, requires that activities affecting quality be accomplished in accordance with documented procedures. Bellefonte QCP-7.5 and QCP-6.17 provide the procedures and acceptance criteria for welding and dimensional inspections of hangers.

Contrary to the above, activities affecting quality were not being accomplished in accordance with QCP-7.5 and QCP-6.17 in that a reinspection of fourteen hangers revealed two hangers did not meet the documented welding acceptance criteria, and two other hangers did not meet the documented dimensional inspection criteria.

This is a Severity Level V violation (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date:     JUL 18 1984    

8410240271 840924  
PDR ADOCK 05000438  
Q PDR