

ENCLOSURE 1

NOTICE OF VIOLATION

Virginia Electric and Power Company  
North Anna

Docket Nos. 50-338 and 50-339  
License Nos. NPF-4 and NPF-7

The following violations were identified during an inspection conducted on June 6 - July 5, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1.c requires that written procedures be established, implemented, and maintained covering surveillance and test activities of safety-related equipment.

Contrary to the above, on June 12, 1984, EMP-P-RT-30 "Protective Relay Maintenance for Breaker 15H2 Emergency Supply to Bus '1H' and EMP-P-RT-38" Protective Relay Maintenance for Bus '1H' were not followed in that, numerous steps in these procedures were not signed as verified or completed. The failure of the licensee's authorization and control personnel to follow procedures is a repeat violation.

This is a Severity Level IV violation (Supplement I), and applies to both units.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUL 30 1984

B410240407 B40927  
PDR ADOCK 05000338  
Q PDR