October 2, 1984

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Richard P. Crouse
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by S. Rozak and A. Januska of this office on September 10-14, 1984, of activities at Davis-Be se Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. Scott at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. In addition, our Mobile Laboratory was at the site during the inspection to perform independent measurements of radio-activity.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

The inspectors did observe a problem with low air flow in laboratory fume hoods that could present a safety hazard. See Section 5 of the enclosed report. Please respond within thirty days of the receipt of this letter as to what action will be or has been taken to restore air flows to within acceptable limits.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure(s) will be placed in the NRC Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1). If we do not hear from you in this regard within the specified periods noted above, a copy of this letter, the enclosure(s), and your response to this letter will be placed in the Public Document Room.

1E:06

B410240431 B41002 PDR ADOCK 05000346 PDR

1

The response directed by this letter is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely:

L. R. Greger, Chief

Emergency Preparedness and

Radiological Protection Branch

Enclosure: Inspection Report No. 50-346/84-21(DRSS)

cc w/encl:
T. D. Murray, Station
Superintendent
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert H. Quillin, Ohio
Department of Health