

**DUKE POWER COMPANY**

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4521

October 10, 1984


Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Subject: McGuire Nuclear Station  
Docket No: 50-369/370  
LER 369/84-22

Gentlemen:

The subject Licensee Event Report (LER), dated August 20, 1984, described a design deficiency in the area of seismic qualification of certain fire protection and drain piping serving the Control Room. The LER also described a planned modification which will rectify the situation. The design of this modification will be completed by November 1, 1985, with implementation to follow as soon as practicable thereafter.

Very truly yours,



Hal B. Tucker

SAG/mjf

cc: Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission-Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30323

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. T. Orders  
Senior Resident Inspector  
McGuire Nuclear Station

8410240457 841010  
PDR ADOCK 05000369  
S PDR

IE22  
/0