RELATED CORRESPONDENCE

HUNTON & WILLIAMS

2000 PENNSYLVANIA AVENUE, N.W.

P.O. Box 19230

707 EAST MAIN STREET P O. BOX 1535 RICHMOND, VIRGINIA 23212 TELEPHONE BOA-78B-8200 TWX 710-956-0061

FIRST VIRGINIA BANK TOWER
P. O. BOX 3889
NURFOLK, VIRGINIA 23514
TELEPHONE 804 625-5501
TELEX 755628

 WASHINGTON, D.C. 20038

TELEPHONE 202 955 1500 85 FEB -8 P3:34

February 6, 1985

299 PARK AVENUE NEW YORK, NEW YORK 10171 TELEPHONE 212-980-8200 TELEX 754708

B B & T BUILDING P O BOX 109 PALEIGH, NORTH CAROLINA 27602 TELEPHONE 919 828 9371

FIRST TENNESSEE BANK BUILDING
P. O. BOX 951
KNOXVII. E. TENNESSEE 37901
TELE HONE 615-637-4311
24566.3

FILE NO

DIRECT MAL NO. 202 955 8453

BY HAND

Lawrence Brenner, Esq.
Dr. Peter A. Morris
U.S. Nuclear Regulatory Commission
4350 East-West Highway
Fourth Floor (North Tower)
Bethesda, Maryland 20814

PROD & UTIL FAC.

Dr. George A. Ferguson School of Engineering Howard University 2300 6th Street, N.W. Washington, D.C. 20555

Dear Judges:

The following two typographical errors of omission should be corrected in LILCO's Motion to Strike the Testimony of Dale G. Bridenbaugh and Gregory C. Minor Regarding Suffolk County's Emergency Diesel Generator Load Contention, dated February 1, 1985:

Page 10, footnote 3, the quote inadvertently omitted the word "error." The quote should read as follows:

The designer shall consider an operator error as a potential single active failure.

Page 11, four lines from the bottom, the word "not" was inadvertently omitted. The sentence should now read as follows:

8502130008 850206 PDR ADOCK 05000322

DS63

HUNTON & WILLIAMS

February 6, 1985 Page 2

There is no regulatory requirement that a plant must be designed to meet the single failure criterion when the limiting conditions for operation set forth in the technical specifications are not met.

Respectfully,

S. Ellis, III

75/403

cc: Service List