

OCT 02 1992

DcD
DcB Rids

Docket No. 50-282
Docket No. 50-306

Northern States Power Company
ATTN: Mr. L. R. Eliason
Vice President, Nuclear
Generation
414 Nicollet Mall
Minneapolis, MN 55401

Dear Mr. Eliason:

This refers to the routine safety inspection conducted by Messrs. M. Dapas, D. Kosloff, and others of this office from July 21 through September 14, 1992, of activities at the Prairie Island Nuclear Generating Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60, and to the discussion of our findings with Mr. M. B. Sellman and other members of your staff at the conclusion of the inspection. This also refers to the routine management meeting conducted at the Region III office on August 13, 1992.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a) of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original signed by
Edward L. Schweebing
B. L. Jorgensen, Chief
Reactor Projects Section 2A

Enclosure:
Inspection Reports
No. 50-282/92015(DRP);
No. 50-306/92015(DRP)

See Attached Distribution

BCC: D. FUNK
T. KOBETZ

RIII
Bywater
10/1/92

4B
RIII
Jacobson
Jacobson
Para. 7

RIII
Snell
Snell
Para. 6
10/2/92

RIII
Jorgensen
Jorgensen
10-2-92

IEO/
41



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

OCT 6 1992

Docket No. 50-282
Docket No. 50-306

Northern States Power Company
ATTN: Mr. L. R. Eliason
Vice President, Nuclear
Generation
414 Nicollet Mall
Minneapolis, MN 55401

Dear Mr. Eliason:

This refers to the routine safety inspection conducted by Messrs. M. Dapas, D. Kosloff, and others of this office from July 21 through September 14, 1992, of activities at the Prairie Island Nuclear Generating Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60, and to the discussion of our findings with Mr. M. B. Sellman and other members of your staff at the conclusion of the inspection. This also refers to the routine management meeting conducted at the Region III office on August 13, 1992.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a) of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Edward F. Schweibing
for B. L. Jorgensen, Chief
Reactor Projects Section 2A

Enclosure:
Inspection Reports
No. 50-282/92015(DRP);
No. 50-306/92015(DRP)

See Attached Distribution

Northern States Power Company

2

Distribution:

cc w/enclosure:

E. L. Watzl, Site Manager,
Prairie Island Site

M. Sellman, Plant Manager

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

Resident Inspector, RIII Monticello

John W. Ferman, Ph.D.,

Nuclear Engineer, MPCA

State Liaison Officer, State
of Minnesota

Prairie Island, LPM, NRR

Robert M. Thompson, Administrator

Wisconsin Division of Emergency
Government