

APPENDIX A

NOTICE OF VIOLATION

Nebraska Public Power District  
Cooper Nuclear Station

Docket: 50-298/84-15  
License: DPR-46

Based on the results of an NRC inspection conducted during the period of July 1-August 31, 1984, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 49 FR 8583, dated March 8, 1984, the following violation was identified:

1. Failure to Perform Accurately a Part of Technical Specification Required Surveillance Test 6.2.4.1

Cooper Nuclear Station Technical Specification, Section 3.4.C.2 states, "The temperature of the liquid control solution shall be maintained above the curve shown in Figure 3.4.2." CNS Surveillance Procedure 6.2.4.1, Attachment A, page 13 of 15, is performed to ensure that liquid control system solution temperature is within the limits specified on Technical Specification, Figure 3.4.2.

Contrary to the above, on July 18, 1984, licensee personnel entered an incorrect value of liquid control solution temperature onto the blank provided in Surveillance Procedure 6.2.4.1. The licensee did not recognize that the incorrect value of liquid control solution temperature did not meet the minimum requirement of Technical Specification, Figure 3.4.2.

This is a Severity Level IV Violation. (Supplement I.D) (298/8415-01)

Pursuant to the provisions of 10 CFR 2.201, Nebraska Public Power District is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

OCT 19 1984

Dated: \_\_\_\_\_

8410250160 841019  
PDR ADDCK 05000298  
G PDR