Arizona Public Service Company

1984 OCT 22 AN ID: 14

REGION VINE

October 17, 1984 ANPP-30873-TDS/TRB

U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Director

Division of Reactor Safety and Projects

Subject: Time Extension For Report - DER 84-58

A 50.55(e) Potentially Reportable Deficiency Relating To Auxiliary Feedwater System Solenoid Valve Failed To Open In

Response To AFAS Signal. File: 84-01)-026; D.4.33.2

Reference: (A) Telephone conversation between J. Ball and T. Bradish on August 8, 1984

(B) ANPP-30449, dated September 6, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by October 19, 1984.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by October 30, 1984, at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr. APS Vice President Nuclear Production ANPP Project Director

EEVB/TRB/nj

cc: See Page Two

16-27

Mr. T. W. Bishop DER 84-58 Page Two

cc:

8

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

L. A. Souza

D. E. Fowler

T. D. Shriver

C. N. Russo

J. Vorees

J. R. Bynum

J. M. Allen

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

R. P. Zimmerman

L. Clyde

M. Woods

T. J. Bloom

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339