



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

October 8, 1984

MURRAY R. EDELMAN
VICE PRESIDENT
NUCLEAR

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

RE: Perry Nuclear Power Plant
Docket Nos. 50-440; 50-441
Significant Deficiency
Concerning Anchor Darling
Globe Valves (RDC 88(84))

Dear Mr. Keppler:

As stated in our letter to you dated January 27, 1984, the corrective action taken to correct a defect in the antirotational setscrew on four Anchor Darling Globe Valves was to be completed for all affected valves by September 15, 1984. While repairing the remaining two valves, it was discovered that replacement valve stem keys supplied by Anchor Darling for use in these two valves were oversized. As a result, the stem collar could not be placed on the valve, delaying implementation of our corrective action. It is now anticipated that the corrective action for all valves will be completed by October 26, 1984.

Please contact us if you have any question.

Sincerely,
M. R. Edelman
Murray R. Edelman
Vice President
Nuclear Group

MRE:pab
cc: Mr. J. A. Grobe
NRC Site Office

Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

U.S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, D.C. 20555

Records Center, SEE-IN
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8410260179 841008
PDR ADOCK 05000440
S PDR

OCT 10 1984

FE27 1/0