


October 12, 1984 RBG- 19153 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-246



An interim or final status report concerning a linear indication on a Benjamin F. Shaw shop weld found during Pre-service Inspection of a spool piece for the RHR system will be provided by December 18, 1984.

Sincerely,

L. J. E. Booker

Manager-Engineering,

Nuclear Fuels & Licensing River Bend Nuclear Group

JEB//JD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8410260268 841012 PDR ADDCK 05000458 PDR IE-27