

Docket No. 50-288

SEP 27 1984

Aerotest Operations, Inc.  
3455 Fostoria Way  
San Ramon, California 94583

Attention: Mr. Richard Newacheck  
President

Gentlemen:

Subject: NRC Examinations

On August 28, 1984, the NRC administered examinations to an employee of your company who had applied for licenses to operate your Aerotest Radiography and Research Reactor.

As a result of this examination the Candidate was found to not meet the minimum qualification requirements for licensing.

At the conclusion of the examinations on August 28, 1984, the examination and preliminary findings were discussed with members of your staff as detailed in the enclosed report.

Sincerely,

Original signed by  
R. J. Pate

Robert J. Pate, Chief  
Reactor Safety Branch

Enclosures:

- 1. Examination Report  
No. 50-288-OL/84-01
- 2. Written Examination and Answer Key (SRO)
- 3. Plant Review of Key

cc w/o enclosures:

John Elin, Operator Licensing Examiner

bcc: RSB/Document Control Desk (RIDS)

Distributed by RV:

Mr. Martin, RV  
State of California

ELIN *JE*  
9/27/84

PATE *RP*  
9/27/84

1E07

8410290008 840927  
PDR ADDCK 05000288  
G PDR

11