




KANSAS GAS AND ELECTRIC COMPANY

GLENN L KOESTER  
VICE PRESIDENT - NUCLEAR

October 8, 1984

Mr. D.R. Hunter, Chief  
Reactor Project Branch 2  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



KMLNRC 84-176  
Re: Docket No. STN 50-482  
Ref: Interim Report KMLNRC 83-161 dated 12/7/83  
from GLKoester, KG&E, to JEGagliardo, NRC  
Subj: Interim Status Report for Wolf Creek  
10CFR50.55(e) Items

Dear Mr. Hunter:

Attached is a copy of Kansas Gas and Electric Company's status report for September, 1984, on 10CFR50.55(e) items. The format and purpose of this report were described in the Reference.

Please contact me or Mr. Otto Maynard of my staff if you have any questions concerning this subject.

Yours very truly,

*Glenn L Koester*

GLK:bb  
Attach  
xc:RCDeYoung, w/a  
PO'Connor, w/a  
HBundy, w/a

8410290055 841008  
PDR ADOCK 05000482  
S PDR

*IE-27*  
*11*

Status Report

On

10CFR50.55(e)/Part 21 Open Items

September 28, 1984

- I. Legend
- II. Status of KG&E Reported Items
- III. Status of SNUPPS Reported Items

## I. LEGEND

- File: QA Record File Number
- Title: Title or Subject Matter
- Date Reported: When Deficiency Was Initially Report to the NRC
- ST: Status
- O - Open: Concern has not been resolved.
  - F - Final Report has been submitted but corrective action has not been completed or close-out documentation has not been through; final review.
  - R - Ready for RRI Review - All corrective actions completed or evaluation has determined that item is not reportable pursuant to 50.55(e)/Part 21.
  - C - Closed: RRI has reviewed and close-out of the concern or item is N/A to WCGS.

II. Status of Significant Deficiencies Report by KG&E

FILE	TITLE	DATE REPORTED	S	NEXT RPT DUE DATE	NRC CLOSE	REMARKS
53564-K001	GENERAL INFORMATION					
53564-K002	UNISTRUT WELDS	79/01/05	C	79-07		
53564-K003	BASEMAT	78/10/26	C	81-19		
53564-K004	VOID-6TH LIFT	78/12/15	C	79-18		
53564-K005	ESWS VALVE OPERATOR (DAM-AGED)	79/02/15	C			NOT REPORTED AS POTENTIAL SC.55(E) - SHOULD NOT HAVE BEEN GIVEN A 53564 NUMBER.
53564-K006	FIREPROOFING (ALBI-DURA-SPRAY)	79/02/26	C	80-02		
53564-K007	G&W PIPE ASSEMBLY WELDS	79/03/29	C	82-09		
53564-K008	ESWS PUMP ANCHOR BOLTS	79/04/23	C	80-18		
53564-K009	FLOOD DAMAGE	79/05/08	C	83-04		
53564-K010	CHARGING PUMP MOTOR BEARING	79/03/29	C	81-19		
53564-K011	GE TYPE SB-12 SWITCHES	79/07/13	C	81-02		
53564-K012	BORG WARNER 2 INCH LIFT VALVES	79/07/27	C	80-18		
53564-K013	G&W WATER COOLANT COMPONENT	79/03/23	C	81-02		
53564-K014	UNISTRUT P1331 BRACKETS AND BOLT	79/09/14	C	80-18		
53564-K015	CROSBY RELIEF VALVES 1/2-3/4	79/09/18	C	81-02		
53564-K016	NEMA-3 STARTERS	79/09/19	C	82-09		
53564-K017	SWAY STRUT BUSHINGS (CORNER AND LADA)	79/11/08	C	83-21		
53564-K018	EMBED PLATE AND NUTS	79/11/05	C	81-19		
53564-K019	FUEL POOL LINER PLATES	79/11/06	C	82-09		
53564-K020	3/2 INCH NUTS-IMPROPER THREADS	79/11/27	C	80-18		
53564-K021	MAIN STEAM ISOLATION VALVES	79/12/14	C	81-19		

LIMIT SWITCH

53564-K022	STAYLOCK FASTENERS	79/12/19 C	80-13
53564-K023	POLAR CRANE RAIL	80/01/05 C	80-04
53564-K024	TINIUS-OLSON TEST MACHINE	80/01/07 C	81-02
53564-K025	STICKEY GE RELAYS	80/01/11 C	81-02
53564-K026	MASONRY WALLS-MISALIGNED REBAR	79/12/19 C	84-03
53564-K027	G/W FEEDWATER TORSIONAL RE- STRAINT	80/01/23 C	81-02
53564-K028	WESTINGHOUSE 7500 SERIES I&C CARDS	79/08/23 C	80-13
53564-K029	FOXBORO CONTROLLERS	80/02/08 C	81-02
53564-K030	BUNKER RAMO AMPHENOL EPA'S (CRIMPING)	80/03/14 C	83-21
53564-K031	ROCKBESTOS CABLE	80/04/03 C	80-15
53564-K032	CONCRETE SPALLING REFUEL POOL LEDGE	80/05/06 C	80-13
53564-K033	CONCRETE DAMAGE AROUND SEAL RING	80/04/29 C	80-13
53564-K034	ESW PIPE WELDS - LINEAR INDICATION	80/05/08 C	80-13
53564-K035	GE SWITCHGEAR WIRING - IN- CORRECT COLORING	80/05/08 C	82-09
53564-K036	GE SAM15A - TIMER RELAYS	80/04/29 C	81-02
53564-K037	DIESEL GENERATOR THRUST BEARING	80/05/13 C	83-06
53564-K038	CONCRETE MIX	80/05/28 C	81-02
53564-K039	GRINNEL-BERGEN PATTERSON SWAY STRUTS	80/05/29 C	83-21
53564-K040	INDUSTRIAL MECHANICS-BOLTS	80/06/06 C	81-02

AND NUTS

53564-K041	BERGEN PATTERSON SHOCK AR- RESTORS	80/07/03 C	83-21
53564-K042	UMS DAM DISPERSIVE/NON-DISPERSIVE MATERIAL	80/06/09 C	82-09
53564-K043	NUCLEAR COATING-SPEC A-125 (Q)	80/07/25 R	
			PREVIOUS INTERIM REPORTS:
			KMLNRC-024 8/25/80
			KMLNRC-034 10/29/80
			KMLNRC 81-052 1/13/81
			81-078 5/16/81
			81-099 7/15/81
			81-117 10/01/81
			81-137 11/19/81
			82-167 2/26/82
			82-188 4/20/82
			82-240 8/30/82
			83-001 1/12/83
			83-083 7/01/83
			CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED, KMLNRC 84-013, 02/10/84.
53564-K044	GULFALLOY 2 INCH 90 DEGREES ELBOW HEAT 408 SEAM DEFECT	80/08/01 C	81-19
53564-K045	UNDERSIZED SOCKET WELDS	80/09/30 R	AWAITING NRC REVIEW
53564-K046	ANACONDA 600 VOLT CONTROL CABLE	80/09/30 C	80-24
53564-K047	MAIN CONTROL AND RELAY PANEL WELDS (COMSIP)	80/10/14 C	81-16
53564-K048	DAMAGED MOTOR CONTROL CENTER	80/11/04 C	81-19
53564-K049	FISHER CONTROLS MANUALLY OPERATED VALVES	81/02/18 C	83-04
53564-K050	FISHER VALVE BETTIS OPERATOR	81/02/09 C	NOT REPORTED AS A POTENTIAL SO.55(CE) - SHOULD NOT HAVE BEEN GIVEN A TE 53564 NUMBER.
53564-K051	GENERAL ELECTRIC HFA RELAYS	81/02/04 C	83-04
53564-K052	GE AKR-30 AND AKR-50 CIRCUIT BREAKER	81/04/02 C	83-04
53564-K053	DRAVO PIPING SPOOLS (WELDS)	81/05/01 C	81-19
53564-K054	CRACKED PARTS IN NK DC SWITCHBOARD	81/05/21 C	81-19
53564-K055	NONCONFORMING ROCKBESTOS CABLE	81/05/22 C	83-04



ID	Description	Date	Status	Notes												
53564-K056	STRETCHED TERMINATION BOLTS		C	NOT REPORTED AS A POTENTIAL S.O.S.S.(E) - SHOULD NOT HAVE BEEN GIVEN A TE 53564 NUMBER.												
53564-K057	GRINDING IN MAIN STEAM PIPE	81/07/01	C	81-19												
53564-K058	GE AKR-30 & 50 SPRING MECH-ANISM	81/07/14	C	84-03												
53564-K059	HVAC DUCT SUPPORTS	81/09/03	C	83-06												
53564-K060	CT OPEN CIRCUIT GE 4160 SWITCHGEAR	81/10/13	C	83-04												
53564-K061	ESWP SUPPORT EMBEDDED PLATE STUD FAILURE	81/11/13	C	83-21												
53564-K062	TERMINALS IN MAIN CONTROL PANELS	82/01/26	C	83-04												
53564-K063	BROKEN SPRINGS ON STAB CON-NECTORS	82/03/04	C	83-04												
53564-K064	SEISMIC DESIGNED NON-Q PIPE HANGERS (SPECIAL SCOPE MATERIAL TRACEABILITY)	82/04/15	R	AWAITING NRC REVIEW.												
53564-K065	W POST ACCIDENT INSTRUMENT ERRORS	82/04/08	R	AWAITING NRC REVIEW.												
53564-K066	DIESEL GENERATOR BOLT TORQUE	82/06/14	C	83-21												
53564-K067	DIESEL GENERATOR VALVE MAL-FUNCTION	82/06/22	C	83-21												
53564-K068	DANIELS TEST FOR WELDING INSPECTORS	82/07/12	R	INTERIM REPORTS: <table border="1"> <tr><td>KMLNRC 82-234</td><td>8/11/82</td></tr> <tr><td>82-247</td><td>10/20/82</td></tr> <tr><td>83-015</td><td>1/31/83</td></tr> <tr><td>83-049</td><td>4/25/83</td></tr> <tr><td>83-114</td><td>8/26/83</td></tr> <tr><td>83-157</td><td>11/28/83</td></tr> </table> CURRENT STATUS: THE CURRENT STATUS WAS PROVIDED IN KMLNRC 83-157. FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 84-134, 8/6/84). AWAITING NRC REVIEW.	KMLNRC 82-234	8/11/82	82-247	10/20/82	83-015	1/31/83	83-049	4/25/83	83-114	8/26/83	83-157	11/28/83
KMLNRC 82-234	8/11/82															
82-247	10/20/82															
83-015	1/31/83															
83-049	4/25/83															
83-114	8/26/83															
83-157	11/28/83															
53564-K069	SUSPECT POTENTIOMETER LEADS ON FOXBORO CARDS	82/10/08	C	83-04												
53564-K070	RESTRICTED MOVEMENT OF NON-STATIONARY PIPE SUPPORTS	82/10/14	C	84-07												
53564-K071	GE AKR BREAKER DEFICIENCY	82/11/09	R	FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 82-257, 12/9/82) AWAITING NRC REVIEW.												

53564-K072 FAILED BATTERY CHARGER LEAD 82/12/14 R

FINAL REPORT HAS BEEN SUBMITTED. (SLNRC 83-009,  
2/18/83) AWAITING NRC REVIEW.

53564-K073 LOOSE PARTS IN THE STEAM GENERATOR 82/12/20 C

83-21

53564-K074 DISCREPANCIES IN THE BN SYSTEM 83/01/31 R

INTERIM REPORTS: KMLNRC 83-016 2/17/83  
83-050 4/25/83  
83-077 6/24/83  
83-124 9/28/83  
CURRENT STATUS: FINAL REPORT SUBMITTED (KMLNRC 84-08 ON 4/24/84). AWAITING NRC REVIEW.

53564-K075 DOUBLE LOCKNUT OMITTED ON III SMALL PIPE SUPPORTS 83/01/31 R

FINAL REPORT HAS BEEN SUBMITTED. (SLNRC 83-006,  
2/19/83) AND CORRECTIVE ACTION HAS BEEN IMPLEMENTED. AWAITING NRC REVIEW.

53564-K076 INSUFFICIENT TORQUE ON STRUCTURAL BOLTS/NUTS 83/02/04 R

INTERIM REPORTS: KMLNRC 83-021 3/03/83  
83-076 6/20/83  
83-116 9/09/83  
83-169 12/30/83  
FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-128,  
9/5/84). AWAITING NRC REVIEW.

53564-K077 U-BOLT MATERIAL TRACE-ABILITY 83/02/04 R

FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-058,  
5/23/83) CORRECTIVE ACTIONS HAVE BEEN IMPLEMENTED.  
AWAITING NRC REVIEW.

53564-K078 COMPONENT TESTING 83/02/09 R

WITHDRAWN (KMLNRC 83-073, 6/17/83) AWAITING NRC REVIEW.

53564-K079 TWO INCH MASONERIAN VALVES 83/02/11 C

83-21

53564-K080 GARRETT SOLENOID VALVES 83/02/11 C

FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-024,  
3/11/83). AWAITING NRC REVIEW.

53564-K081 CONCERNING WORKMANSHIP OF SWAGelok FITTINGS 83/02/15 R

WITHDRAWN (KMLNRC 83-109, 9/22/83) AWAITING NRC REVIEW.

53564-K082 FOXBORO MODULES 83/02/18 R

FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-027,  
3/18/83 AND KMLNRC 83-054, 5/12/83). AWAITING NRC REVIEW.

53564-K083 RAY MILLER CORP.	83/02/18 R		INTERIM REPORTS: KMLNRC 83-030, 3/16/83 KMLNRC 83-092, 7/15/83 CURRENT STATUS: ALSO REFERENCE I&E BULLETIN 83-07 FOR WHICH A FINAL RESPONSE WAS SUBMITTED. (SLNRC 84-0049, 3/23/84). KGBE HAS WITHDRAWN THIS POTENTIAL 10CFR50.55(E). (KMLNRC 84-100, 6/28/84). AWAITING NRC REVIEW.
53564-K084 BRASS FITTING ON DIESEL FIRE PUMP	83/02/21 R		FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-028, 3/21/83) AWAITING NRC REVIEW.
53564-K085 HANGER NOTES AND SYMBOLS	83/02/21 C	84-07	
53564-K086 BOLT TORQUE ON INSTRUMENT MOUNTS	82/02/24 R		FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-078, 6/24/83) AWAITING NRC REVIEW
53564-K087 GA TECHNOLOGIES RM-23	83/02/24 R		FINAL REPORT HAS BEEN SUBMITTED. (SLNRC 83-031, 5/27/83) AWAITING NRC REVIEW.
53564-K088 WELDS ON BERGEN-PATERSON SUPPORTS	83/02/24 R		INTERIM REPORTS: KMLNRC 83-054, 3/25/83 83-060, 5/26/83 83-093, 7/18/83 83-138, 10/21/83 CURRENT STATUS: NO SIGNIFICANT STRUCTURAL DEFICIENCIES HAVE BEEN IDENTIFIED. WITHDRAWN (KMLNRC 84-052 ON 3/16/84) AWAITING NRC REVIEW.
53564-K089 GE AKR CIRCUIT BREAKERS	82/02/28 R		FINAL REPORT HAS BEEN SUBMITTED. (SLNRC 83-023, 4/28/83) AWAITING NRC REVIEW.
53564-K090 POWER CONVERSION PRODUCTS BATTERY CHARGERS	83/03/09 R		INTERIM REPORTS: KMLNRC 83-040, 4/08/83 83-087, 7/11/83 83-126, 10/03/83 CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-129, 8/6/84). AWAITING NRC REVIEW.
53564-K091 STRUCTURAL STEEL WELDS	83/03/23 R		WITHDRAWN: AWAITING NRC REVIEW (KMLNRC 83-139, 10/21/83)
53564-K092 STITCH WELDING ON ELECTRICAL RACEWAYS AND CONDUIT	83/03/25 R		WITHDRAWN: AWAITING NRC REVIEW (KMLNRC 83-047, 4/22/83.)
53564-K093 LOOSE PARTS FOUND IN STEAM GENERATORS	83/04/26 R		FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 83-105, 8/12/83) AWAITING NRC REVIEW.

53564-K094	USE OF TEFLON IN THE POWER BLOCK	83/05/04 C		FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 83-066, 6/3/83) Awaiting NRC REVIEW.
53564-K095	CONTAINMENT SPRAY/RHR MOTOR OIL PROBLEM	83/05/12 C	83-21	
53564-K096	PIPING SPOOL PIECE	83/05/24 C	83-21	
53564-K097	CUTLER-HAMMER PUSH BUTTON SWITCHES	83/06/09 R		INTERIM REPORTS: KMLNRC 83-085, 7/08/83 83-123, 9/28/83 CURRENT STATUS: FINAL REPORT SUBMITTED (KMLNRC 84-057 ON 4/9/84) AWAITING NRC REVIEW.
53564-K098	DEAD BATTERY ON BACKUP EMER. DIESEL FIRE PUMPS	83/06/10 C	83-21	
53564-K099	BERGEN-PATERSON WELD BEAM ATTACHMENTS	83/06/17 R		INTERIM REPORTS: KMLNRC 83-089, 7/15/83 83-141, 10/28/83 CURRENT STATUS: WITHDRAWN (KMLNRC 84-021 ON 2/22/84). Awaiting NRC REVIEW
53564-K100	GUYON 1/2 INCH SOCKET COUPLING	83/06/17 R		WITHDRAWN (KMLNRC 83-135, 10/14/83) Awaiting NRC REVIEW.
53564-K101	VULKENE SUPREME CABLE	83/06/20 C		INTERIM REPORTS: KMLNRC 83-095, 7/20/83 83-125, 7/25/83 83-151, 11/23/83 CURRENT STATUS: KMLNRC 83-151 PROVIDED CURRENT STATUS - ANTICIPATE FINAL REPORT IN October 1984.
53564-K102	GE AKR BREAKERS	83/06/20 C	84-05	WITHDRAWN (KMLNRC 83-127, 10/7/83)
53564-K103	SWAY STRUT WASHERS	83/07/15 R		INTERIM REPORTS: KMLNRC 83-104, 8/12/83 83-143, 11/03/83 CURRENT STATUS: FINAL REPORT WAS SUBMITTED (KMLNRC 84-165 ON 9/21/84). Awaiting NRC REVIEW.
53564-K104	AUXILIARY FEEDWATER PUMP SHAFT	83/07/16 R		FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 83-108, 5/17/83) Awaiting NRC REVIEW
53564-K105	TUBE-LINE	83/08/12 C	84-03	FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 83-155, 11/25/83).
53564-K106	GOULD-RUNDELL HANDSWITCHES	83/08/24 F		FINAL REPORT HAS BEEN SUBMITTED (SLNRC 84-024 ON 2/9/84). SUPPLEMENTAL INFORMATION WAS PROVIDED. (SLNRC 84-067, 4/13/84 AND SLNRC 84-103, 7/20/84). Awaiting ISSUANCE OF PMP'S. ISSUANCE ANTICIPATED IN OCTOBER.
53564-K107	PSA SNUBBERS	83/09/13 R		FINAL REPORT HAS BEEN SUBMITTED (SLNRC 85-0058, 11/9/83) Awaiting NRC REVIEW.

53564-K108 EXPOSED THREADS ON SEAL WELDED CONNECTIONS	83/10/12 R	INTERIM REPORTS: KMLNRC 83-146, 11/09/83 CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-041 ON 3/16/84) AWAITING NRC REVIEW.
53564-K109 CRACKED EDGE CONNECTORS ON WESTINGHOUSE 7300 PROCESS SYSTEM	83/10/25 R	INTERIM REPORTS: KMLNRC 83-153, 11/23/83 CURRENT STATUS: WITHDRAWN (KMLNRC 84-036 ON 3/16/84) AWAITING NRC REVIEW.
53564-K110 IMPROPER FITTING ON MSIV	83/10/25 R	INTERIM REPORTS: KMLNRC 83-152, 11/23/83 CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-133, 8/5/84). AWAITING NRC REVIEW.
53564-K111 HVAC	83/11/10 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 83-153, 12/9/83) FINAL REPORT WAS SUBMITTED. (KMLNRC 83- 137, 8/8/84). AWAITING NRC REVIEW.
53564-K112 POLAR CRANE TESTING	83/11/18 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 83-165, 12/16/83) (POTENTIAL 50.55(E).) ALL TESTING HAS BEEN COMPLETED FINAL REPORT WAS SUBMITTED (KMLNRC 84-164 ON 9/21/84). AWAITING NRC REVIEW
53564-K113 CABLE TERMINATION LUGS	83/11/18 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 83-164, 12/16/83) WITHDRAWN (KMLNRC 84-90 ON 6/15/84). AWAITING NRC REVIEW
53564-K114 I BEAMS	83/12/01 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 83-170, 12/30/83) (POTENTIAL 50.55(E).) FINAL REPORT ANTICIPATED IN OCTOBER.
53564-K115 CODE WELDING	83/12/07 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-02 ON 1/6/84) WITHDRAWN (KMLNRC 83-042 ON 3/16/84) AWAITING NRC REVIEW.
53564-K116 PIPE SCHEDULE	83/12/13 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-05 ON 1/12/84) AWAITING COMPLETION OF CONSTRUCTOR INSPECTIONS OF TWO SYSTEMS. ANTICIPATING FINAL REPORT IN OCTOBER.
53564-K117 PDP PULSATION DAMPERS	83/12/21 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-007 ON 1/19/84) WITHDRAWN (KMLNRC 83-37 ON 3/16/84) AWAITING NRC REVIEW.
53564-K118 FIELD PROCUREMENT	84/01/03 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-011 ON 02/02/84) AWAITING COMPLETION OF EVALUATION. (POTENTIAL 10CFR50.55(E). ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K119 BUTTERFLY VALVES	84/01/10 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-014 ON 02/09/84) FINAL REPORT WAS SUBMITTED (KMLNRC

84-132, 8/6/84). Awaiting NRC Review.

53564-K120 FUSION WELDED PIPE	84/01/30 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-018 ON 02/17/84) ANTICIPATE FINAL REPORT IN AUGUST. FINAL REPORT WAS SUBMITTED (KMLNRC 84-163 ON 9/21/84). Awaiting NRC Review.
53564-K121 LIMITORQUE OPERATORS	84/02/03 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-024 ON 3/1/84) Awaiting COMPLETION OF EVALUATION. (POTENTIAL 10CFR 50.55(E).) ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K122 CHECK VALVES	84/02/06 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-027 ON 3/7/84). FINAL REPORT WAS SUBMITTED (KMLNRC 84-166 ON 9/21/84). Awaiting NRC Review.
53564-K123 TEN INCH GATE VALVES	84/02/27 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-44 ON 3/26/84) WITHDRAWAL WAS SUBMITTED (KMLNRC 84-131, 8/6/84) Awaiting NRC Review.
53564-K124 LOAD SHEDDER EMERGENCY LOAD SEQUENCER	84/02/27 R	FINAL REPORT SUBMITTED (KMLNRC 84-52 ON 3/30/84) Awaiting NRC Review.
53564-K125 PORV RELAYS	84/03/02 R	FINAL REPORT SUBMITTED (KMLNRC 84-0064 ON 4/13/84) Awaiting NRC Review.
53564-K126 DIESEL GENERATOR LUBE OIL KEEP WARM PUMP	84/03/09 O	30 DAY INTERIM REPORT HAS BEEN SUBMITTED (KMLNRC 84-56 ON 4/5/84) Awaiting COMPLETION OF EVALUATION (POTENTIAL 10CFR 50.55(E).) ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K127 VALCOR WIRING	84/03/15 R	FINAL REPORT SUBMITTED (SLNRC 84-65 ON 4/13/84) Awaiting NRC Review
53564-K128 FAN MECHANICAL INTERLOCKS	84/03/16 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-61 ON 4/11/84) Awaiting COMPLETION OF EVALUATION. (POTENTIAL 10CFR 50.55(E).) ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K129 SAFETY INJECTION ACCUMULATORS	84/03/19 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-63 ON 4/19/84) WITHDRAWN (KMLNRC 84-089 ON 6/15/84). Awaiting NRC Review.
53564-K130 DISCHARGE PULSATION DAMPER	84/03/19 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-66 ON 4/18/84) WITHDRAWAL WAS SUBMITTED (KMLNRC 84-111, 7/11/84). Awaiting NRC Review.
53564-K131 AFW TURBINE RELAY	84/03/19 R	FINAL REPORT SUBMITTED (KMLNRC 84-64 ON 4/18/84) SUPPLEMENTAL INFORMATION WAS SUBMITTED (KMLNRC 84-136, 8/8/84) Awaiting NRC Review.

53564-K132	SEISMIC POSITIONER PLATES ON DS416 REACTOR TRIP BREAKERS	84/03/27 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-071, ON 4/26/84). FINAL REPORT WAS SUBMITTED (KMLNRC 84- 160 ON 9/21/84). AWAITING NRC REVIEW.
53564-K133	CONTAINMENT SPRAY PUMP ROOM FLOODING	84/03/27 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-072 ON 4/26/84). FINAL REPORT ANTICIPATED IN OCTOBER.
53564-K134	LIMITORQUE SHEARED PINION KEY	84/04/19 R	FINAL REPORT HAS BEEN SUBMITTED, (SLNRC 84-078, 05/09/84). AWAITING NRC REVIEW.
53564-K135	BARTON 752 TRANSMITTERS KEY	84/04/24 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-078 ON 05/23/84). AWAITING COMPLETION OF EVALUATION. ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K136	ISOLATION RELAY CARDS	84/04/26 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-081 ON 05/25/84). FINAL REPORT WAS SUBMITTED (KMLNRC 84-140, 8/3/84). AWAITING NRC REVIEW.
53564-K137	REACTOR VESSEL LEVEL INDICATION SYSTEM	84/04/27 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-082 ON 05/25/84). FINAL REPORT WAS SUBMITTED (KMLNRC 84-138, 8/3/84). AWAITING NRC REVIEW.
53564-K138	DIESEL TURBOCHARGER	84/05/04 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-083 ON 06/01/84). AWAITING COMPLETION OF EVALUATION. ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K139	TMI LEAD AUDITOR	84/05/24 O	30 DAY INTERIM REPORT WAS SUBMITTED. (KMLNRC 84- 098, 6/21/84). ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K140	3-HOUR FIRE DOORS	84/05/25 R	FINAL REPORT WAS SUBMITTED (KMLNRC 84-097, 6/21/84). AWAITING NRC REVIEW.
53564-K141	MICROBIOLOGICALLY INFLU- ENCED CORROSION	84/05/01 O	30 DAY INTERIM REPORT WAS SUBMITTED. (KMLNRC 84- 106, 6/29/84). REWORK IN PROGRESS. ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K142	FISCHER VALVE WITH BETTIS ACTUATOR	84/05/13 R	FINAL REPORT WAS SUBMITTED (KMLNRC 84-116, 7/13/84) AWAITING NRC REVIEW.
53564-K143	ASME COMPONENT REMOVAL	84/06/13 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-115, 7/11/84). UNDER EVALUATION. ANTICIPATE CLOSURE IN OCTOBER.

53564-K144 CONTAINMENT SPRAY PUMP	84/06/14 R		WITHDRAWAL WAS SUBMITTED. (KMLNRC 84-114, 7/11/84) AWAITING NRC REVIEW.
53564-K145 LAUNDRY AND HOT SHOWER CHARCOAL ABSORBER	84/06/18 R		WITHDRAWAL WAS SUBMITTED. (KMLNRC 84-112, 7/11/84) AWAITING NRC REVIEW.
53564-K146 LIMITORQUE SB-2-80 ACTUATOR GEAR DAMAGE	84/04/19 O		30 DAY INTERIM REPORT WAS SUBMITTED (SLNRC 84-90 ON 06/01/84). INTERIM REPORT WAS SUBMITTED (SLNRC 84-106, 7/20/84) AWAITING COMPLETION OF TESTING AND REWORK. ANTICIPATE CLOSURE IN OCTOBER.
53564-K147 LUBE OIL PIPING SYSTEM	84/07/17 O		30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-147, ON 8/17/84). AWAITING COMPLETION OF ENGINEERING EVALUATION. ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K148 RCS RTD CALIBRATION DATA	84/08/01 O		30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-158, ON 8/31/84). ENGINEERING EVALUATION IN PROGRESS. ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K149 INCORE THERMOCOUPLES	84/08/06 F		FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-159, ON 9/05/84). ANTICIPATE WORK WILL BE COMPLETED IN OCTOBER.
53564-K150 TC/CCM ALARM RELAYS	84/08/21 O		30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-162, ON 9/20/84). ANTICIPATE FINAL REPORT IN OCTOBER.
53564-K151 MECHANICAL SHOCK ARRESTORS	84/08/23 F		FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-166 ON 9/21/84). ANTICIPATE WORK WILL BE COMPLETED IN OCTOBER.
53564-K152 INSPECTION OF WELDS	84/09/18 O	84/10/15	30 DAY INTERIM REPORT WILL BE SUBMITTED BY 10/18/84. UNDER INITIAL EVALUATION.
53564-K153 TURBINE AFW PUMP TERMINAL STRIPS	84/07/17 O	84/10/19	30 DAY INTERIM REPORT WILL BE SUBMITTED BY 10/19/84. UNDER INITIAL EVALUATION.

..... END REPORT .....



III. Status of Significant Deficiencies Report by SNUPPS Staff

Note: Some of the items in this file are not applicable to Wolf Creek.

DATE 25 SEP 84 16:38:57 RID 2 23 AUG 83 NUCLIC  
 \* SIGNIFICANT DEFICIENCY TRACKING

FILE	TITLE	DATE REPORTED	S	NEXT RPT DUE	NRC DATE CLOSE	REMARKS
55780-K001	SNUPPS - 10CFR50.55(E) REPORTING - GENERAL INFO.		C			
55780-K002	ECCS FINAL ACCEPTANCE CRI- TERIA- REVISED ACCIDENT ANALYSIS	76/08/05	R			FINAL REPORT WAS SUBMITTED SLNRC 6-6, 9/3/76; AWAITING NRC REVIEW.
55780-K003	FABRICATED STRUCTURAL STEEL CRACKS		C			NOT APPLICABLE TO WCGS.
55780-K004	REACTOR COOLANT PUMP - TIE ROD EMBEDS		C			NOT APPLICABLE TO WCGS.
55780-K005	BORIC ACID PUMP WELDS		C			NOT APPLICABLE TO WCGS.
55780-K006	CLIP ANGLE CRACKS		C			NOT APPLICABLE TO WCGS.
55780-K007	RUSKIN FIRE DAMPERS	80/01/18	R			FINAL REPORT HAS BEEN SUBMITTED SLNRC 80-24, 5/16/80. AWAITING NRC REVIEW.
55780-K008	BUNKER RAMO/AMPHENOL-SAMS ELECTRIC PENETRATION ASSEMBLIES (53564-K30)		C			SAME AS 53564-K30.
55780-K009	CHECK VALVE CLOSURE EXCES- SIVE PRESSURE	80/06/30	R			WITHDRAWN SLNRC 80-32, 6/30/80. AWAITING NRC RE- VIEW.
55780-K010	QUALIFICATION OF CONTROL SYSTEMS	79/08/30	R			FINAL REPORT HAS BEEN SUBMITTED, SLNRC 80-6, 2/5/80 AWAITING NRC REVIEW.
55780-K011	PRESSURIZED ANCHOR BOLT SUPPORTS	79/03/23	R			FINAL REPORT HAS BEEN SUBMITTED, SLNRC 79-6, 5/1/79 AWAITING NRC REVIEW.
55780-K012	ROD DROP SAFETY ANALYSIS	79/03/29	R			WITHDRAWN SLNRC 79-5, 4/26/79. AWAITING NRC REVIEW
55780-K013	G & W PIPE ASSEMBLIES (53564-K07)		C			SAME AS 53564-K07
55780-K014	UNDERSIZED SOCKET WELDS (CALLAWAY)		C			NOT APPLICABLE TO WCGS.
55780-K015	GE STICKY RELAYS (53564- K25)		C			SAME AS 53564-K25.
55780-K016	STRUCTURAL MEMBERS - IMPRO- PER PREHEAT		C			NOT APPLICABLE TO WCGS.
55780-K017	CORNER & LADA SWAY STRUTS (53564-K17)		C			SAME AS 53564-K17.
55780-K018	ANALYSIS OF PIPING SYSTEMS		C			NOT A DEFICIENCY - MISFILED.
55780-K019	CHARGING PUMP OPERATION FOLLOWING SECONDARY SIDE HIGH ENERGY LINE RUPTURE	80/05/08	R			FINAL REPORT HAS BEEN SUBMITTED, SLNRC 82-42, 10/29/82. AWAITING NRC REVIEW.

\* CENTRIFUGAL

55780-K020	UNDETECTABLE FAILURE IN ENGINEERED SAFETY FEATURES ACTUATION SYSTEM RUPTURE	79/12/06 R	FINAL REPORT HAS BEEN SUBMITTED, SLNRC 80-12, 3/20/83 AND SLNRC 80-19, 4/19/80. AWAITING NRC REVIEW.
55780-K021	ANCHOR BOLT FORCES WITH HORIZONTAL STEAM LINE BREAK	C	NOT A DEFICIENCY - MISFILED.
55780-K022	APPLICATION OF STRUCTURAL STEEL FIREPROOFING	C	NOT APPLICABLE TO WCGS.
55780-K023	3 1/2 INCH NUTS IMPROPER THREADS (53564-K20)	C	NOT APPLICABLE TO WCGS.
55780-K024	3 INCH ISOLATION VALVES (W)	80/10/30 R	FINAL REPORT HAS BEEN SUBMITTED, SLNRC 82-036, 9/5/82. AWAITING NRC REVIEW.
55780-K025	BERGEN-PATTERSON PIPE SNUBBER ASSEMBLIES (53564-K41)	80/10/27 C	
55780-K026	PIPE WHIP RESTRAINTS (4 INCH AND UNDER)	80/12/24 R	FINAL REPORT HAS BEEN SUBMITTED, SLNRC 81-43, 6/5/81.
55780-K027	ELONGATION OF RCP STUD BOLTS	C	NOT APPLICABLE TO WCGS.
55780-K028	BERGEN-PATTERSON SIZE NO. 6 AND SIZE NO. 15 SWAY STRUTS	81/10/09 R	WITHDRAWN SLNRC 81-128, 12/14/81. AWAITING NRC REVIEW.
55780-K029	LIMITORQUE SHEARED PINION KEYS IN MOTOR OPERATORS	82/08/04 R	WITHDRAWN: SLNRC 83-012, 3/3/83. AWAITING NRC REVIEW.
55780-K030	UNDETECTABLE FAILURE IN ON-LINE CIRCUITS FOR RELAYS	82/03/04 R	INTERIM REPORTS: SLNRC 82-0036, 9/3/82 83-0015, 3/3/83 83-0049, 9/2/83 CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED, SLNRC 84-0020, 02/02/84. AWAITING NRC REVIEW.
55780-K031	VALVE POSITION INDICATION FOR W GATE VALVES	82/12/22 R	FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-032, 5/31/83. AWAITING NRC REVIEW.
55780-K032	ANCHOR DARLING CHECK VALVES	83/03/23 R	FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-020, 4/20/83. AWAITING NRC REVIEW.
55780-K033	REACTOR TRIP SWITCHGEAR	83/04/21 R	FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-023, 5/23/83. AWAITING NRC REVIEW.
55780-K034	W 7300 PROCESS RACKS	83/06/02 F	INTERIM REPORTS: SLNRC 83-0039, 7/21/83 AWAITING COMPLETION OF SEISMIC TESTING OF REPLACEMENT CARDS IN OCTOBER.
55780-K035	YARWAY VALVES	83/06/17 F	FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-037, 7/18/83 AND SLNRC 83-043, 7/29/83. AWAITING COMPLETION OF REWORK IN OCTOBER.
55780-K036	EXCESSIVE VOLTAGE DROP CONTROL CABLES	83/06/23 F	FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-040, 7/22/83. AWAITING COMPLETION OF CORRECTION ACTION IN OCTOBER.

-----  
55780-K037 HANGER CLASSIFICATION 83/10/23 R  
\*  
\*  
\*  
\*  
-----

INTERIM REPORT: SLNRC 83-0060 11/22/83  
CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED,  
SLNRC 84-006, 01/20/84. AWAITING NRC REVIEW.

-----  
55780-K038 LIMITORQUE LIMIT SWITCH 83/11/16 R  
\*  
\*  
\*  
\*  
-----

30 DAY INTERIM REPORT WAS SUBMITTED (SLNRC 83-0064  
12/22/83) (POTENTIAL 50.55(E).) FINAL REPORT HAS  
BEEN SUBMITTED (SLNRC 84-0064, 4/13/84). AWAITING  
NRC REVIEW.

-----  
..... END REPORT .....