

POST OFFICE BOX 2951 . BEAUMONT TEXAS 77704


AREACODE 402 010 0001

February 1, 1985 RBG-20047 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station Unit 1 Docket No. 50-458 Final Report/DR-204



Gulf States Utilities Company (GSU) has completed its evaluation of DR-204 concerning jacket defects on NGP-70 cable (21C No. 16 AWG) supplied by Rockbestos. The defects in the cable jacket will not affect cable performance. Since the cable will perform properly for design operating conditions, GSU has determined this condition is not reportable under 10CFR50.55(e).

Sincerely,

fre J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/FJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

2E-27