

POST CFFICE BOX 2951 . BEAUMONT, TEXAS 77704


AREA CODE 409 838 6631

February 1, 1985 RBG-20048 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station Unit 1 Docket No. 50-458 Final Report/DR-179



Gulf States Utilities Company (GSU) has completed its evaluation of DR-179 concerning test loop diagrams that were not updated to agree with the latest approved design documents prior to testing control circuitry identified on 11 loop calibration reports (LCRs). This condition did not invalidate any previous testing and no retesting was required. GSU has therefore determined this condition does not meet the reporting requirements of 10CFR50.55(e). The 11 LCRs were revised to incorporate the latest design documents.

Sincerely,

for J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing

River Bend Nuclear Group

JEB/VJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

2E-27