## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-II-84-77

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region II staff on this date.

Georgia Power Company FACILITY:

Hatch Unit 1 Docket No. 50-321 Baxley, Georgia

Licensee Emergency Classification: Notification of Unusual Event

Alert

Site Area Emergency General Emergency X Not Applicable

SUBJECT: CRACK IDENTIFIED IN CORE SPRAY SPARGER/DISTRIBUTION BOX WELD

The licensee has identified a crack at the toe of the sparger/distribution box weld during inspection of the lower "B" core spray sparger on Unit 1. The crack appears to be in excess of 180° of the circumference. The depth of the crack has not been determined.

The licensee reports that the upper core spray sparger exhibited no signs of cracking.

Spargers were inspected on Unit 2 during its last outage, and no cracks were identified.

Region II will perform follow-up inspections to assure proper resolution of this event.

Media interest is not expected. Neither the licensee nor the NRC plans to issue a news release at this time.

The State of Georgia has been informed.

Region II (Atlanta) received notification of this occurrence by telephone from the licensee at 1:40 p.m. (EDT) on October 27.

This information is current as of 10:00 a.m. (EST) on October 29.

Contact: V. Panciera, 242-5525

J. Blake, 242-5539

DISTRIBUTION:

ACRS CA

PDR

H. Street Chairman Palladino EDO Comm. Roberts Comm. Asselstine Comm. Bernthal Comm. Zech SECY

Phillips MNBB NRR 2:50 PA MPA ELD

E/W IE OIA AEOD Willste NMSS RES

MAIL: ADM: DMB

DOT: Trans Only Applicable State

INPO 3:00 Air Rights NSAC

Regions:

Licensee: 3:35 (Reactor Licensees)

Applicable Resident Site 4:00

8410310422 841029 PDR I&E PND-II-84-077 PDR PDR