

APPENDIX A

NOTICE OF VIOLATION

Baltimore Gas and Electric Company
Calvert Cliffs Units 1 and 2

Docket/License: 50/317;DPR53
50/318;DPR69

As a result of the inspection conducted on July 11 - August 20, 1984 and in accordance with the NRC Enforcement Policy, (10 CFR2 Appendix C) the following violation was identified:

Criterion V of Appendix B to 10 CFR Part 50 requires that, "Activities affecting quality shall be prescribed by documented procedures of a type appropriate to the circumstances and shall be accomplished in accordance with these procedures."

Technical Specification 4.7.6.1.e(2) requires, "Verifying that on a control room high radiation test signal, the system automatically switches into a recirculation mode of operation with flow through the HEPA filters and charcoal adsorber banks and that the isolation valves close."

Contrary to the above, on August 9, 1984, it was determined that procedure STP-0-72-0, Revision 1, "Control Room High Radiation Functional Test" was inappropriate to the circumstances, in that several components which would automatically actuate on high radiation were not being verified for proper operation as required by Technical Specification 4.7.6.1.e(2).

This is a Severity Level V Violation (Supplement I) applicable to DPR-53 and DPR-69.

Although Section 2.201 requires you to submit to this office, within 30 days of your receipt of this notice, a written statement of explanation, we note that this violation was corrected prior to the completion of our inspection, and therefore, no response with respect to this matter is required.

8410310483 841009
PDR ADOCK 05000317
Q PDR

OFFICIAL RECORD COPY

50-317/84-19 - 0003.0.0
08/31/84