

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

84 OCT 16 ~~October 6~~ 11, 1984

BLRD-50-438/82-51
BLRD-50-439/82-46

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENCY IN UNDERVOLTAGE
PROTECTION DURING AN ACCIDENT - BLRD-50-438/82-51, BLRD-50-439/82-46 -
SIXTH INTERIM REPORT


The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on July 27, 1982 in accordance with 10 CFR 50.55(e) as NCR BLN EEB 8205. This was followed by our interim reports dated August 25 and November 19, 1982, January 17 and September 15, 1983 and April 17, 1984. Below is our sixth interim report. We expect to submit our next report by July 19, 1985.

TVA has completed the initial analysis to determine voltage and time-delay relay setpoints and is still in the process of checking this analysis. Additional information will be provided after the analysis is issued.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulator, Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8410310682 841011
PDR ADOCK 05000438
S PDR

OFFICIAL COPY

1627
110