

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

84 OCT 18 October 18, 1984

BLRD-50-438/83-40  
BLRD-50-439/83-34  
BLRD-50-438/84-04  
BLRD-50-439/84-04

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Mr. James P. O'Reilly, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - FIELD CABLES NOT TERMINATED IN  
PENETRATIONS PROPERLY - BLRD-50-438/83-40, BLRD-50-439/83-34 - SUPPLEMENTAL  
REPORT


The subject deficiency was initially reported to NRC-OIE Inspector  
Linda Watson on June 14, 1983 in accordance with 10 CFR 50.55(e) as NCRs  
2383, 2384, 2385, and 2395. This was followed by our interim reports  
submitted on July 14 and December 23, 1983. NCR 2494 (BLRD-50-438/84-04,  
BLRD-50-439/84-04), which documented a similar condition was subsequently  
reported on December 28, 1983 and was followed by our interim report dated  
January 26, 1984 and our final report dated July 30, 1984. Below is our  
supplemental report on both NCRs.

As discussed with NRC-OIE Inspector P. E. Fredrickson on September 26,  
1984, the date of October 1, 1984 for completion of corrective actions  
indicated in our final report on this matter would not be met. This is due  
to a delay of the approval of termination cards for the subject cables.

If you have any questions, please get in touch with R. H. Shell at  
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager  
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

OFFICIAL COPY

8410310713 841012  
PDR ADDOCK 05000438  
S PDR

An Equal Opportunity Employer

IE 27  
10