

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

84 SEP 18 13:29  
September 12, 1984

TELEPHONE  
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Re: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287  
IE Bulletin 84-02

Dear Sir:

This letter is a Supplemental response to IE Bulletin 84-02 which concerns failures of GE type HFA relays in use in class IE Safety Systems. By a letter dated July 13, 1984, Duke provided an initial response to this Bulletin for Oconee Nuclear Station. In this letter you were informed that Duke's review addressing the generic concerns expressed in the Bulletin was still in progress and would be provided shortly after completion of the investigation. This letter provides the results of our investigation.

Duke has found that there are no similar problems with Oconee's safety-related relays.

I declare under penalty of perjury that the information contained herein is correct to the best of my knowledge as executed on September 12, 1984.

Very truly yours,



Hal B. Tucker

PFG:slb

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. J. C. Bryant  
NRC Resident Inspector  
Oconee Nuclear Station

Ms. Helen Nicolaras  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8410310717 840912  
PDR ADOCK 05000269  
Q PDR

IE1110