

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775

AREA CODE 504 635-3237


387-4257

January 30, 1985 RBG- 20009 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 70611

Dear Mr. Martin:

River Bend Station Unit I Docket No. 50-458 Interim Report/DR-242



An interim or final report concerning the fracture of a pinion gear in a motor operator supplied by Limitorque for a safety related valve in the Residual Heat Removal System will be provided by March 1, 1985.

Sincerely,

L. A. Enfand for J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

PJD JEB/PJD/cem

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site