

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Prairie Island Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 2 8 2	PAGE (3) 1 OF 0 2
--	--------------------------------------	----------------------

TITLE (4)
One main steam safety valve setpoint found out of spec

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 1	1 2	8 5	8 5	0 0 2	0 0	0 2	1 1	8 5			0 5 0 0 0
											0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

OPERATING MODE (9) N	20.402(b)	20.406(a)	90.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 0 0 0	20.406(a)(1)(i)	90.36(a)(1)	90.73(a)(2)(v)	73.71(e)
	20.406(a)(1)(ii)	90.36(a)(2)	90.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
20.406(a)(1)(iii)	X 90.73(a)(2)(i)	90.73(a)(2)(vii)(A)		
20.406(a)(1)(iv)	90.73(a)(2)(ii)	90.73(a)(2)(vii)(B)		
20.406(a)(1)(v)	90.73(a)(2)(iii)	90.73(a)(2)(ix)		

LICENSEE CONTACT FOR THIS LER (12)

NAME Arne A. Hunstad, Staff Engineer	TELEPHONE NUMBER 6 1 2 3 8 8 - 1 1 2 1
---	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR 0 3 1 5 8 5
---	-----------------------------	--

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During surveillance test at shutdown for refueling, one of ten main steam safety valves failed to open at its setpoint. A supplemental report will be made.

8502150484 850211
PDR ADOCK 05000282
S PDR

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Prairie Island Unit 1	0 5 0 0 0 2 8 2	8 5	- 0 0 2	- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On January 12th, Unit 1 was shutdown for refueling. During a surveillance test, one of the ten main steam (SB) safety valves (V) failed to open at its setpoint. Cause has not yet been determined since repairs have not been made. The valve will be made operable before restart and a supplemental report will be made.



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

February 11, 1985

U S Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

One Main Steam Safety Valve Stepout
Found Out of Spec

The License Event Report for this occurrence is attached.

This event was reported via Emergency Notification System per 10 CFR Part 72
on January 12, 1985.

Eugene Eckholt

for David Musolf
Manager - Nuclear Support Services

DMM/EFE/dab

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
MPCA
Attn: J W Ferman

Attachment

IE22
1/1