

9-24-73

631 Park Avenue  
King of Prussia, Pennsylvania 19406

D. L. Capton, Senior Reactor Inspector, Facility Operations Branch  
Directorate of Regulatory Operations, Region I

RO Inspection Report No. 50-219/73-11  
Jersey Central Power & Light Company  
Oyster Creek

It appears to me that Jersey Central has made great strides in their management controls at the site. In addition, there seems to be more of a desire to keep us informed of unusual events.

The requested information was obtained or action initiated, as appropriate for the following items:

<u>Request</u>	<u>Information or Action</u>
MRS 1/31/73	Procedure written but not reviewed by PORC (Proprietary)
MRS 3/5/73	Very fine pitting observed in the discharge area of the cylinder (P 19)
MRS 3/6/73	Liquid poison level is measured by float.
Letter Knuth to Regional Director - 5/24/73 FACF RO:I/73-8	Have had occasion of rods failing to fully insert; however, evaluation indicated seal leakage.

The problem with the GORB Minutes was discussed with Mr. Don Ross, Manager, Nuclear Generating Stations. I was assured that copies of "draft" and "official" minutes would be placed promptly in a file at the site so that they would be available for our review.

According to Mr. Carroll, Jersey Central is actively interviewing for a Radiation Protection Supervisor, but has not had success in locating a certified H. P.

5/143

MC# 611611	OFFICE ▶ CRESS					
	SURNAME ▶ Greenman:eby					
	DATE ▶ ij/csl					

According to Mr. Carroll, Oyster Creek has a handwritten procedure for a  
"job threat." However, this procedure has not been reviewed by the  
PORC. He plans to present the procedure to PORC, but maintain a very  
limited distribution.

F. S. Cantrell  
Reactor Inspector  
Facility Operations Branch