

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER
VICE PRESIDENT
NUCLEAR POWER GENERATION

February 8, 1985

PGandE Letter No.: DCL-85-057

Mr. John B. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission, Region V
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368

Re: Docket No. 50-323
Diablo Canyon Unit 2
Response to IE Bulletin 79-13

Dear Mr. Martin:


IE Bulletin 79-13, including its supplements, summarized NRC requirements for the inspection of feedwater nozzle-to-pipe welds. At this time, items 1a, 1b, 1c, 4, and 5 are required to be addressed for Unit 2. PGandE letter to the NRC dated December 12, 1979 addressed Item 5 of the Bulletin. The following information provides PGandE's final response for the remaining items.

PGandE completed radiographic examinations of the feedwater nozzle-to-pipe welds and adjacent areas on January 10, 1985. The radiography complied with the requirements of Item 1.a of IE Bulletin 79-13. All welds were found acceptable; therefore, Items 1.b and 4 of the Bulletin do not apply.

PGandE has also completed visual inspections of the feedwater system piping supports and snubbers inside containment as required by Paragraph 1.c of the Bulletin. An engineering walkdown was conducted during hot functional testing to verify operability. As-built drawings were used to verify that all supports and snubbers were installed correctly.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerely,


for J. D. Shiffer

cc: R. T. Dodds
G. W. Knighton
H. E. Schierling
Service List

8502200228 850208
PDR ADOCK 05000323
G PDR

IE-11/0