

UNITED STATES ATOMIC ENERGY COMMISSION DIVISION OF COMPLIANCE REGION I 970 BROAD STF NEWARK, NEW JERSEY 2,102

201 645- 3754

NOV 9 1971

R. T. Carlson, Sr. Reactor Inspector Division of Compliance, Region I

CO INSPECTION REPORT NO. 50-219/71-03 JERSEY CENTRAL POWER & LIGHT COMPANY OYSTER CREEK 1 - BWR

Approximately 75% of the time spent at the site was used in observing the fuel handling and fuel inspection process. It appeared that the procedures were being followed and the overall operation was being performed in a safe manner.

The area of reservation I have is the lack of nuclear knowledge and experience of the GE fuel handlers. They were given about two weeks of training before the operation started, their backgrounds to that point were non-nuclear. I don't think the nuclear industry is ready for people performing monkey functions.

T. Young

Reactor Inspector