

APR 26 1973

Jersey Central Power and Light Company
Attention: Mr. Ivan R. Pinfrock
Vice President of Power Generation
Madison Avenue at Punch Bowl Road
Morristown, New Jersey 07960

Docket No. 50-219

Gentlemen:

This refers to the inspection conducted by Dr. Gallina of this office on February 28 through March 2, March 6 and 7, 1973, of the activities authorized by AEC License No. DPR-16 and to the discussions of our findings held by Dr. Gallina with Messrs. Ross, Criumins and Trikouras of your staff at your Parsippany offices on March 6, 1973, and Messrs. McCluskey and Sullivan of your staff at the conclusion of the inspection at the site.

Areas examined during this inspection included: operational environmental monitoring program, environmental monitoring equipment and a review of fish kills which have occurred at the Oyster Creek facility. Within these areas, the inspection consisted of a selective examination of procedures and representative records, interviews with plant personnel, representatives of state and federal marine laboratories and marina owners, and observations by our inspector.

During this inspection, it was found that certain of your activities appeared to be in violation of AEC requirements. The items and references to the pertinent requirements are listed in the enclosure to this letter. This letter constitutes a notice sent to you pursuant to the provisions of Section 2.201 of the AEC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within 20 days of your receipt of this notice, a written statement of explanation in reply, including: (1) corrective steps which have been or will be taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved.

During the course of our inspection, it was also noted that the Water Quality Monitoring Program was not being conducted as described in Section 5.5.2.3 of the Environmental Report for the Oyster Creek Nuclear Generating Station in that samples were not being taken when designated and when taken, not analyzed for the water quality parameters listed. It is our understanding that this program will be carried out as described in the above stated reference, but we would appreciate further clarification from you as to the current status of the program.

OFFICE ▶	638				
SURNAME ▶	Gallina/ds	Stehr	Nelson	O'Reilly	Carlson
DATE ▶	4/17/83	4/25/73	4/27/73	4/25	

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

James P. O'Reilly
Director

Enclosure:
Description of Violations

bcc: RO Chief, OB
RO Chief, EPB
RO:HC (4)
Licensing (4)
DR Central Files
PDR
LPDE
NSIC
TIC
State of New Jersey