

UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION 1
970 BROAD STREET
NEWARK, NEW JERSEY 07102

11
420

April 24, 1973

James P. O'Reilly, Director
Region I, Directorate of Regulatory Operations

MANAGEMENT MEETING WITH JERSEY CENTRAL ON APRIL 24, 1973

Summary of Environmental Monitoring Inspection

This inspection of both radiological and non-radiological areas was conducted in the first week of March, 1973.

Findings


There were 13 items of noncompliance (see attached Description of Violations) - all associated with multiple instances of failure to meet the requirements in the Technical Specifications. It was also observed that the sampling for the Water Quality Program described in the OC Environmental Report had not been performed in all instances.

Programmatic Deficiencies (Related to Management)

The negative findings appeared associated with the following programmatic deficiencies: inadequate manpower to conduct the program; inadequate review of the data obtained; failure to upgrade the existing equipment to meet the requirements of the present program.

Evaluation of Present Program

It appears that the whole program should be reviewed and updated to meet current guides. (RO:I recommendations to DL are attached). In some cases this would involve additional sampling, in others, discontinuing some of present analyses.


J. P. Stohr, Senior Radiation Specialist
Environmental & Special Programs Section

Enclosures:
Description of Violations
RO:I Recommendations to DL

B1260

April 24, 1973

James P. O'Reilly, Director
Region I, Directorate of Regulatory Operations

MANAGEMENT MEETING WITH JERSEY CENTRAL ON APRIL 24, 1973

Summary of Environmental Monitoring Inspection

This inspection of both radiological and non-radiological areas was conducted in the first week of March, 1973.

Findings

There were 13 items of noncompliance (see attached Description of Violations) - all associated with multiple instances of failure to meet the requirements in the Technical Specifications. It was also observed that the sampling for the Water Quality Program described in the OC Environmental Report had not been performed in all instances.

Programmatic Deficiencies (Related to Management)

The negative findings appeared associated with the following programmatic deficiencies: inadequate manpower to conduct the program; inadequate review of the data obtained; failure to upgrade the existing equipment to meet the requirements of the present program.

Evaluation of Present Program

It appears that the whole program should be reviewed and updated to meet current guides. (RO:I recommendations to DL are attached). In some cases this would involve additional sampling, in others, discontinuing some of present analyses.

J. P. Stohr, Senior Radiation Specialist
Environmental & Special Programs Section

Enclosures:
Description of Violations
RC:I Recommendations to DL

OFFICE ▶	REG OPS					
SURNAME ▶	STOHR:maz					
DATE ▶	4/24/73					