



Northern States Power Company

414 Nicollet Mall Minneapolis, Minnesota 55401 Telephone (612) 330-5500

February 12, 1985

Director Office of Nuclear Reactor Regulation U S Nuclear Regulatory Commission Washington, DC 20555

> PRAIRIE ISLAND NUCLEAR GENERATING PLANT Docket Nos. 50-282 License Nos. DPR-42 50-306 DPR-60

Unit 1 Inservice Inspection Summary Report

Attached for your review are four copies of the report, "Inservice Inspection - Examination Summary, Prairie Island Nuclear Generating Plant - Unit 1, October 23 to November 4, 1984, Steam Generator Tube - Eddy Current Examination, Inspection Period 3".

This report is a summary of steam generator tube eddy current examinations performed on steam generators No. 11 and No. 12 at Prairie Island - Unit 1. The examinations were performed during the period from October 23 through November 4, 1984 after tube leakage was detected via secondary side chemical analysis.

A summary of the tubes exhibiting eddy current indications and the total number of tubes plugged to date are exhibited in Appendices B and C of the report.

David Musolf

Manager - Nuclear Support Services

DMM/EFE/dab

c: Regional Administrator-III, NRC (2 copies of attachment) NRR Project Manager, NRC (1 copy of attachment) Resident Inspector, NRC (w/o attachment) G Charnoff (w/o attachment) H Baron, Chief Boiler Ins., State of MN (1 copy of attachment) S Tack, Hartford Ins. (1 copy of attachment)

Attachment

A047