Jersey Central Power and Light Company Attention: Mr. R. H. Sims Vice President Madison Avenue at Punch Bowl Road Morristown, New Jersey 07960

Docket No. 50-219

This refers to the special inspection conducted by Mr. Meyer and Gentlemen: Mr. Cantrell of this office on February 13 through 16, 1973, of activities authorized by AEC License No. DPR-16. This inspection also relates to our findings of the inspection conducted during November and December 1972 and to additional information received by this office regarding the radiological conditions at the facility. Our inspection findings were discussed by Mr. Meyer and Mr. Cantrell with Mr. McCluskey and members of his staff at the conclusion of the inspection.

This also refers to a telephone discussion between Mr. Finfrock and me on February 14, 1973, and to a meeting held at our office on March 1, 1973, attended by Mr. Finfrock and members of his staff and by me and members of my staff.

Areas examined during this inspection included: individual exposure records for the period from January 1, 1970 through February 12, 1973; survey records and air sample records for the period January 1, 1972 through February 13, 1973; health physics log for the period January 1 through February 14, 1973; solid waste storage, handling and disposal; posting and labeling of areas and containers; personnel monitoring program; radiation protection procedures: employee training program; radiation protection program and administrative controls; Plant Operation Review Committee and General Office Review Board Committee audits and inspections; posting and access control of radiation areas and high radiation areas; and housekeeping conditions with respect to radiological controls. Within these areas, the inspection consisted of selective examination of procedures and representative lecords, interviews with plant personnel, measurements made by our inspectors and observations by our inspectors.

In addition to the above areas, our inspectors examined those activities conducted under your license relating to the subject covered in your letter to the Directorate of Regulatory Operations dated February 8, 1973. We have no further questions regarding this matter. 3301

						1
				Carlson		
	T 1		A: -5-	Carlson	vistam.	O'Reilly
OFFICE >	CRESS: 1	11	Smith	Carlson	Neison	117
	Meyer pac	Cantrell	- 1-7-3	Carlson	3/7	1-4-
SURNAME &	3/6/73		13/4			15
DATE &	A company of the					
4EC-318 (Rev.)	9-531 AECM 0240					

-ing this inspection, it was found that certain of your activities appeared to be in violation of AEC requirements, and other activities appeared to raise questions concerning the safety of operations. The items and references to the pertinent requirements and to generally accepted guidance are listed in the enclosures to this letter. This letter constitutes a notice sent to you pursuant to the provisions of Section 2.201 of the AEC's "Rules of Practice," Fart 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within 20 days of your receipt of this notice, a written statement of explanation in reply, including: (1) corrective steps which have been or will be taken by you, and the results achieved: (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. In addition to the need for corrective action regarding these specific deficiencies, we are concerned about the implementation of your management control system that permitted these deficiencies to occur. Consequently, in your reply, you should describe in particular, those actions taken or planned to improve the effectiveness of your management control system.

As indicated in Enclosure 1 of this letter, we have noted that you had corrected the first item of 4c and the first and third items of 5a, therefore, you need not address yourself to these matters in your response.

Should you have any questions concering this inspection, we will be pleased to discuss them with you.

Sincerely,

James F. O'Reilly Director

Enclosures:

- 1. Description of Violations
- 2. Description of Safety Items

Co: T. J. McCluskey Oyster Creek Fuclear Generating Station T. O. Box 388 Forked River, New Jersey 08731 bcc: RO Chief, Reactor Test & Operations Branch, HQ

RO:HQ (4) RO Directors

Directorate of Licensing, HQ (4)

DR Central Files

PDR

Local PDR

NSIC

DTIE

State of New Jersey