			GE 1 OF 2
PRAIRIE ISLAND NUCLEAR GENERATING PLANT NORTHERN STATES POWER COMPANY		EMERGENCY PLAN IMPLEMENTING PROCEDURES	
		Number: TABLE OF CO	TENTS Down 29
NORTHERN STR	ALES POWER COMPANY	Number: India of con	History Copy
		Retention Time:	Lifetime
Reviewed By: Approved By:	Supt Rad Protection	_ TITLE: F3	
	Plant Managor	EMERGENCY PLAN IMPLEMENTING PROCEDURES TABLE OF CONTENTS	
Date:	9-25-84		
NUMBER	TITLE		REV #
1	Onsite Emergency Organiza	tion	4
2	Classifications of Emerge	encies	5
3	Responsibilities During a Notification of Unusual Event		4
4	Responsibilities During an Alert, Site Area, or General Emergency		10
5	Emergency Notifications		30
6	Activation and Operation of Technical Support Center		4
7	Activation and Operation of Operational Support Center		4
8	Recommendations for Offsite Protective Actions		3
9	Emergency Evacuation		3
10	Personnel Accountability		5
11	Search and Rescue		1
12	Emergency Exposure Control		2
13	Offsite Dose Calculations		6
14.1	Onsite Radiological Monit	oring	2
14.2	Operations Emergency Surv	reys	2
841	1020183 841008 ADDCK 05000282 PDR		

1

1

Table of Contents Page 2 Rev. 29

1

NUMBER	TITLE	<u>REV #</u>
15	Responsibilities of the Radiation Survey Teams During a Radioactive Airborne Release	7
16	Responsibilities of the Radiation Survey Teams During a Radioactive Liquid Release	5
17	Core Damage Assessment	2
18	Thyroid Iodine Blocking Agent (Potassium Iodide)	2
19	Personnel and Equipment Monitoring and Decontamination	0
20	Manual Determination of Radioactive Release Concentrations	4
21	Establishment of a Secondary Access Control Point	3
22	Prairie Island Radiation Protection Group Response to a Monticello Emergency	2
23	Emergency Sampling	7
23.1	Emergency Hotcell Procedure	0
23.2	Post Accident Chloride Analysis by Ion Exchange Chromatography	
24	Record Keeping During an Emergency	1
25	Re-Entry	2
26	Operation of the Recall Display Computer	1
27	DELETED	
28	Review and Revision of Emergency Flans	0
29	Emergency Security Procedures	2

TITT

	PAGE 1 OF 16
PRAIRIE ISLAND NUCLEAR	EMERGENCY PLAN IMPLEMENTING PROCEDURES
GENERATING PLANT NORTHERN STATES POWER COMPANY	Number: F3-1 Rev: 4
	History Copy Retention Time: Lifetime
Reviewed By: Supt. Rad Protection Approved By: Plant Manager	TITLE: ONSITE EMERGENCY ORGANIZATION _
O.C. Date: 9-25-84	

1.0 PURPOSE

The purpose of this instruction is to:

- Specify the onsite emergency organization during normal and off normal hours.
- (2) Specify primary designates and alternates for key emergency organization positions, and
- (3) Establish individual responsibilities and duties.

The onsite emergency organization is illustrated in Figure 1, and is comprised of personnel from the normal plant organization. The detailed organization discussed in this procedure may be further augmented or decreased as the needs of the emergency condition dictate.

2.0 PRECAUTIONS

- (1) Prairie Island plant staff <u>shall</u> not make any information releases to members of the news media or the public. All inquiries by the news media shall be directed to the NSP Communications Department at NSP Headquarters or to the Joint Public Information Center (JPIC) located at the Minnesota State Capitol in St. Paul.
- (2) In order to provide a sufficient number of alternates to fill the various Prairie Island emergency organization positions, some individuals (by title) are listed in more than one emergency organization position. In the event that an individual is assigned to more than one emergency organization position, the position required to implement immediate actions by the onsite emergency organization shall take precedence over all other positions.

IBM

3.0 APPLICABILITY

This procedure is applicable to all plant personnel.

4.0 RESPONSIBILITIES

4.1 DIRECTION AND CONTROL

4.1.1 Emergency Director (ED)

During the initial stages of an emergency condition, the Emergency Director has overall coordinating authority for NSP. The Emergency Director has the authority and responsibility to immediately initiate any emergency actions including providing protective action recommendations to offsite authorities responsible for implementing offsite emergency measures. Following activation of the corporate emergency organization, the Emergency Manager shall assume the offsite coordinating authority and the Emergency Director shall retain the responsibility for onsite operations.

During an emergency, the Duty Shift Supervisor of the unaffected unit assumes the responsibility of the Emergency Director.

The Shift Supervisor of the unaffected unit shall be relieved of the Emergency Director responsibilities when the designated Emergency Director arrives onsite. The Plant Manager shall be the designated Emergency Director and shall be available with a pager on a twenty-four (24) hour basis. When he is unavailable, (e.g., out of town), the designated Emergency Director responsibility and pager shall be passed down to the next individual in the line of succession.

Any of the individuals above the Shift Supervisor in the line of succession may take over the responsibility of the Emergency Director until the designated Emergency Director arrives onsite.

- A. The line of succession for the Emergency Director position is as follows:
 - (1) Plant Manager
 - (2) Plant Supt. Engr. and Rad Prot.
 - (3) Plant Supt. Operations & Maintenance
 - (4) Supt. Radiation Protection
 - (5) Duty Shift Supervisor of Unaffected Unit

- NUTE: (a) The duty Shift Supervisor of the affected unit, until relieved, shall remain in the Control Room at all times during accident situations to direct the activities of the Control Room operators.
 - (b) Exceptions to the line of succession for the Emergency Director position are individuals serving as
 STA. The STA shall not assume other emergency organization positions until he is formally relieved by an alternate STA.

B. The responsibilities of the Emergency Director are:

- Coordinate response of the plant onsite emergency organization;
- (2) Notification of offsite authorities;
- Recommend offsite protective actions (the responsibility to authorize offsite protective action recommendations may not be delegated);
- (4) Direct the activation of all onsite emergency response centers, delegate coordinators for all onsite emergency response centers, and ensure that the emergency response center's environment is being monitored for habitability
- (5) Direct onsite protective actions as necessary;
- (6) Insure twenty-four (24) hour coverage for key positions in the onsite emergency organization;
- (7) During plant evacuations, initiate and ensure that personnel accountability is completed within thirty (30) minutes of declaration of emergency and maintained throughout the emergency condition;
- (8) Authorize radiation exposure in excess of normal limits;

(9) Ensure that radiologic: 1 monitoring (onsite and offsite) is initiated (when required).

4.1.2 Emergency Manager (EM)

During an Alert, Site Area or General Emergency, the Corporate Nuclear Emergency Organization shall be activated. It is expected that the Corporate Organization can be fully activated within approximately 2 hours of notification. The Corporate Organization will base their operations at the Near-Site EOF, under the direction of the Emergency Manager (EM). A designated EOF Coordinator will be available at the EOF within 1 hour and may assume the Emergency Manager responsibilities until the designated Emergency Manager arrives.

The Emergency Manager shall assume, from the Emergency Director, responsibility for overall management of all offsite support efforts. This includes efforts performed to enhance control of the plant and efforts performed to determine the potential or actual radiological impact in the environs of the plant.

A. Emergency Manager - alternates

The Emergency Manager position should normally be staffed by the General Manager, Nuclear Plants. In his absence, the position shall be filled in a timely fashion by use of a call list. A designated EOF Coordinator may fill the role of Emergency Manager until one of the following arrives at the EOF.

- (1) General Manager Nuclear Plants
- (2) Manager Nuclear Technical Services
- (3) General Supt. Rad. Prot. and Chem.
- (4) Asst. to General Mgr. Nuclear Plants
- (5) Production Training Manager
- (6) General Manager Headquarters Nuclear Group
- B. The responsibilities of the Emergency Manager are:
 - Determine the extent of the offsite response.
 - (2) Make recommendations for the potential need for protective actions.
 - Supervise the operation of the EOF.

- F3-1 Rev. 4 Page 5
- (4) Direct personnel to provide the necessary offsite support for the plant as requested by the Emergency Director.
- (5) Provide technical support as necessary.
- (6) Provide direction to personnel performing offsite radiation surveys and dose estimates as to the desired types of samples and sample location.
- (7) Direct the activation of the Emergency Radiological Environmental Monitoring Program (EREMP) as needed.
- (8) Direct personnel to provide the necessary logistics support for the plant and EOF operation.
- (9) Provide information to the Power Production Management, as necessary, to assist in development of news releases.
- (10) Provide a direct interface with NRC representatives assigned to the EOF.
- (11) Provide overall guidance to the corporate staff operating the HQEC in the event that the Power Production Management is not available to assume control of HQEC operations.

4.2 EMERGENCY ORGANIZATION COORDINATORS

4.2.1 Technical Support Center Coordinator

The Technical Support Center Coordinator shall be responsible for the general activation, operation and coordination of activities in the Technical Support Center (TSC).

- A. The Technical Support Center Coordinator alternates are as follows:
 - (1) Supt. Operations Engineering
 - (2) Supt. Technical Engineering
 - (3) Supt. Nuclear Engineering .
 - (4) Supt. QA Engineering
- B. The responsibilities of the TSC Coordinator are:
 - Establish and verify radiological monitoring for the TSC including startup of the TSC cleanup systems;
 - (2) Assist personnel performing the accountability check;

- (3) Maintain or designate individuals to maintain records throughout the emergency condition.
- (4) Coordinate activities of plant and non-plant personnel located in the TSC;
- (5) Establish or ensure that communications are established between all onsite emergency facilities and the EOF;
- (6) Ensure plant status is obtained via Data Recall computer, plant process computer and/or via the communicator assigned to the Control Room;
- (7) Periodically update personnel located in the TSC with appropriate information;
- (8) Maintain any necessary status boards;
- (9) Control the use of equipment located in the emergency locker;
- (10) Provide technical guidance to the Emergency Director and Control Room operators on plant operations;
- (11) Obtain technical assistance as required to support the Control Room operations.

4.2.2 Operational Support Center Coordinator

The Operational Support Center Coordinator shall be responsible for the general activation, operation, and coordination of activities in the Operational Support Center (OSC).

- A. The Operational Support Center Coordinator Piternates are as follows:
 - (1) Maintenance Supervisors (Mechanical)
 - (2) Maintenance Supervisor (Electrical)
 - (3) I & C Supervisor
- B. The responsibilities of the OSC Coordinator are:
 - Establish and verify radiological monitoring for the OSC and the Control Room;
 - (2) Coordinate activities of plant personnel located in the OSC to support plant operations as requested by the Control Room and TSC.

- (3) Assist personnel performing the accountability check.
- (4) Maintain the communications systems in the OSC. A person may be designated to act as a communicator.
- (5) Issue dosimetry to OSC and Control Room personnel.
- (6) Ensure OSC status boards are updated as required.
- (7) Periodically update personnel located in the OSC with appropriate information.
- (8) Control the use of equipment located in the emergency locker.

4.2.3 Assembly Point Coordinator

The Assembly Point Coordinator shall be responsible for the general operation of the assembly area.

- A. The Assembly Point Coordinator alternates are as follows:
 - Radiation Protection Specialist, as directed by the Emergency Director
- B. The responsibilities of the Assembly Point Coordinator are:
 - Verify that radiological monitoring has been established for the Assembly Point.
 - (2) Coordinate activities of all personnel (plant and non-plant) located at the Assembly Point.
 - (3) Assist the Emergency Director in performing the accountability check, as necessary.
 - (4) Maintain the communication systems. A person may be designated as the communicator, if necessary.
 - (5) Control the use of equipment located in the Emergency Locker.
 - (6) Update all personnel with appropriate information when directed by the Emergency Director.

(7) Provide instructions to personnel when they are released from the assembly point for reentry or transport offsite.

4.2.4 Radiological Emergency Coordinator

The Radiological Emergency Coordinator (REC) shall be responsible for radiological accident assessment, onsite and offsite. The REC shall report to the Technical Support Center when the TSC is activated. Upon activation of the Near-Site EOF, the Radiation Protection Support Supervisor shall assume responsibility for the offsite accident assessment.

- A. The Radiological Emergency Coordinator (REC) alternates are as follows:
 - (1) Supt. Rad Protection
 - (2) Principal Prod Engr Rad Prot Section
 - (3) Rad Protection Supervisor
 - (4) Radio-Chemistry Supervisor
- B. The responsibilities of the REC are:
 - (1) Offsite dose assessment
 - (2) Formulating offsite protective action recommendations
 - (3) Offsite surveys
 - (4) Onsite surveys
 - (5) Chemistry
 - (6) Radiochemistry
 - (7) Onsite Radiation Protection for:
 - (a) access control
 - (b) damage control and repair
 - (c) search and rescue
 - (d) first-aid
 - (e) fire fighting
 - (f) personnel monitoring & decontamination
 - (g) dosimetry

4.3 SHIFT ORGANIZATION

4.3.1 Operations Group

The Operations Group consist of the Supt. Operations, Shift Supervisors, and all operators.

A. Group Leader - Line of Succession

- (1) Supt. Operations
- (2) Duty Shift Supervisor
- (3) Senior Shift Supervisor present
- (4) Senior Lead or Reactor operator present
- B. Responsibilities

The Operations Group shall have responsibility for:

- Plant Operations and assessment of operational aspects of the emergency.
- (2) Rad Waste equipment operation
- (3) Emergency radiation surveys
- (4) Short term damage control and repair for electrical, mechanical, and I & C equipment

4.3.2 Security Group

The Security Group consists of the Supervisor, Security and Services, the Shift Security Supervisor and the contract Guard Force.

- A. Group Leader Line of Succession
 - (1) Supervisor Security and Services
 - (2) Shift Security Supervisor

B. Responsibilities

The Guard Force shall:

- Carry out the plant security and Access Control program.
- (2) Maintain strict personnel accountability onsite.
- (3) Assist communications efforts when necessary.
- (4) Assist in first aid treatment.

4.3.3 Shift Technical Advisor (STA)

The Shift Technical Advisor (STA) shall be onsite continuously. The STA acts as an advisor to the Shift Supervisor when on shift.

A. STA - Line of Succession

STA duty roster

- B. Responsibilities
 - Provide technical support to the Shift Supervisor in the area of operational event evaluation.
 - (2) Provide the Shift Supervisor technical and engineering support in the area of accident assessment.

NOTE: The Shift Technical Advisor shall not be assigned or assume duties which could in any way inhibit his accident assessment advisory function during an emergency, until properly relieved of his STA duties by another Shift Technical Advisor.

4.3.4 Shift Emergency Communicator (SEC)

The Shift Emergency Communicator (SEC) shall be onsite continuously. The SEC is responsible for initial notification and maintaining communications during emergency conditions.

A. SEC - Line of Succession

SEC duty roster

- B. Responsibilities
 - Initial notification of offsite agencies and personnel.

NOTE: When the Corporate Emergency Organization is activated and the Near-Site EOF is functional, the communications with the offsite agencies and personnel shall be maintained by the EOF personnel.

- (2) Augmentation of the plant staff.
- (3) Maintain communication systems throughout the emergency situation.

NOTE: As the emergency organization is activated, addition communicators on the SEC duty roster personnel should augment the plant staff to assist in the communication efforts.

4.3.5 Fire Brigade

The Fire Brigade should consist of:

- (1) Brigade Chief Unit 2 Shift Supervisor
- (2) Assistant Chief Turbine or Auxiliary Building APEO

NOTE: Usually the APEO from the affected building shall fulfill the duties of the Brigade Chief in his absence.

- (3) Fire Fighters BOP Operators and Excess CR Operators (two operators per unit shall remain in the Control Room.
- (4) Runner As designated to accompany fire department or operate equipment.

During normal work hours, emergency assistance may be provided by maintenance and plant helpers. During backshifts, or at the discretion of the Brigade Chief, the Red Wing Fire Department shall provide Emergency assistance and shall be called immediately on report of any fire requiring Fire Brigade Action.

- A. Fire Brigade Chief Line of Succession
 - (1) Unit 2 Shift Supervisor
 - (2) Turbine or Auxiliary Building APEO
- B. Responsibilities
 - The Fire Brigade shall be responsible for fire fighting.

4.3.6 Shift Radiation Protection Specialist

The Shift Radiation Protection Organization consist of one Radiation Protection Specialist onsite at all times.

- A. Shift RPS Line of Succession
 - (1) Shift RPS
 - (2) Control Room licensed operators are trained to perform emergency radiation surveys.
- B. Responsibilities

During emergency conditions, the shift Radiation Protection Specialist shall be responsible for:

- (1) In-Plant surveys
- (2) Chemistry
- (3) Radiochemistry
- (4) Dose Assessment

NOTE: The Control Room licensed operators are responsible to perform emergency radiation surveys.

4.4 Emergency Staff Augmentation Groups

4.4.1 Maintenance Group

The Maintenance Group consists of all maintenance crew personnel, all plant electricians, and plant helpers. The onsite Emergency Organization includes, the Plant Supt. Operations and Maintenance, and the Supt. Maintenance, who shall report to the Technical Support Center (TSC); and the Maintenance Supervisors (Mechanical & Electrical), and designated Electricians who shall report to the Operational Support Center (OSC). The mechanical and electrical maintenance staff in the OSC can be further augmented or decreased as emergency conditions dictate.

A. Group Leader - Line of Succession

- (1) Supt. Maintenance
- (2) Maintenance Supervisors
- B. Responsibilities

The Mechanical and Electrical Maintenance Group shall have responsibility for:

- Supporting the repair and corrective actions for the mechanical and electrical systems in support of emergency response and recovery actions.
- (2) Supporting the Search and Rescue effort.

4.4.2 Instrument and Control Group

The Instrument and Control Group consists of all I & C Specialists including I & C Coordinators and the I & C Supervisor. The onsite emergency organization includes the Supt, Technical Engineering, who shall report to the Technical Support Center; and the I & C Supervisor and Coordinators who report to Operational Support Center. The I & C Group can be further augmented or decreased as emergency conditions dictate.

- A. Group Leader Line of Succession
 - (1) Supt. Technical Engineer
 - (2) I & C Supervisor
 - (3) I & C Coordinators

B. Responsibilities

The I & C Group shall be responsible for:

- Supporting the repair and corrective actions for the instrument and control systems in support of emergency response and recovery actions.
- (2) Supporting the search and rescue effort.

4.4.3 Radiation Protection Group

The Radiation Protection Group consists of the Supt. Radiation Protection and all members of the Radiation Protection Group.

- A. Group Leader Line of Succession
 - (1) Supt. Radiation Protection
 - (2) Principal Prod Engr Rad Prot Section
 - (3) Radiation Protection Supervisor
 - (4) Radiochemistry Supervisor
 - (5) Rad Protection Coordinator

B. Responsibilities

The responsibilities of the Radiation Protection Group are:

- (1) Offsite Dose Assessment
- (2) Offsite Surveys
- (3) Onsite Surveys
- (4) Chemistry
- (5) Radiochemistry
- (6) Radiation Protection for:
 - (a) Access Control
 - (b) Damage control and Repair
 - (c) Search and rescue
 - (d) First aid
 - (e) Fire fighting
 - (f) Personnel monitoring and decontamination
 - (g) Dosimetry

4.4.4 Engineering Group

The Engineering Group consists of Operation Engineers, Nuclear Engineers, Radiation Protection Engineers, Technical Engineers, Quality Assurance Engineers, Staff Engineer, and Scheduling Engineer.

Upon activation of the onsite emergency organization, all Engineering Superintendents and engineers assigned to the emergency organization shall report to the Technical Support Center. Other designated engineers may be requested to further augment engineering support in the TSC, as required.

- F3-1 Rev. 4 Page 15
- A. Group Leader Line of Succession
 - Plant Supt. Engineering and Rad Protection
 - (2) Supt. Operations Engineering
 - (3) Supt. Technical Engineering
 - (4) Supt. Nuclear Engineering
 - (5) Supt. Quality Assurance Engineering
- B. Responsibilities

The Engineering Group shall have responsibility for:


- Providing technical support for emergency repairs and corrective actions on electrical/mechanical systems.
- (2) Providing technical support for plant system engineering on electrical/mechanical systems.
- (3) Providing technical support for operating radioactive waste control systems.
- (4) Providing core parameter analysis to determine current core status.

4.4.5 Logistics Support Group


The Support Group consists of the Purchasing and Inventory Control Group, the Administrative Services Group, and the Document Control Group.

- A. Group Leader Line of Succession
 - (1) Plant Office Manager
 - (2) Administrative Services Supervisor
- B. Responsibilities

The Support Group shall supply logistical support in their area of expertise. Personnel in these may be called in to provide support for emergency response on an as needed basis.



Control Room or the Tech Support Center



	PAC	GE 1 JF 48
PRAIRIE ISLAND NUCLEAR	EMERGENCY PLAN IM PROCEDURES	PLEMENTING
GENERATING PLANT NORTHERN STATES POWER COMPANY	Number: F3-2	Rev: 5
	Retention Time:	History Copy Lifetime
Reviewed By: A. Schuelke Supt Rad Protection	TITLE:	
Approved By: Plant Manager	CLASSIFICATIONS OF EMERGENCIES	
O.C. Date: 9-25-84		

1.0 PURPOSE

The purpose of this procedure is to specify the Emergency Action Levels that indicate that an emergency condition exists and to properly classify the emergency into one of the four graded levels of emergency classifications.

2.0 APPLICABILITY

This instruction SHALL apply to all Shift Supervisors, Control Room Operators, Shift Technical Advisors and Emergency Directors.

- 3.0 PRECAUTIONS
 - 3.1 The operator should believe his indications and take action based on those indications, however, he shall attempt to verify his indications by checking secondary or coincident indicators.
 - 3.2 Continuously monitor the control room instrumentation, radiation monitors, or any other developments which would be indicative of further system degradation. Be prepared to escalate to a more severe emergency classification.

4.0 DISCUSSION

- 4.1 Definitions
 - 4.1.1 <u>Notification of Unusual Event</u> events that are in progress or have occurred which indicate a potential degradation of the level of safety of the plant.

No releases of radioactive material requiring offsite response or monitoring are expected unless further degradation of safety systems occurs.

IBM

4.1.2 <u>Alert</u> - events are in progress or have occurred which involve actual or potential substantial degradation of the level of safety of the plant. It is the lowest level of emergency classification when some necessity for emergency planning and offsite response is necessary.

> Any releases expected are limited to small fractions of the EPA Protective Action Guideline exposure levels.

4.1.3 <u>Site Emergency</u> - events are in progress or have occurred which involve actual or likely major failure of plant functions needed for protection of the public.

> Any releases are not expected to exceed the EPA Protective Action Guideline exposure levels except near the site boundary.

4.1.4 <u>General Emergency</u> - events are in progress or have occurred which involve actual or imminent substantial core degradation or melting with a potential for loss of containment integrity.

> Releases during a General Emergency can be reasonably expected to exceed the EPA Protective Action Guideline exposure levels offsite for more than the immediate site area.

4.1.5 <u>Emergency Action Levels (EAL)</u> - specific instrument readings, surface or airborne contamination levels or radiation dose rates that designate a specific emergency class requiring emergency measures for that class.

4.2 Summary

Attached to this procedure is a Summary of Emergency Action Levels. This table identifies the four emergency classifications, the initiating conditions(s), emergency actions levels for each classification, and, where applicable, specific instruments and indications to be used to detect and classify an emergency. The emergency action levels for each classification and the instrument readings and indications listed do not reflect a complete list of instrumentation that will show abnormal indications but does list those key parameters useful in classifying the event.

The Summary of Emergency Action levels lists the initiating conditions as required by Appendix 1 of NUREG-0654 and accidents analyzed in the Prairie Island FSAR.

5.0 PROCEDURE

5.1 Any significant event that may be classified as an emergency condition shall be reported to the Shift Supervisor immediately.

> NOTE: The events may be instrumentation readings or visual observations made by plant personnel.

- 5.2 Attempt to verify the initial indication by comparing the indication to redundant instrument channels or to other related parameters, visual observations, and field reports as applicable.
- 5.3 Assess the situation and determine the emergency classification, using the guidelines of Attachment 1.

NOTE: Personnel should become familiar with Attachment 1 during training sessions.

- 5.4 Take immediate actions, using applicable plant operating procedures, Sections C and E of the Operations Manual, to return the plant to normal (or cold shutdown, if determined to be necessary).
- 5.5 Declare the appropriate emergency classification and perform actions as specified in the appropriate responsibility procedure applicable to emergency classification:
 - 5.5.1 For a Notification of Unusual Event, proceed to F3-3
 - 5.5.2 For an Alert, Site or General Emergency, proceed to F3-4.

- 5.6 Continue to assess and respond to the emergency condition.
 - NOTE: Watch for changing parameters or visual indication of further system degradation and be prepared to escalate to a more severe emergency classification as indicated by the Emergency Action Levels in Attachment 1.
- 5.7 As plant conditions stabilize, downgrade or terminate the emergency classification, as appropriate, as per the guidelines of Attachment 1.

NOTE :	Depending upon the severity of the
	accident, it may not be possible to
	downgrade the emergency classification
	following the guidelines of Attach-
	ment 1. Therefore, once the plant
	is in a stable mode and long-term
	cooling has commenced, the emergency
	condition may be reclassified and/or
	terminated and long-term recovery
	initiated. The Emergency Director
	should consult the Emergency Manager
	prior to reclassification and/or
	termination and initiation of the
	long-term recovery.

Attachment 1

SUMMARY

OF

EMERGENCY ACTION LEVELS

.

1

C

-

ATTACHMENT 1

INITIATING CONDITION INDEX

No.	Condition Description	Page
1	Safety System Functions	7
2	Abnormal Primary Leak Rate	10
3	Abnormal Coolant Temperature/Pressure	13
4	Abnormal Primary/Secondary Leak	14
5	Core Fuel Damage	16
6	Loss of 2 of 3 Fission Product Barriers	17
7	Secondary Coolant Anomaly	24
8	Radiological Effluents	27
9	Major Electrical Failures	30
10	Control Room Evacuations	33
11	Fires	34
12	Plant Shutdown Functions	35
13	Fuel Handling Accidents	38
14	Coolant Pump	40
15	Serious or Fatal Injury	41
16	Security Threats	42
17	Hazards to Plant Operations	43
18	Natural Events	46
19	Other	48

-

Attachment 1

CONDITION #1

SAFETY SYSTEM FUNCTIONS

Initiating Condition

ECCS initiated and discharge to vessel. NOTE: FSAR Sections 14.2.4 14.2.5 14.2.6 14.3

Indication Used

- First out on reactor trip panel:

 Containment High Pressure SI-Reactor Trip; or
- Classification

Alert

- b. A Steam Generator Lo-Lo Pressure SI; or
- c. B Steam Generator Lo-Lo Pressure SI; or
- d. Pressurizer Lo Pressure SI

and

- 2. Confirmation 1rcm indicators:
 - a. 2/3 High Containment Pressure (4psig) PI-945, PI-947, PI-949; or
 - b. 2/3 Lo Steam Line Press. Loop A (500 psig) PI-468, PI-469, PI-482A; or
 - c. 2/3 Lo Steam Line Press. Loop B (500 psig) PI-478, PI-479, PI-483A; or
 - d. Lo Prz. Press (1815 psig) PI-429, PI-430, PI-431

and

 Confirmation of SI Flow indicated by FI-925 and FI-924.

or

 Manual SI-Reactor Trip initiated if Auto SI did not occur at confirmed indicator setpoints (#2 above) or when pressurizer level is off scale low on at least 2/3 channels, LI-426, LI-427, LI-428.

Loss of Containment integrity requiring shutdown by technical specification Loss of Containment Integrity, defined Notification of by Technical Specification 3.6, Unusual Event which requires a unit shutdown, as determined by the Shift Supervisor.

Attachment 1

CONDITION	#1 ((Cont'	d)
-----------	------	--------	----

SAFETY SYSTEM FUNCTIONS				
Initiating Condition	Indication Used Engineered Safety Feature found inoperable, as defined by Technical Specification 3.3, which requires a unit shutdown, as determined by the Shift Supervisor. Loss of fire protection systems, defined by Technical Specification 3.14, which requires a unit shutdown, as determined by the Shift Supervisor.		Classification Notification of Unusual Event	
Loss of engineered safety feature requiring shutdown by Technical Specification				
Loss of fire protection system function requiring shutdown by Technical Specification			Notification of Unusual Event	
Failure of a safety or relief value in a safety related system to close following reduction of		nd then fails to reset, as U	Notification of Nusual Event	
applicable pressure.	1. (a)	Annunciator "Pressurizer Safety/Relief Valve Flow"; and		
	(b)	Annunciators;		
		(1) "Pressurizer Power Relief line High Temp; or		
		(2) "Pressurizer Safety Valve line A or B High Temp"		
	or			
	(c)	Safety/Relief line high Temper- ature indicated by		
		<pre>(1) Pressurizer safety valve outlet temperature, TI-436 > 225°F; or</pre>		
		<pre>(2) Pressurizer safety valve outlet temperature, TI-437 > 225°F; or</pre>		
		(3) Pressurizer relief valve outlet temperature, TI-438 > 225°F.		

Classification

Unusual Event

Attachment 1

CONDITION #1 (Cont'd)

SAFETY SYSTEM FUNCTIONS

Initiating Condition

Indication Used

Steam Generator safety or relief valve Notification of opens and then fails to reset, as indicated by:

- 1. Visual and/or audible indication at vent stacks of open steam generator safety or relief valve; and
- 2. As determined by Shift Supervisor

-

Attachment 1

CONDITION #2

ABNORMAL PRIMARY LEAK RATE

Initiating Condition	Indication Used	Classification		
Primary system leak rate from unidentified or uncon- trolled sources exceeding Technical Specifications	 Primary system leak rate, other than controlled leakage sources, exceeds Technical Specification 3.1.c; and Notification of Unusual Event 			
	 Requires a unit shutdown, as determined by the Shift Supervisor. 			
Primary coolant leak rate greater than 50 gpm	 (a) Decreasing pressurizer level, as indicated by LI-426, LI-427, LI-428; or 	Alert		
	(b) High radiation levels in contain ment, as indicated by:	•		
	R2 High Alarm - 50mR/hr; or R7 High Alarm - 50mR/hr; or			
	R-11 (Containment Position) High Alarm - 5 x 10 cpm, R-12 (Containment Position) High Alarm - 6 x 10 cpm; and	or		
	 Annunciator "Charging Pump in Auto High/Low Speed"; and 			
	 Charging line flow (FI-128B) greater than 50 gpm more than Letdown Flow (FI-134). 			
	NOTE: Rapid Temperature decrease in RCS results in same			
	indications however no primary coolant leak rate.			

Attachment 1

CONDITION #2 (Cont'd)

ABNORMAL PRIMARY LEAK RATE

Initiating Condition

jection).

Indication Used

Loss of coolant accident 1. 1 with leak rate in excess of available pump capacity (Charging, High Head Injection, and Low Head In-

 No Pressurizer Level indicated by LI-426, LI-427, LI-428

and

 All available pumps running as indicated by the red light at the switch.

Small LOCA and initially successful ECCS. Subsequent failure of containment heat removal systems over several hours could lead to core melt and likely failure of containment.

- 1. LOCA has occurred; and
- Inadequate containment cooling exists, as indicated by:
 - (a) Containment temperature has become excessive, > 300°F, and is still rising; or
 - (b) Containment pressure > 23 psig with minimum containment pressure suppression equipment not available:
 - No fan cooler units operating and less than two spray pumps; or
 - (2) No spray pumps operating and less than four fan cooler units; or
 - (3) Less than two fan cooler units running with one spray pump.

Small and large LOCA's with failure of ECCS to perform leading to severe core degradation or melt in from minutes to hours. Ultimate failure of containment likely for melt sequences. 1. Loss of coolant indicated by:

General Emergency

(a) (1) Pressurizer low pressure trip (1900 psig); or RCS pressure decreasing uncontrollably;

and

General Emergency

Classification

Site Area Emergency

Attachment 1

CONDITION #2 (Cont'd)

ABNORMAL PRIMARY LEAK RATE

Initiating Condition

Indication Used

Classification

(2) High containment pressure; or High containment humidity; or High containment sump levels; or High containment radiation levels

and

(3) Steam Generator's A and B pressures equal

or

- (b) (1) Decreasing RCS pressure; and
 - (2) Loss of subcooling margin (<10°F)</p>

and

- 2. Fuel Damage indicated by:
 - a. R48 High Alarm 2 x $10\frac{4}{4}$ R/hr; or R49 High Alarm - 2 x 10 R/hr

or

 b. High RCS activity, > 300 µCi/cc iodine equivalent, as determined by sample analysis

and

- 3. Loss of ECCS indicated by
 - (a) High head SI failure; or
 - (b) Low head SI failure.

Attachment 1

CONDITION #3

6

ABNORMAL COOLANT TEMPERATURE/PRESSURE

Initiating Condition	Indication Used	Classification
Abnormal coolant tempera- ture and/or pressure or abnormal fuel temperatures	At Steady State Power Operations; 1. T _{avg} > 564°F; <u>or</u>	Notification of Unusual Event
outside of Technical Specification limits.	2. RCS pressure > 2385 psig; or	
	 RCS pressure < 2205 psig, and core exit temperature > 620°F, as indicated by a valid thermocouple; 	
	or	
	4. Core Subcooling Margin < 10°F.	

-

Attachment 1

CONDITION #4

*

10.00

1

н.

Initiating Condition	Indication Used	<u>Classification</u> Notification of Unusual Event	
Primary/Secondary leak rate exceeding Technical Specification of 1.0 gpm requiring a unit shutdown	When shutdown commences, as deter- mined by the Shift Supervisor and Duty Engineer		
Failure of steam generator tube(s) resulting in ECCS initiation	 First out on reactor trip panel: "Pressurizer Low Press SI" and 	Alert	
	 Confirmation from Prz. Press indi- cators, PI-429, PI-420, PI-431, (2/3 Low pressure, 1815 psig). 		
	and		
	3. Annunciators: a. "A SG High Water Level" or b. "B SG High Water Level"		
	and		
	 4. Confirmation from SG level indicators: a. LI-461, LJ-462, LI-463 (2/3 greater than 67%) or b. LI-471, LI-472, LI-473 (2/3 greater than 67%) 		
	5. Safety injection flow indicated by FI-925 and FI-924 and pump discharge pressure corresponding to flow		
Failure of steam generator tube(s) resulting in ECCS initiation and loss of offsite power	 First out on reactor trip panel: "Pressurizer low pressure SI" and 	Site Area Emergeno	

Attachment 1

CONDITION #4 (Cont'd)

ABNORMAL PRIMARY/SECONDARY LEAK

Initiating Condition

Indication Used

Classification

 Confirmation from Prz. Press indicators: PI-429, PI-430, PI-431 (2/3 low pressure, 1815 psig)

and

3. Annunciators: a. "A SG Water Level High" or b. "B SG Water Level High"

and

- 4. Confirmation from SG level indicators: a. LI-461, LI-462, LI-463 (2/3 greater than 67%) or
 - b. LI-471, LI-472, LI-473 (2/3 greater than 67%)

and

 Safety injection flow indicated by FI-626 and FI-928

and

 All of the following indicators:
 a. 4.16 KV bus voltage (0 Volts) Buses 11-14 and 21-24

and

- b. D1 and D2 generators running and closed in on safeguard buses:
 - (1) D1 & D2 Tach, (~ 900 rpm)
 - (2) D1 & D2 Volts, (4260-4380 Volts)
 - (3) Safeguard breakers closed Bus 15, Breaker 15-2 Bus 26, Breaker 26-2 Bus 16, Breaker 25-6 Bus 25, Breaker 16-7

-

Attachment 1

CONDITION #5	Attachment 1	
CORE FUEL DAMAGE		
Initiating Condition	Indication Used	Classification
Fuel Damage Indication	 Hi Alarm on letdown line radiation monitor, R-9, indicating greater than 1 R/hr and confirmed by portable instrumentation 	Notification of Unusual Event
	or	
	 High coolant activity sample: a. exceeding Technical Specific activity in primary coolant <u>or</u> b. exceeding Technical Specification limit on primary coolant iodine activity which requires a unit shutdown. 	
Severe loss of fuel cladding	 Very high coolant activity sample; 300 µCi/cc iodine equivalent, as determined by chemical analysis 	Alert
	or	
	 Letdown line radiation monitor R-9 in alarm mode and indicating greater than 10 R/hr, as con- firmed by portable instrumentation 	
Degraded core with	1. Degraded core, indicated by:	Site Area Emergency
possible loss of coolable geometry	 (a) High primary coolant activity, > 300 µCi/cc; or (b) High core exit temperature, indicated by exit thermocouples, > 700°F; or (c) Inadequate subcooling margin, < 10°F; or (d) Indication of core uncovered (Shift Supervisor's opinion) 	
	and 2. Loss of coolable geometry, indicated	hv
	 (a) Core ΔT increasing; or (b) No core ΔT; or (c) Shift Supervisor's opinion 	, by .

Attachment 1

CONDITION #6

LOSS OF 2 OF 3 FISSION PRODUCT BARRIERS

Initiating Condition

Loss of 2 of 3 fission product barriers with a potential loss of 3rd barrier (e.g., loss of primary coolant boundary clad failure, and high potential for loss of containment).

CASE 1: Loss of clad, loss of primary coolant boundary (LOCA), and high potential for loss of containment Three permutations exist for loss of 2 of 3 fission product barriers with a potential loss of 3rd barrier;

- Failure of cladding and primary coolant boundary with potential loss of containment.
- Failure of cladding and containment with potential loss of primary coolant boundary.
- Failure of containment and primary coolant boundary with potential loss of cladding.

These 3 permutations are represented in the following 5 cases, each with its own set of EAL's:

Indication Used

1. LOSS OF CLAD & LOCA, INDICATED

DICATED General Emergency

Classification

A.(1)(a) Very high coolant activity sample; 300 µCi/cc iodine equivalent, as determined by chemical analysis

or

(b) Letdown line radiation monitor R-9 in alarm mode and indicating greater than 10 R/hr, as confirmed by portable instrumentation

and

(2)(a) Pressurizer low pressure trip (1900 psig); or RCS pressure decreasing uncontrollably;

and

(b) High containment pressure; or High containment humidity; or High containment sump levels; or High containment radiation levels

Attachment 1

CONDITION #6 (Coat'd)

LOSS OF 2 OF 3 FISSION PRODUCT BARRIERS Indication Used

Classification

and

(c) Steam Generator's A and B pressures equal

or

- B. Valid high radiation levels in containment, as indicated by:
 - (a) R-48 High Alarm 2×10^4 R/hr; or (b) R-49 High Alarm 2×10^6 R/hr;

and

- 2. POTENTIAL FOR LOSS OF CONTAINMENT, INDICATED BY:
 - A. Containment pressure approaching design pressure (46 psig) and increasing.

or

- B. Loss of containment cooling capability indicated by minimum containment pressure suppression equipment not available:
 - (1) No fan cooler units operating and less than two spray pumps or
 - (2) No spray pumps operating and less than four fan cooler units or
- (3) Less than two fan cooler units running with one spray pump
- or
- C. Control Room status lights indicate both Train A and Train B Containment Isolation valves not closed for any containment penetration and Shift Supervisor's opinion.

Attachment 1

CONDITION #6 (Cont'd)

LOSS	OF	2	OF	3	FISSION	PRODUCT	BARRIERS	
							Indication	Used

Classification

CASE 2: Loss of clad, loss of primary coolant boundary (SG tube rupture), and high potential for loss of containment. 1.LOSS OF CLAD, AND LOSS OF PRIMARY General Emergency COOLANT BOUNDARY (SG TUBE RUPTURE), INDICATED BY:

A.(1) Loss of clad

 (a) Very high coolant activity sample;
 300 µCi/cc iodine equivalent, as determined by chemical analysis

or

(b) Letdown line radiation monitor R-9 in a arm mode and indicating greater than 10 R/hr, as confirmed by portable instrumentation

and

(2) SG Tube Rupture

- (a) First out on reactor trip panel: "Pressurizer Low Press SI"
- and
- (b) Confirmation from Prz. Press indicators PI-429, PI-420, PI-431, (2/3 Low pressure, 1815 psig) and
- (c) Annunciators: "A SG High Water Level" or "B SG High Water Level"

and

(d) Confirmation from SG level indicators: LI-461, LI-462, LI-463 (2/3 greater than 67%)

and

(e) Safety injection flow indicated by FI-925 and FI-924 and pump discharge pressure corresponding to flow

Attachment 1

CONDITION #6 (Cont'd)

1

-

-

	Indication Used	Classification
	or	
	B. Steam Line Monitor in valid hi alarm mode: R-51, > 100 mR/hr; or R-52, > 100 mR/hr and	gh
	2. POTENTIAL FOR LOSS OF CONTAINMEN INDICATED BY:	т,
	A. Steam Generator safety or relie opens and then fails to reset, indicated by:	
	(1) Visual and/or audible indica at vent stacks of open steam generator safety or relief v and	
	(2) As determined by Shift Super	visor
	B. Imminent failure of MSIV, as det by Shift Supervisor	ermined
CASE 3: Loss of clad, containment failure, and	1. LOSS OF CLAD, INDICATED BY:	General emergency
high potential for loss of the RCS boundary.	A. Very high coolant activity samp 300 µCi/cc iodine equivalent, a determined by chemical analysis or	s
	B. Letdown line radiation monitor R-9 in alarm mode and indicating greater than 10 R/hr, as con- firmed by portable instrumentat: and	
	2. LOSS OF CONTAINMENT, INDICATED BY	۲:
	A. Control Room status lights indice both Train A and Train B Contain Isolation valves not closed for containment penetration and Shit Supervisor's opinion.	cate nment any

.

144

5

Attachment 1

CONDITION #6 (Cont'd)

LOSS OF 2 OF 3 FISSION PRODUCT BARRIERS Indication Used Classification or B. Steam line break downstream of MISV, and open-close indicator shows MSIV not closed. or C. Steam line break between containment and the MSIV. and 3. POTENTIAL FOR LOSS OF THE RCS BOUNDARY, INDICATED BY: A. Loss of ECCS indicated by a loss of High head SI capability. CASE 4: Loss of RCS 1. LOSS OF RCS BOUNDARY (LOCA), General Emergency boundary (LOCA), loss of INDICATED BY: containment, and high potential for loss of A. Pressurizer low pressure trip cladding. (1900 psig); or RCS pressure decreasing uncontrollably; and B. High containment pressure; or High containment humidity; or High containment sump levels; or High containment radiation levels and C. Steam Generator's A and B pressures equal and 2. LOSS OF CONTAINMENT, INDICATED BY: A. Control Room status lights indicate both Train A and Train B Containment Isolation valves not closed for any containment penetration. and B. Shift Supervisor's Opinion

Attachment 1

SS OF 2 OF 3 FISSION PROD	UCT BARRIERS	
55 OF 2 OF 5 FISSION FROD	Indication Used	Classification
	and	
	3. POTENTIAL FOR LOSS OF CLADDING, INDICATED BY:	
	A. Reactor vessel level low and decreasing (Shift Supervisor's opinion) or	
	<u>01</u>	
	B. Core exit thermocouples > 700°F and increasing or	
	C. Loss of ECCS indicated by a loss High head SI capability.	of
SE 5: Loss of RCS undary (SG Tube Rupture), ss of containment, and gh potential for loss of adding.	 LOSS OF RCS BOUNDARY (SG TUBE RUPTURE) INDICATED BY: A. First out on reactor trip panel: "Pressurizer Low Press SI" 	General Emergency
auding.	and	
	 B. Confirmation from Prz. Press indicators, PI-429, PI-420, PI-431, (2/3 Low pressure, 1815 psig). and 	
	C. Annunciators: "A SG High Water Level" or	
	"B SG High Water Level" and	
	D. Confirmation from SG level indicators:	
	<pre>(1) LI-461, LI-462, LI-463 (2/3 greater than 67%) or</pre>	
	(2) LI-471, LI-472, LI-473 (2/3 greater than 67%)	

1.4

Attachment 1

CONDITION #6 (Cont'd)

LOSS OF 2 OF 3 FISSION PRODUCT BARRIERS Indication Used

Classification

and

E. Safety injection flow indicated by FI-925 and FI-924 and pump discharge pressure corresponding to flow.

and

F. High Radiation on Condenser Air Ejector and/or Steam Generator Blowdown radiation monitors.

and

- 2. LOSS OF CONTAINMENT, INDICATED BY:
 - A. Steam line break downstream of MSIV, and open-close indicator shows MSIV not closed.

or

B. Steam line break between containment and the MSIV.

and

- POTENTIAL FOR LOSS OF CLADDING, INDICATED BY:
 - A. Reactor vessel level low and decreasing (Shift Supervisor's opinion).

or

B. Core exit thermocouples > 700°F and increasing.

or

C. Loss of ECCS indicated by a loss of High head SI capability.

-

Attachment 1

CONDITION #7

SECONDARY COOLANT ANOMALY

Initiating Condition	Indication Used	Classification		
Rapid depressurization of Secondary Side	 (a) Steam Generator A/B Pressure Differential, ≥ 100 psig; and 	Notification of Unusual Event		
	(b) High Containment Pressure, 4 psig;			
	or			
	 2.(a) Hi Steam Flow, .745 x 10⁶ lb/hr; (b) and Lo-Lo T_{avg}, 540°F 			
	or			
	 Steam line pressure Safety Injection Signal; 	n		
	or			
	 Failed Open Steam Dump, Relief, or Safety Valve; 			
	or			
	5. Shift Supervisors Opinion			
Rapid depressurization of secondary side (any Steam Line Break with 0-50 gpm primary to secondary leak rate) Note: FSAR 14.2.5	 First out on reactor trip panel: a. "A Steam Generator Lo-Lo pressure SI" or b. "B Steam Generator Lo-Lo Pressure SI" 	Alert		
	and			
	 2. Confirmation from Steam Generator pressure indicators: a. PI-468, PI-469, PI-482 (2/3 less than 500 psig), b. PI-478, PI-479, PI-483 (2/3 less than 500 psig) 			

Attachment 1

CONDITION #7 (Cont'd)

SECONDARY COOLANT ANOMALY

Initiating Condition

Indication Used

Classification

Site Area Emergency

and, if primary to secondary leak rate is occurring:

 Hi radiation on:
 a. R-15 Air Ejector Rad Monitor in alarm mode reading greater than 5 x 10⁴ cpm;

and

4. Leak rate as calculated

Steam line break with greater than 50 gpm primary to secondary leakage and indication of fuel damage

- First out on reactor trip panel:

 a. "A Steam Generator Lo-Lo Pressure SI"
 - b. "B Steam Generator Lo-Lo Pressure SI"

and

- Confirmation from Steam Generator pressure indicators:

 a. PI-468, PI-469, PI-482 (2/3 less than 500 psig), or
 - b. PI-478, PI-479, PI-483, (2/3 less than 500 psig)

and

- 3. Primary to secondary leakage indicated by: a. R-15 Air Ejector Rad Monitor, in alarm4mode reading > 5 x 10° cpm; and b. leak rate calculation > 50 gpm; and
- 4. Indication of fuel damage:
 a. Primary sample > 300 µCi/cc Iodine 131 equivalent; or
 - b. Steam Line Monitor in valid high alarm mode: R-51, > 100 mR/hr; or R-52, > 100 mR/nr.

Attachment 1

CONDITION #7 (Cont'd)

SECONDARY COOLANT ANOMALY

Initiating Condition

Indication Used

Classification

or

c. High Containment Radiation levels indicated by: R48 High Alarm - 200 R/hr; or R49 High Alarm - 200 R/hr;

Transient initiated by loss of feedwater and condensate systems (principal heat removal system) followed by failure of emergency feedwater system for extended period. Core melting possible in several hours. Ultimate failure of containment likely if core melts.

 a. Loss of main condenser which includes all Condensate and Main Feed Pumps; and General Emergency

- b. Loss of all Aux Feedwater; and
- c. No High Head Safety Injection
- or
- 2. a. Successful High Head Safety injection with
 - Loss of main condenser which includes all Condensate and Main Feed Pumps; and
 - (2) Loss of all Aux Feedwater

and

b. Either of the following not established within 30 minutes:

(1) Aux Feedwater; or

(2) Normal RHR Cooling

Classification

Attachment 1

CONDITION #8

RADIOLOGICAL EFFLUENTS

Initiating Condition

Airborne Radiological effluent Technical Specification limits exceeded Note: FSAR Section 14.2.2

Indication Used

Any of the following gaseous effluent Notification of monitors in valid alarm mode reading Unusual Event greater than:

1. 1R-22 (5 x 10^3 cpm) 2. 2R-22 (5 x 10^3 cpm)

Due to release rate of radioactive gaseous effluents exceeding the dose rate limits

per Technical Specification 3.9.B.1.a.

Liquid Radiological effluent Technical Specification limits exceeded Note: FSAR Section 14.2.2 Any of the following valid liquid effluent monitor readings which exceed: (1) R-18 High alarm setpoint and

- isolation valve fails to close.
- (2) R-19 High alarm setpoint (while blowdown is directed to river) and isolation valve fails to close.

Due to release rate of radioactive liquids exceeding values listed per Technical Specification 3.9.A.1.a.

Airborne Radiological effluents greater than ten times Technical Specification instantaneous limits (an instantaneous rate which, if continued for over two hours, would result in about 1 mR at the site boundary under average meteorological conditions)

Any of the following valid gaseous Alert effluent monitor readings:

1R-22 Hi-Hi Alarm (> 5 x 10⁴ cpm)
 2R-22 Hi-Hi Alarm (> 5 x 10⁴ cpm)
 3. 1R-50 Greater Than 1.2 mR/hr
 4. 2R-50 Greater Than 1.2 mR/hr

Due to release rate of gases exceeding
Technical Specification 2.0 R loo has

Technical Specification 3.9.B.1.a by a factor of 10.

Notification of Unusual Event

CONDITION #8 (Cont'd)

RADIOLOGICAL EFFLUENTS

Initiating Condition

Airborne Effluent monitors detect levels corresponding to greater than:

- 50 mR/hr whole body for one-half hour or
- 2. 250 mR/hr for one-half hour for the thyroid, or
- 500 mR/hr whole body for two minutes, or
- 2500 mR/hr to the thyroid for two minutes

at the site boundary for adverse meteorology Attachment 1

Indication Used

- Any of the following valid gaseous effluent monitor readings:
 - (a) 1R-50 Hi Alarm (70 mR/hr)
 - (b) 2R-50 Hi Alarm (70 mR/hr)

or

- Offsite dose projection calculations result in the following dose projections at the site boundary, greater than:
 - (a) 50 mR/hr whole body for 1/2 hour; or
 - (b) 250 mR/hr thyroid for 1/2 hour; or
 - (c) 500 mR/hr whole body for 2 minutes; or
 - (d) 2500 mR/hr thyroid for 2 minutes

or,

 Radiation Survey Teams measure dose rates greater than 50 mR/hr for 1/2 hour or greater than 500 mR/hr for 2 minutes (beta + gamma) at the site boundary;

or

- Radiation Survey Teams measure thyroid dose rates (equivalent I-131 Concentrations), at the site boundary, which are greater than:
 - (a) 250 mR/hr for 1/2 hour, or
 - (b) 2500 mR/hr for 2 minutes.

Classification

Site Area Emergency

CONDITION #8 (Cont'd)

RADIOLOGICAL EFFLUENTS

Initiating Condition

Effluent monitors detect levels corresponding to:

 1R/hr whole body, or
 5R/hr thyroid at the site boundary under actual meteorological conditions Attachment 1

Indication Used

- Any of the following valid gaseous effluent monitor readings in alarm mode, reading greater than:
 - (a) 1R-50 (1000 mR/hr)
 - (b) 2R-50 (1000 mR/hr)

or,

- Offsite dose projection calculations result in the following dose projections at the site boundary, greater than:
 - (a) 1R/hr whole body; or
 (b) 5R/hr thyroid; or

or,

 Radiation Survey Teams measure dose rates greater than 1R/hr whole body

or

 Radiation Survey Teams measure thyroid dose rates (equivalent I-131 Concentrations), at the site boundary, which are greater than 5R/hr.

Radiation levels or airborne contamination which indicate a severe degradation in the control of radioactive materials (e.g., increase of factor of 1000 in direct radiation readings within facility).

 Unexpected radiation levels above 1000 mR/hr

104.4

Alert

- or
- Widespread contamination above 10,000 dpm/100 cm² beta-gamma or 500 dpm/100 cm² alpha activity

Classification

General Emergency

-

Attachment 1

CONDITION #9

Initiating Condition	Indication Used	Classification
Loss of Offsite Power Note: FSAR Section 14.1.9	All of the following indicators: 1. 4.16 KV Bus Voltage (0 Volts) a. Bus 11(21), 4119304 (4172804) b. Bus 12(22), 4119305 (4172805) c. Bus 13(23), 4119306 (4172806) d. Bus 14(24), 4119307 (4172807)	Notification of Unusual Event
	and	
	 D1 & D2 Generators up to Speed and Voltage and Supplying Safe- guard buses: 	
	 a. D1 (D2) Tach (900 rpm) b. D1 (D2) Gen. Volts (4260-4380 Volts) c. Safeguard bus breakers closed: 	
	Bus 15, Breaker 15-2 Bus 26, Breaker 26-2 Bus 16, Breaker 25-6 Bus 25, Breaker 16-7	
Loss of onsite AC Power Capability	Loss of both diesel generators	Notification of Unusual Event
Loss of offsite power and loss of all onsite AC power (See Site Area Emergency for extended loss). Note: FSAR Section 14.1.11	All of the following indicators: 1. 4.16 KV Bus Voltage (0 Volts) a. Bus 11(21), 4119304 (4172804) b. Bus 12(22), 4119305 (4172805) c. Bus 13(23), 4119306 (4172806) d. Bus 14(24), 4119307 (4172807) and	Alert
	2. Loss of both diesel generators	
Loss of offsite power and loss of onsite AC power for more than	All of the following indicators: 1. 4.16 KV Bus Voltage (0 Volts) a. Bus 11(21), 4119304 (4172804)	Site Area Emergency

Attachment 1

CONDITION #9 (Cont'd)

MAJOR ELECTRICAL FAILURES

Initiating Condition

Indication Used

Classification

General Emergency

Alert

c. Bus 13(23), 4119306 (4172806)
d. Bus 14(24), 4119307 (4172807)

and

2. Loss of both diesel generators

and

 Blackout has occurred for more than 15 minutes.

Failure of offsite and onsite power along with total loss of emergency feedwater makeup capability for several hours. This would lead to eventual core melt and likely failure of containment.

 Loss of AC power, (offsite & onsite) indicated by:

- a. 4.16 KV Bus Voltage (0 Volts) (1) Bus 11(21), 4119304 (4172804) (2) Bus 12(22), 4119305 (4172805)
 - (3) Bus 13(23), 4119306 (4172806)
 (4) Bus 14(24), 4119307 (4172807)

and

b. Loss of both diesel generators

and

2. Turbine driven Aux Feedwater pumps inoperable for several hours.

Loss of all onsite DC power (See Site Area Emergency for extended loss). All of the following annunciators received:

 "Safeguard Train A DC Control Power Supply Failure"

and

 "Safeguard Train B DC Control Power Supply Failure"

Attachment 1

CONDITION #9 (Cont'd)

MAJOR ELECTRICAL FAILURES

Initiating Condition

Indication Used

Classification

Site Area Emergency

NOTE :	4 annunciators	numbered:
1.1	47018-0501	
	47018-0502	
	47518-0501	
	47518-0502	

Loss of all vital onsite DC power for more than 15 minutes. All of the following annunciators received:

 "Safeguard Train A DC Control Power Supply Failure"

and

2. "Safeguard Train B DC Control Power Supply Failure"

NOTE :	4	annunciators	numbered:
	470	018-0501	
	470	018-0502	
1	475	518-0501	
	475	518-0502	

and

3. Loss of DC Power has lasted more than 15 minutes.

Attachment 1

CONDITION #10

C

CONTROL ROOM EVACUATIONS

Initiating Condition	Indication Used	Classification
Evacuation of the control room anticipated or re- quired with control of shutdown systems estab- lished from Hot Shutdown Panels and local stations	As required by the Shift Supervisor	Alert
Evacuation of the control room and control of shutdown systems not established from hot shutdown panel and local stations within 15 minutes	As required by the Shift Supervisor	Site Area Emergency

-

Attachment 1

CONDITION #11

FIRES

Initiating Condition	Indication Used	Classification Notification of Unusual Event	
Fire within the plant lasting more than 10 minutes after initial use of fire extinguishing equipment	As reported by Fire Brigade Chief		
Fire potentially affecting safety systems	 Observation that fire could affect safety systems; and 	Alert	
	2. Shift Supervisor's opinion		
Fire comprising the func- tions of safety systems.	 Observation of major fire that defeats safety systems or functions; and 	Site Area Emergency	
	2. Shift Supervisor's opinion		

Attachment 1

CONDITION #12

C

PLANT SHUTDOWN FUNCTIONS

Initiating Condition	Indication Used	<u>Classification</u> Notification of Unusual Event	
Nonfunctional indications or alarms in the Control Room requiring a plant shutdown	 Annunciators: a. "NSSS Annunciator System Power Failure" or b. "BOP Annunciator System Power Failure" and 		
	Failed indication as determined by the Shift Supervisor		
All alarm (annunciators) lost	Annunciators received: 1. "NSSS Annunciator System Power Failure"	Alert	
	and		
	 "BOP Annunciator System Power Failure" 		
Most or all alarms (annun- ciators) lost while unit is not in cold shutdown or during plant transient	Annunciators received: 1. "NSSS Annunciator System Power Failure"	Site Area Emergency	
ouring prono oromorene	or		
	 "BOP Annunciator System Power Failure" 		
	during a transient, as determined by the Shift Supervisor		
Complete loss of any function needed for plant cold shutdown	As determined by Shift Supervisor	Alert	
Complete loss of any function needed for plant hot shutdown	As determined by Shift Supervisor	Site Area Emergency	

.

Attachment 1

CONDITION #12 (Cont'd)		
PLANT SHUTDOWN FUNCTIONS Initiating Condition	Indication Used	Classification
Turbine Failure requiring a reactor/turbine trip	1. High Vibration (7 mils) and	Notification of Unusual Event
	 High-High Vibration (14 mils) as indicated by Control Room recorder and alarms 	
Turbine Failure causing casing penetration	1. High Vibration (7 mils)	Alert
	and	
	 High-High Vibration (14 mils) as indicated by Control Room recorder and alarms 	
	and	
	3. As determined by Visual Inspection	
Failure of the reactor protection system to initiate and complete a trip which brings the	 Any Reactor Trip Setpoint and redundancy requiring a reactor trip has been exceeded 	Alert
reactor subcritical	and	
	2. Intermediate range detector output not decaying	
Transient requiring operation of shutdown systems with failure to	 Failure to bring reactor subcriti- cal with control rods; and 	Site Area Emergency
scram (continued power generation but no core	2. No indication of core damage; and	
damage immediately evi- dent).	 Shift Supervisor's opinion that a transient is in progress 	

Attachment 1

CONDITION #12 (Cont'd)

PLANT SHUTDOWN FUNCTIONS

Initiating Condition

Indication Used

Classification

Transient requiring operation of shutdown systems with failure to scram which results in core damage or additional failure of core cooling and makeup systems (which could lead to core melt) Reactor remains critical after trip;

and

- Indication of overpressurization of RCS because of inability to remove heat, as indicated by:
 - (a) RCS pressure greater than safety valve setpoint (2485 psig); or
 - (b) Rapidly increasing containment pressure and temperature

General Emergency

÷.,

Attachment 1

CONDITION #13

FUEL HANDLING ACCIDENTS			
Initiating Condition	Indication Used	Classification	
Fuel damage accident with release of radio- activity to contain- ment Note: FSAR Section 14.2.1	 Any of the following containment rad monitors in valid alarm mode and reading greater than: (a) R2 - 350 mR/hr; or (b) R7 - 350 mR/hr or The containment vent monitor in valid alarm mode, reading greater than: (a) R11 - 10⁶ cpm; or (b) R12 - 10⁵ cpm 		
Fuel damage accident with release of radioactivity to the fuel handling building Note: FSAR Section 14.2.1	 3. Shift Supervisor's opinion 1. Any of the following valid radiation monitor readings: (a) R-22 HiHi Alarm, > 5 x 10⁴ cpm; (b) R-50, > 1.2 mR/hr and 2. Spent Fuel Pool Area Monitor R-5 in valid alarm mode reading > 350 mR/hr and 	Alert	
	3. Shift Supervisor's opinion		

Attachment 1

CONDITION #13 (Cont'd)

FUEL HANDLING ACCIDENTS

Initiating Condition

Major damage to spent fuel in containment or fuel handling building (e.g., large object damages fuel or water loss below fuel level)

Indication Used

Classification

Site Area

Emergency

and

(b) Shift Supervisor's opinion

or

- For fuel damage in the Spent Fuel Pool:
 - (a) Valid Radiation Monitor readings on:
 (1) R50 Hi Alarm, > 70 mR/hr; or
 - (2) R5, in alarm mode reading
 - > 1R/hr

and

(b) Shift Supervisor's opinion

Attachment 1

1. RCP Trip (over current 86

CONDITION #14

COOLANT PUMP

Initiating Condition

Indication Used

lock-out);

Classification

Alert

Coolant pump seizure leading to fuel failure Note: FSAR Section 14.1.8

and

 Primary sample analysis indicating fuel failure (> 300 µCi/cc iodine 131 equivalent)

Attachment 1

CONDITION #15

SERIOUS OR FATAL INJURY

Initiating Condition

Indication Used

Classification

Transportation of a seriously or fatally injured (may or may not involve contamination) individual from site to hospital for treatment As determined by the Shift Supervisor

NOTE: Serious injury is considered to be one that will require admission for treatment or observation for an extended period of time (greater than 48 hours) Notification of Unusual Event

a toma and

Attachment 1

CONDITION #16

SECURITY THREATS

Initiating Condition	Indication Used	Classification
Security threat or attempted sabotage	Per security plan	Notification of Unusual Event
Ongoing security compromise	Per security plan	Alert
Imminent loss of physical control of plant	Per security plan	Site Area Emergency
Loss of physical control of plant	Per security plan	General Emergency

Attachment 1

CONDITION #17

C

HAZARDS TO PLANT OPERATIONS			
Initiating Condition	Indication Used	Classification	
Aircraft crash onsite or unusual aircraft activity over facility	 Visual observation by plant personnel and/or plant security personnel; and 	Notification of Unusual Event	
	2. Reported to the Shift Supervisor	1	
Aircraft crash in the protected area	Visual observation by plant personnel and/or plant security personnel	Alert	
Aircraft crash within protected area and affect- ing vital structures by impact or fires with plant not in cold shutdown	Visual observation by plant personnel and/or plant security personnel	Site Area Emergency	
Near or onsite explosion	 Visual observation by plant personnel and/or plant security personnel; <u>and</u> Personnel to the Shift Supervisor 	Notification of Unusual Event	
	2. Reported to the Shift Supervisor		
Known explosion damage to facility affecting plant operation	Visual observation by plant personnel	Alert	
Severe damage to engi- neered safety system equipment from explo- sions with plant not in cold shutdown	Visual observation by plant personnel	Site Area Emergency	
Near or onsite toxic or flammable gas release	Gaseous hazards being experienced or projected, <u>onsite (out of plant)</u> , as detected by portable instrumentation, which exists in concentrations greater than:	Notification of Unusual Event	

-

Attachment 1

CONDITION #17 (Cont'd)	Attachment 1		-
HAZARDS TO PLANT OPERATIONS			
Initiating Condition	Indication Used	Classification	
	 80 ppm hydrazine; or 25 ppm chlorine; or 500 ppm ammonia; or explosive limits as detected by explosive meter, 		
	and, reported to the Shift Supervisor		
Entry into the plant environs of toxic or flammable gases	Gaseous hazards being experienced or projected, within the plant, as detected by portable instru- mentation, which exists in concen- trations greater than:	Alert	
	 80 ppm hydrazine; or 25 ppm chlorine; or 500 ppm ammonia; or explosive limits as detected by explosive meter, 		-
	and, reported to the Shift Supervisor		0
Entry of toxic or flammable gases into vital areas with plant not in cold shutdown	Gaseous hazards being experienced or projected within vital areas of the plant, as detected by portable instru- mentation, which exists in concentration greater than:	Site Area Emerge	ency
	 80 ppm hydrazine; or 25 ppm chlorine; or 500 ppm ammonia; or explosive limits as detected by explosive meter, 		
	and, reported to the Shift Supervisor		
Missile impacts from whatever source on facility	Visual observation by plant personnel and/or plant security personnel	Alert	

*

Visual observation by plant personnel Site Area Emergency

Attachment 1

CONDITION #17 (Cont'd)

HAZARDS TO PLANT OPERATIONS

Initiating Condition

Indication Used

Classification

Severe damage to engineered safety system from missiles with plant not in cold shutdown

.

Attachment 1

CONDITION #18

	1000		100	1000.00		
NΔ	TI	IRΔ		1.1	/EN	TS
110		- INCO	1.1.1	1.1	1.1.1	10

Indication Used	Classification	
Annunciator "Seismic Event" received on the seismograph	Notification of Unusual Event	
Annunciator "Operational Earthquake" received on the seismograph	Alert	
Annunciator "Design Basis Earthquake" received on the seismograph	Site Area Emergency	
Visual observation by plant personnel and/or plant security <u>and</u> reported to the Shift Supervisor.	Notification of Unusual Event	
Visual observation by plant personnel and/or plant security <u>and</u> reported to the Shift Supervisor.	Alert	
686' elevation	Notification of Unusual Event	
oproaching 692' elevation - requires both units to be shut down		
698' elevation - highest level transformers will function	Site Area Emergency	
ow water levels being 672.5' elevation - (At 672.5' xperienced or projected elevation, both 11 and 21 cooling eyond usual levels water pumps trip)		
	Annunciator "Seismic Event" received on the seismograph Annunciator "Operational Earthquake" received on the seismograph Annunciator "Design Basis Earthquake" received on the seismograph Visual observation by plant personnel and/or plant security and reported to the Shift Supervisor. Visual observation by plant personnel and/or plant security and reported to the Shift Supervisor. 686' elevation 692' elevation - requires both units to be shut down 698' elevation - highest level transformers will function 672.5' elevation - (At 672.5' elevation, both 11 and 21_cooling	

Attachment 1

CONDITION #18 (Cont'd)

NATURAL EVENTS

Initiating Condition Indication Used		Classification	
Low water levels being experienced or projected to be near design levels	Approximately 669.5' elevation	Alert	
Low water levels being experienced or projected to be greater than design levels or failure of vital equipment with plant <u>not</u> in cold shutdown.	 Approximately 666.5' elevation corresponding to loss of set of miter gates or loss of one spill- way gate or Major vital equipment failure at low water level 	Site Area Emergency	
Sustained winds being experienced or projected near design levels Sustained wind speed indicated by met tower in excess of 90 mph		Alert	
Sustained winds being in excess of design levels being experienced or pro- jected with plant <u>not</u> in cold shutdown	ess of design levels met tower, in excess of 100 mph ng experienced or pro- ted with plant not in		
Any major internal or external events (e.g., fires, earthquake, sub- stantially beyond design levels) which could or has caused massive damage to plant systems re- sulting or potential for resulting in large releases to the offsite environment in excess of the EPA Protective Action Guides	As determined by the Shift Supervisor and/or Emergency Director	General Emergency	

-

Attachment 1

CONDITION #19

OTHER

12.20

: .

3

Initiating Conditions	Indication Used	Classification Notification of Unusual Event Notification of Unusual Event	
Conditions that warrant increased awareness on the part of a plant operating staff or state and/or local offsite authorities	Duty Engineer and Shift Supervisor concurrence		
Conditions that require plant shutdown under Technical Specification requirements or involve other than normal con- trolled shutdown	Duty Engineer and Shift Supervisor concurrence		
Conditions that warrant activation of Technical Support Center and near- site Emergency Operating Facility	Duty Engineer and Shift Supervisor concurrence	Alert	
Other plant conditions that warrant activation of emergency operating centers and monitoring teams or a precautionary notification to the public near the site	Shift Supervisor opinion	Site Area Emergency	
Other plant conditions exist, from whatever source, that make release of large amounts of radio- activity in a short time period possible, e.g., any	Shift Supervisor's opinion	General Emergency	

	PAGE 1 OF 7	
PRAIRIE ISLAND NUCLEAR	EMERGENCY PLAN IMPLEMENTING	
GENERATING PLANT NORTHERN STATES POWER COMPANY	 Number: F3-3 Rev: 4	
0 0 .	History Copy Retention Time: Lifetime	
Reviewed By: A. Schuelbe Supt. Rad Protection Approved By:	TITLE:	
Plant Manager	NOTIFICATION OF UNUSUAL EVENT	
OC Date: <u>9-25-84</u>		
1.0 PURPOSE		

The purpose of this instruction is to delineate the responsibilities of various emergency organization personnel and onsite organizations required to respond to a Notification of Unusual Event.

- 2.0 SUMMARY
 - 2.1 Notification of Unusual Event
 - A. Definition

Unusual Events are events that are in progress or have occured which indicate a potential degradation of the level of safety of the plant.

No release of radioactive material requiring offsite response or monitoring are expected unless further degradation of safety systems occurs.

B. Purpose of the Notification of Unusual Event Class

The purpose of the Notification of Unusual Event Emergency classification is to:

- Have the operating staff come to a state of readiness from the standpoint of emergency response in the event the handling of the initiating condition needs to be escalated to a more severe action level class;
- (2) Provide for systematic handling of Unusual Events information.
- C. Plant Actions & Responsibilities:
 - Promptly inform State and/or local offsite authorities of nature of unusual condition as soon as discovered.

- (2) Augment on-shift resources (if needed).
- (3) Assess and respond to Unusual Event.
- (4) Close out with verbal summary to offsite authorities.

or

- (5) Escalate to a more severe class.
- D. State and/or local offsite authority actions:
 - Provide fire or security assistance if required.
 - (2) Standby until verbal closeout.

or

(3) Escalate to a more severe class.

3.0 PRECAUTIONS

- During the Notification of Unusual Event class of emergency, the Emergency Director position will not be activated. The Shift Supervisor from the unaffected unit shall assume overall authority for direction and control.
- (2) Plant personnel shall monitor plant conditions throughout the duration of the Unusual Event for indication that the level of safety of the plant has not been degraded, and shall be prepared to escalate to a more severe class of emergency should conditions warrant it.
- (3) All personnel shall stay clear of any areas as announced over the public address system.
- (4) All personnel shall refrain from using the public address system or telephone system during any emergency situation.

4.0 APPLICABILITY

This instruction shall apply to all NSP plant personnel.

5.0 PROCEDURE

5.1 Organization Control

- 5.1.1 Overall Responsibility Shift Supervisor of <u>unaffected</u> unit.
- 5.1.2 In-Charge, Control Room Shift Supervisor of affected unit.
- 5.1.3 Assistance, Control Room Control Room Operators Shift Technical Advisor TSC - Shift Emergency Communicator Plant - Shift Radiation Protecttion Specialist.

5.2 Responsibilities

5.2.1 Shift Supervisors

A. Shift Supervisor of affected unit:

 The Shift Supervisor of the affected unit shall proceed to the Control Room (if not already there).

> NOTE: He shall remain in the Control Room at all times during accident conditions until properly relieved.

- (2) If needed, ensure that applicable Emergency Operating Procedures are implemented to respond to the Notification of Unusual Event condition with the objective of returning the plant to a normal, safe condition (or cold shutdown, if determined to be necessary).
- (3) Monitor plant conditions to determine when the threat to plant safety, if any, has passed. Be prepared to escalate to a more severe emergency classification, if required.
- (4) Coordinate, with the Shift Supervisor of the unaffected unit and the Shift Emergency Communicator, anytime the Notification of Unusual Event class is escalated to more severe emergency classification or terminated, or any plant operations which may impact on radioactive releases.
- B. Shift Supervisor of unaffected unit:
 - Contact the STA and SEC (if not already done so), and have them report to the Control Room immediately.

- (2) Assist the SEC in completing the Initial Emergency Notification Report, Figure 1 (PINGP #577), F3-5.
- (3) Designate the SEC to complete the notification of state, local and NSP personnel in accordance with F3-5, "Emergency Notifications".

NOTE: State and local authorities shall be notified within 15 minutes of the declaration of the emergency class.

(4) Ensure that the NRC has been notified.

NOTE: Notification of the NRC required within 1 hour.

- (5) Determine appropriate plant staff support requirements, if needed, and make applicable notifications and requests for support. Coordinate the notifications of plant support with the SEC.
- (6) If local support services are required (e.g., fire department, hospital assistance, ambulance, etc.) ensure the required notifications are made. This may be coordinated with the SEC.
- (7) Assist the Shift Supervisor of the affected unit as required in 5.2.1 (A).
- (8) Designate the SEC to complete the notifications of state, local, and NSP personnel whenever the emergency is escalated, or when the Notification of Unusual Event Classification is terminated.

5.2.2 Control Room Personnel

- (1) Assist the Shift Supervisor as requested.
- (2) Utilize applicable Operations Manual procedures to respond to the Notification of Unusual Event emergency classification, as appropriate, with the object of returning the plant to a normal safe status (or cold shutdown, if determined to be necessary).
- (3) Announce the location and nature of the emergency over the public address system, if applicable. Direct all non-essential personnel to remain clear of the affected area (i^f applicable) and to refrain from using the public address system.
- (4) Continuously monitor the Control Room instrumentation, radiation monitors, or any other developments which would be indicative of further system degradation. Inform the nift Supervisor immediately of any changes in the plant status.

5.2.3 Shift Technical Advisor

- Report to the Control Room immediately upon notification of the Unusual Event.
- (2) Assist the Shift Supervisor in assessing the emergency condition and safety related status of the plant.

5.2.4 Emergency Director

 The Emergency Director position will not be activated during the Notification of Unusual Event. The Shift Supervisor of the <u>unaffected</u> unit has the overall responsibility during this classification of emergency.

5.2.5 Shift Emergency Communicator

- Report to the Control Room immediately upon notification.
- (2) Complete the "Initial Emergency Notification Report", Figure 1 (PINGP #577), F3-5, with assistance from the Shift Supervisor.

(3) Complete the required notification of state and local authorities, and NSP personnel in accordance with F3-5, "Emergency Notifications".

> NOTE: State and local authorities shall be notified within 15 minutes of the declaration of the emergency classification.

- (4) Assist the Shift Supervisor in the coordination of other required communication contacts (e.g., medical support, fire support, etc.). See the "Emergency Preparedness Telephone Directory" for local support services phone numbers.
- (5) Notify appropriate plant staff support personnel to augment the onsite staff as deemed necessary by the Shift Supervisors.
- (6) Maintain communications through-out the emergency classification as required by F3-5, "Emergency Notifications".

NOTE: Be prepared to notify applicable authorities if conditions escalate to a more severe emergency class.

- (7) When the Notification of Unusual Event class has been terminated, close-out the emergency classification, by notifying the state, local, and NSP personnel in accordance with F3-5, "Emergency Notifications".
- 5.2.6 Other Operations Personnel
 - Assistant Plant Equipment Operators and Plant Attendants should continue with assigned duties or report to the Control Room if requested.
 - (2) Relief Shift Operators onsite, should continue with assigned operations unless their assistance is requested.
 - (3) The Superintendent, Operations, if on site, should report to the Control Room and provide assistance where necessary.

F3-3 Rev. 4 Page 7

5.2.7 Radiation Protection Group

- The Shift Radiation Protection Specialist shall provide assistance (e.g., sampling, chemistry, radio-chemistry, surveys, etc.) as requested by the Shift Supervisor.
- (2) Other Radiation Protection Group personnel should continue with normal duties unless directed to do otherwise.

5.2.8 Plant Security Force

- Continue with normal duties unless directed to do otherwise.
- (2) During off-normal work hours, designate a member of the Security Force to control the telephone switchboard in the TSC, when requested by the Shift Emergency Communicator (SEC).

5.2.9 All Other Personnel On Site

- Continue with normal duties unless directed to do otherwise.
- (2) Stay clear of areas as announced over the public address system.

	PAG	E 1 OF 33	
PRAIRIE ISLAND NUCLEAR	EMERGENCY PLAN IMPLEMENTING PROCEDURES		
GENERATING PLANT NORTHERN STATES POWER COMPANY	Number: F3-4	Rev: 10	
	 Retention Time:	History Copy Lifetime	
Reviewed By: A. Schuelke Supt. Rad Protection	TITLE:		
Approved By: Plant Manager	RESPONSIBILITIES DURING AN ALERT, SITE AREA OR GENERAL EMERGENCY		
OC Date: 9-25-84			

1.0 PURPOSE

The purpose of this instruction is to delineate the responsibilities of various emergency organization personnel and onsite organizations required to respond to an Alert, a Site Area Emergency or a General Emergency.

2.0 SUMMARY

A graded scale of response is provided for the different classes of emergencies, each requiring a specific response by emergency organization personnel for the protection of the public health and safety.

2.1 Alert

A. Definition

The Alert Conditions are events which are in progress or have occurred which involve actual or potential substantial degradation of the level of safety of the plant.

Some releases of radioactive material to offsite areas are probable. Hence there is some necessity for emergency planning and response by offsite agencies. Any radioactive release will be limited to a small fraction of the EPA Protective Action Guideline exposure levels.

B. Purpose of Alert Class

The purpose of the Alert Emergency classification is to (1) assure that emergency personnel are readily available to respond if the situation becomes more serious or to perform confirmatory radiation monitoring, if required; (2) provide offsite authorities current status information.

C. Plant Actions and Responsibilities:

- Promptly inform State and/or local authorities of Alert status and reason for Alert as soon as discovered.
- Augment resources by activating onsite Technical Support Center, onsite Operational Support Center and Near-Site Emergency Operations Facility (EOF).
- 3. Assess and respond to the Alert condition.
- Dispatch onsite or offsite survey teams and associated communications (if needed).
- Provide periodic plant status updates to offsite authorities.
- Provide periodic meteorological assessments to offsite authorities and, if any releases are occurring, dose estimates for actual releases.
- 7. Close out by verbal summary to offsite authorities.

or

- 8. Escalate to a more severe class.
- D. State and/or Local Offsite Authority Actions:
 - 1. Provide fire or security assistance, if required.
 - 2. Augment resources by activating Emergency Operating Centers and EBS to standby status.
 - Alert to standby status key emergency personnel including monitoring teams and associated communications.
 - 4. Provide confirmatory offsite radiation monitoring and ingestion pathway dose projections if actual releases substantially exceed technical specification limits.
 - 5. Maintain alert status until verbal closeout.

or

6. Escalate to a more severe class.

2.2 Site Area Emergency

A. Definition

The Site Area Emergency describes events which are in progress or have occurred which involve actual or likely major failures of plant functions needed for protection of the public.

Significant offsite releases are likely to occur or are occurring but where a core melt situation is not expected although severe fuel damage may have occurred.

Any radioactive releases are not expected to exceed the EPA Protective Action Guideline exposure levels except near the site boundary.

B. Purpose of Site Area Emergency Class

The purpose of the Site Area Emergency classification is to (1) assure that response centers are manned; (2) assure that monitoring teams are dispatched; (3) assure that personnel required for evacuation of Near-Site areas are at duty stations if the situation becomes more serious; (4) provide current information for and consultation with offsite authorities, and (5) provide updates for the public through offsite authorities.

- C. Plant Actions and Responsibilities:
 - Promptly inform State and/or local offsite authorities of Site Area Emergency status and reason for emergency as soon as discovered.
 - Augment resources by activating onsite Technical Support Center, onsite Operational Support Center and the Near-Site Emergency Operations Facility (EOF).
 - 3. Assess and respond to the Site Area Emergency.
 - 4. If radiological or environmental conditions permit, evacuate onsite, nonessential personnel.
 - 5. Dispatch onsite and offsite survey teams and associated communications (if needed).
 - 6. Provide a dedicated individual for plant status updates to offsite authorities.
 - Make senior technical and management staff onsite available for consultation with NRC and State on a periodic basis.
 - Provide meteorological and dose estimates to offsite authorities for actual releases via a dedicated individual.

- Provide release and dose projections based on available plant condition information and foreseeable contingencies.
- Close out or recommend reduction in emergency class by contacting offsite authorities.

or

- 11. Escalate to General Emergency class.
- D. State and/or Local Offsite Authority Action:
 - 1. Provide any assistance requested.
 - 2. If sheltering near the site is desirable, activate the Public Notification System within at least 2 miles of the plant.
 - Provide public within at least 10 miles, periodic updates on emergency status.
 - 4. Augment resources by activating Emergency Operating Centers and EBS to standby status.
 - 5. Dispatch key emergency personnel including monitoring teams and associated communications.
 - Alert to standby status other emergency personnel (e.g., those needed for evacuation) and dispatch personnel to Near-Site duty stations.
 - Provide offsite monitoring results to licensee and others and jointly assess them.
 - Continuously assess information from licensee and offsite monitoring with regard to changes to protective actions already initiated for public and mobilizing evacuation resources.
 - 9. Recommend placing milk animals within 2 miles on stored feed and assess need to extend distance.
 - 10. Provide press briefings, perhaps with licensee.
 - Maintain Site Area Emergency status until closeout or reduction of emergency class.

12. Escalate to General Emergency class.

2.3 General Emergency

A. Definition

The General Emergency describes events in progress or which have occurred which involve actual or imminent substantial core degradation or melting with the potential for loss of containment integrity. Radioactive releases can be reasonably expected to exceed the EPA Protective Action Guideline exposure levels offsite for more than the immediate site area, hence, Protective Actions may have to be taken for protection of the general public.

B. Purpose of General Emergency Class

The purpose of the General Emergency classification is to (1) initiate predetermined protective actions for the public; (2) provide continuous assessment of information from licensee and offsite measurements; (3) initiate additional measures as indicated by actual or potential releases; (4) provide current information for the public and consultation with offsite authorities, and (5) provide updates for the public through offsite authorities.

- C. Plant Actions and Responsibilities
 - Promptly inform state and local offsite authorities of General Emergency status and reason for emergency as soon as discovered.
 - Augment resources by activating onsite Technical Support Center, onsite Operational Support Center and Near-Site Emergency Operations Facility (EOF).
 - 3. Assess and respond to General Emergency.
 - 4. If radiological or environmental conditions permit, evacuate onsite, nonessential personnel.
 - 5. Dispatch onsite and offsite survey teams and associated communications.
 - 6. Provide a dedicated individual for plant status updates to offsite authorities.
 - Make senior technical and management staff onsite available for consultation with NRC and State on a periodic basis.

a,

- 8. Provide meteorological and dose estimates to offsite authorities for actual releases via a dedicated individual.
- Provide release and dose projections based on available plant condition information and foreseeable contingencies.
- Close out or recommend reduction of emergency class by briefing of offsite authorities at EOC by phone.
- D. State and/or Local Offsite Authority Actions
 - 1. Provide any assistance requested.
 - Activate immediate public notification of emergency status and provide public periodic updates.
 - Recommend sheltering for 2 mile radius and 5 miles downwind and assess need to extend discances. Consider advisability of evacuation (projected time available vs estimated evacuation times).
 - Augment resources by activating Near-Site EOC and any other primary response centers.
 - 5. Dispatch key emergency personnel including monitoring teams and associated communications.
 - Dispatch other emergency personnel to duty stations within 5 mile radius and alert all others to standby status.
 - 7. Provide offsite monitoring results to licensee and others and jointly assess these.
 - Continuously assess information from licensee and offsite monitoring with regard to changes to protective actions already initiated for public and mobilizing evacuation resources.
 - 9. Recommend placing milk animals within 10 miles on stored feed and assess need to extend distance.
 - 10. Provide press briefings, perhaps with licensee.
 - Maintain General Emergency status until closeout or reduction of emergency class.

3.0 PRECAUTIONS

- All personnel shall stay clear of any areas as announced over the public address system.
- (2) All personnel shall refrain from using the public address system or telephone system during an emergency.
- (3) When the evacuation alarm is sounded, listen for instructions over the public address system before evacuating.
- (4) Anyone working in a contaminated area when the evacuation alarm sounds should remove as much protective clothing as time permits, especially gloves, booties or rubbers. If wearing a double suit, removal of outside clothing would only be necessary. Proceed to the designated assembly area. If unable to remove all protective clothing, inform personnel in charge at the assembly area of your condition.

NOTE: When the evacuation alarm sounds during a DRILL, remove ALL protective clothing prior to evacuating.

- (5) When exiting the Protected Area via the Guard House, proceed through the portal monitor quickly. Step through without stopping. All I.D. cards (badges) shall be collected and checked out by the Security Force, so an early printout of all personnel within the Protected Area can be obtained.
- (6) Everyone shall remain at assembly area for monitoring and accountability checks until released by the Emergency Director or directed for reassignment for duty within the plant. Follow instructions from the Assembly Point Coordinator. When departing the site property, obey all instructions from traffic control personnel.
- (7) All entries into the Auxiliary Building should be controlled through the OSC. Aux entries made for purposes of equipment operation, search and rescue, damage control, etc., should be led by a Radiation Protection Specialist, or other qualified individual.

4.0 APPLICABILITY

This instruction shall apply to all plant personnel.

5.0 ORGANIZATIONAL CONTROL

- 5.1 Overall Responsibility Emergency Director
- 5.2 In-Charge, Control Room Shift Supervisor

Technical Support Center - TSC Coordinator

Operational Support Center - OSC Coordinator

Assembly Point - Assembly Point Coordinator

- 5.3 Assistance, Control Room Control Room Operators
 - Shift Technical Advisor
 - Supt Operations

TSC - Operations Committee

- Shift Emergency Communicator
- Radiological Emergency Coordinator
- Engineering support as needed (i.e., systems experts)

OSC - Extra Operators

- Rad Survey Teams
- Maintenance Supervisors
- I & C Supv & Coordinators
- Chief Station Electrician and Alternates
- Additional Support as needed

6.0 RESPONSIBILITIES

6.1 Shift Supervisor of the affected unit.

(1) Proceed to the Control Room (if not already there)

NOTE: The Shift Supervisor of the affected unit shall remain in the Control Room at all times during accident conditions until properly relieved.

(2) Implement the appropriate Emergency Operating Procedures, as needed, and respond to the emergency condition with the objective of returning the plant to a normal safe condition (or cold shutdown, if determined to be necessary).

- (3) Monitor plant conditions to determine when the threat to plant safety has passed. Be prepared to escalate to a more severe emergency class, if required.
- (4) Coordinate, with the Emergency Director, all plant operations which may impact on radioactivity releases.
- 6.2 Shift Supervisor of the unaffected unit:
 - (1) Assume the position as Emergency Director.
 - (2) Start the duties and responsibilities assigned to the Emergency Director as specified in Section 6.3. Use Attachment A, Emergency Director's Checklist (PINGP #571).
 - (3) When the designated Emergency Director arrives onsite, update him on the current plant status and formally transfer the Emergency Director responsibilities over to that individual. Ensure that the Shift Supervisor of the affected unit is aware that a turnover of Emergency Director responsibilities has occurred.
 - (4) Assist the Shift Supervisor of the affected unit, as required in section 6.1.
- 6.3 Emergency Director
 - Assume the role as Emergency Director. Use Attachment A, Emergency Director's Checklist (PINGP #571).
 - (2) Determine the plant status. Report to the Control Room and become familiarized with the situation and sequence of events preceding and propagating the Emergency Condition.
 - (3) Announce, or ensure that the following message is announced over the public address system:

ATTENTION ALL PLANT PERSONNEL:

A (N) (pick correct class):

ALERT, or SITE AREA EMERGENCY, or GENERAL EMERGENCY

HAS BEEN DECLARED.

ALL MEMBERS OF THE ONSITE EMERGENCY ORGANIZATION REPORT TO YOUR EMERGENCY DUTY STATIONS. ALL OTHER PERSONNEL STANDBY FOR FURTHER INSTRUCTIONS.

Repeat announcement.

IBM

,

.

NOTE: A plant evacuation may be initiated during an Alert, and shall occur during a Site Area, or General Emergency, however, the Emergency Director must consider special conditions, (e.g., high winds or tornado) where an evacuation is not feasible or when the onsite assembly point is not habitable. See procedure F3-9, "Emergency Evacuation", for specific evacuation criteria.

- (4) Contact the STA and SEC (if not already done so), and have them report to the Control Room immediately.
- (5) Assist the SEC in completing the Notification Report Form, Figure 1, F3-5 (PINGP #577).
- (6) Designate the SEC to complete the notification of state, local, and NSP personnel, in accordance with F3-5, "Emergency Notifications".

NOTE: State and local authorities shall be notified within 15 minutes of the declaration of the emergency class.

- (7) Direct the SEC to activate the onsite emergency organization, in accordance with F3-5, "Emergency Notifications", and to notify any other appropriate plant personnel, as deemed necessary.
- (8) Notify any other offsite support agencies required to provide assistance to respond to the emergency condition, e.g., local support services, such as fire fighting, ambulance, hospital, etc. See "Emergency Preparedness Telephone Directory" local support services phone numbers.

NOTE: These contacts should be coordinated with the SEC and the Control Room to ensure that the contacts required are made in a timely manner.

- (9) Direct the Shift RPS to
 - (a) perform the appropriate sampling and analysis as necessary, e.g., primary system, containment air, steam generator liquid, shield building stack, etc., and/or
 - (b) perform offsite dose calculations, if the high range effluent stack monitors (R-50) are in valid alarm mode.
- (10) Direct the RPS and/or operator to conduct onsite and in-plant radiation surveys, as necessary.
- (11) If the first notification of an emergency is a General Emergency, call the County Sheriff and make the initial Protective Action recommendation:
 - (a) Recommend activation of the Public Alert and Notification System, and
 - (b) Recommend sheltering of the public within a two mile radius of the plant and 5 miles downwind. (See F3-8, "Protective Action Recommendations).
- (12) Ensure that the NRC has been notified and designate an individual to maintain communications with the NRC via the ENS phone, as necessary.

NOTE: Notification of the NRC via the ENS required within 1 hour.

- (13) During plant evacuations, direct the evacuation of all non-essential personnel from the plant site to the designated assembly point (per F3-9).
 - (a) Normally, the Construction Office Building should be the designated assembly point. However, the Screenhouse may be used if conditions make the Construction Office Building uninhabitable.
 - (b) Direct the Security Force to warn all personnel within the Owner Controlled Area and outside the Protected Area.
- (14) Monitor the habitability of the Auxiliary Building and order an evacuation of the Auxiliary Building Operators to the OSC if:

(a) General area radiation levels exceed 100 mR/hr; or

- (b) Based upon recommendations from the Radiation Protection Group.
- (15) Account for all personnel (Plant personnel, visitors and construction personnel) onsite, within 30 minutes following the evacuation. (This responsibility may be delegated). See Procedure F3-9.
- (16) Determine if the assembly point and guardhouse are safe and watch for changing conditions which would require further evacuation.
- (17) Complete a turnover of Emergency Director responsibilities from the Shift Supervisor of the <u>unaffected</u> unit to the designated Emergency Director when that individual arrives onsite. Ensure that both Shift Supervisors are aware of the turnover of the Emergency Director responsibilities. The Shift Supervisor of the unaffected unit shall continue with the Emergency Responsibilities until a formal turnover occurs.
- (18) During plant evacuations, direct monitoring of all personnel for contamination (adequate instrumentation is available at both assembly points for this task).
- (19) Direct the activation of the Technical Support Center and Operational Support Center per procedure F3-6, and F3-7, and ensure that coordinators are assigned to the emergency response centers.
- (20) Update TSC personnel on plant status.
- (21) Verify that communications have been established between all the onsite emergency operating centers (Control Room, OSC, and TSC). Assign the TSC Coordinator responsibility to handle the Emergency Director phones.
- (22) If necessary, based on plant conditions, initiate monitoring of onsite and offsite areas. This responsibility may be delegated to the Radiation Protection Group.
- (23) If offsite releases are occurring or may occur, direct the calculation of projected offsite dose rates as per F3-13. This responsibility may be delegated to the Radiological Emergency Coordinator.
- (24) Make appropriate protective action recommendations to the offsite authorities. (See F3-8, "Recommendations for Offsite Protection Actions"). The authority to approve protective action recommendations shall not be delegated.

(25) Ensure that continuous updates (approximately every halfhour) are provided to the State EOC's (Wisc and Minn) which were activated by the initial notification. (See F3-5).

> NOTE: When the EOF is activated, communications with the offsite authorities will be transferred to the EOF.

- (26) Periodically, request TSC personnel to present an update to all TSC personnel on status of activities in their specific area.
- (27) Authorize overexposures in accordance with F3-12, "Emergency Exposure Control".
- (28) Direct operation of the assembly point via the Assembly Point Coordinator and arrange for any assistance required at the assembly area.
- (29) If conditions indicate that further system degradation has occurred, escalate to a more severe emergency classification and direct the notification of all offsite agencies and personnel of such action, per F3-5. Announce, or have announced, the reclassification and escalation to a higher emergency classification, over the public address system.
- (30) As conditions permit, terminate the emergency condition or downgrade the emergency classification to a lower classification. Direct the notification of all offsite agencies and personnel, per F3-5. Announce or have announced the downgrading or termination of the emergency condition over the public address system.
- (31) When the Near-Site EOF has been activated, the Emergency Manager will inform the Emergency Director. The Emergency Director will then transfer control of all offsite activities over to the Emergency Manager. Ensure that all TSC personnel are aware that a turnover of responsibilities to the EOF has occurred.
- (32) Coordinate with all group Superintendents to insure that plant manpower requirements for all subsequent workshifts are determined and that the necessary personnel are scheduled.
- (33) When the emergency condition is terminated, ensure that all offsite and onsite personnel are notified of the termination of the emergency condition and initiation of recovery operations.

6.4 Operations Group

- Utilize applicable operations manual procedures to respond to the Emergency Condition as appropriate, with the objective of returning the plant to a normal safe status (or cold shutdown, if necessary).
- (2) Assist the Shift Supervisor as requested.
- (3) Announce the location and nature of the Emergency over the public address system. When an evacuation is declared, sound the evacuation alarm and direct all non-essential personnel to evacuate to the designated assembly point. Direct all personnel to remain clear of the affected area (if applicable). See F3-9, "Emergency Evacuation."
- (4) Assist in the activation of onsite emergency centers and organization.
- (5) Continuously monitor the Control Room instrumentation, radiation monitors, or any other developments which could be indicative of further system degradation. Inform the Shift Supervisor immediately of any changes in plant status.
- (6) Operators (Aux & BOP) should report to their duty station when the emergency is declared.
 - (a) Aux operators shall ensure that they have a low and high range dosimeter and a dose rate indicating device for all further required operations in the Auxiliary Building.
 - (b) Aux & BOP operators should give consideration to terminating all non-essential plant operations. (e.g., shutdown evaporators).
 - (c) When a plant evacuation is declared, the Aux & BOP operators should immediately establish a communication channel with the OSC.
 - (d) If the Auxiliary Building general rad levels exceed 100mR/hr or upon recommendations from the Emergency Director or Radiation Protection Group, the Aux Operators shall evacuate to the OSC. For exposure control purposes, all further Auxiliary Building entries shall be controlled thru the OSC.
- (7) Perform the necessary onsite and in-plant radiation surveys as requested by the Shift Supervisor.

- (8) Relief Shift and Training Operators should proceed to the Operational Support Center for further instructions to support operations in the Control Room.
- (9) The Superintendent, Operations, if on site, should report to the Control Room and provide assistance where necessary.
- 6.5 Shift Technical Advisor
 - Report to the Control Room immediately upon notification of the Emergency Condition.
 - (2) Assist the Shift Supervisor and Emergency Director in assessing the emergency condition and safety related aspects of the plant.
- 6.6 Shift Emergency Communicator
 - (1) Report to the Control Room immediately upon notification.
 - (2) Complete the Notification Report Form, Figure 1 (PINGP #577), F3-5, with assistance from the Emergency Director/Shift Supervisor of the unaffected unit.
 - (3) Complete the required notification of state and local authorities, and NSP personnel in accordance with F3-5, "Emergency Notifications".

NOTE: State and local authorities shall be notified within 15 minutes of the declaration of the emergency classification.

- (4) Notify applicable offsite authorities if conditions escalate to a more severe emergency class or whenever the emergency class is downgraded in accordance with F3-5, "Emergency Notifications".
- (5) When the emergency classification has been terminated, close-out the emergency classification, by notifying the state, local, and NSP personnel in accordance with F3-5, "Emergency Notifications".

NOTE: If the EOF has been activated, notifications of offsite agencies for an escalation, downgrade or termination of the emergency condition will be completed by EOF personnel.

6.7 Technical Support Center Coordinator

The Technical Support Center Coordinator shall be responsible for the general activation, operation and coordination of activities in the Technical Support Center (TSC).

The TSC Coordinator shall:

- Report to the TSC and assume the position as TSC Coordinator. Use Attachment C, Technical Support Center Coordinator Checklist (PINGP #573).
- (2) Coordinate activities of plant and non-plant personnel located in the TSC.
- (3) Designate individuals to fill the following positions:
 - a. Record Keeper (Maintain Emergency Director's Log)
 - Control Room Technical Communicator (Transfer plant status information to TSC Technical Communicator)
 - c. TSC Technical Communicator (Receive plant status information from Control Room Technical Communicator)
 - d. Event Status Board Recorder (Maintain status board with information obtained from TSC Technical Communicator)
 - e. Computer Operator (Operate Engineer's console & B&W Data Re-call Computer)
- (4) Establish and verify radiological monitoring for the TSC, in accordance with F3-6.
- (5) Ensure that the TSC doors are closed and initiate the TSC cleanup system, in accordance with F3-6.
- (6) Issue or designate an individual to issue dosimetry to all TSC personnel, in accordance with F3-6, Activation of the TSC.
- (7) Determine if all necessary positions are adequately staffed and request the SEC to notify additional staff to augment the emergency organization, as necessary.
- (8) Assist the Emergency Director in performing the accountability check as necessary as per F3-10.
- (9) Establish or ensure that communications are established with all onsite emergency operating facilities (Control Room, OSC and assembly area) to ensure all emergency organization personnel are informed of current plant status.

- (10) Assume responsibility for the Emergency Director phones.
- (11) Periodically update personnel located in the TSC with appropriate information.
- (12) Control the use of equipment located in the emergency locker.
- (13) Provide technical guidance on plant operations to the Emergency Director and Control Room operators.
- (14) Obtain and provide technical assistance as required to support the Technical Support Center and Control Room operations.
- (15) Assist in the establishment of 24 hour coverage of all key emergency organization positions.
- (16) Establish appropriate office space in the TSC for all emergency organization personnel (NSP and non-NSP representatives).

Interface with the non-NSP representatives located in the Technical Support Center and lend assistance where necessary.

- (17) When the Near-Site EOF has been activated, establish communications between the TSC and the EOF.
- 6.8 Operational Support Center Coordinator

The Operational Support Center Coordinator shall be responsible for the general activation, operation, and coordination of activities in the Operational Support Center (OSC).

The OSC Coordinator shall:

- Report to the OSC and assume the role as OSC Coordinator. Use Attachment D, Operational Support Center Coordinator Checklist (PINGP #574).
- (2) Determine the status of the plant and update all OSC personnel as necessary. Plant status may be determined by reporting to the Control Room and getting a briefing from the Shift Supervisor of the unaffected unit.
- (3) Coordinate activities of plant personnel located in the OSC to support plant operations as requested by the Control Room and TSC.

NOTE: The REC shall be responsible for control and direction for the Radiation Protection Specialists located in the OSC.

- (4) Establish and verify radiological monitoring for the OSC and the Control Room, as per F3-7.
- (5) When a plant evacuation occurs,
 - (a) Ensure all OSC personnel insert their badges into the OSC card reader. Inform the Emergency Director upon completion.
 - (b) Designate an individual to perform a Control Room accountability and transfer accountability sheet to the Emergency Director.
- (6) Ensure that dosimetry is issued to all OSC and Control Room Personnel, in accordance with F3-7.
- (7) Establish communications between the OSC, the TSC and the Control Room.
- (8) Designate an individual to update and maintain the OSC Status Board.
- (9) Periodically update personnel located in the OSC with appropriate plant status information.
- (10) Control the use of all food use in the OSC until directed by the Radiation Protection Group.
- (11) Control the use of equipment located in the emergency locker.
- 6.9 Assembly Point Coordinator

The Assembly Point Coordinator shall be responsible for the general operation of the assembly area.

The Assembly Point Coordinator shall:

- Verify that radiological monitoring has been established for the Assembly Point.
- (2) Coordinate activities of all personnel (plant and non-plant) located at the Assembly Point.
- (3) Assist the Emergency Director in performing the accountability check, as necessary, per F3-10.
- (4) Maintain the communication systems. A person may be designated as the communicator, if necessary.

- (5) Control the use of equipment located in the Emergency Locker.
- (6) Update all personnel with appropriate information when directed by the Emergency Director.
- (7) Provide instructions to personnel when they are released from the assembly point for reentry or transport offsite.
- 6.10 Radiological Emergency Coordinator (REC)

The Radiological Emergency Coordinator (REC) shall be responsible for accident assessment, onsite and offsite. The REC shall:

- Report to the Technical Support Center and assume responsibility for the Radiological Emergency Coordinator position. Use Attachment B, Radiological Emergency Coordinator Checklist (PINGP #572).
- (2) Determine the current plant status.
- (3) If radiological releases are occurring, airborne or liquid, verify that the Radiation Survey teams have been dispatched in accordance with F3-15 or F3-16.
- (4) If radiological airborne releases may or are occurring, initiate offsite dose projections in accordance with F3-13.
- (5) Assist the Emergency Director in performing the personnel accountability check of the Radiation Survey Teams, as necessary.
- (6) Designate or ensure that an RPS is designated to proceed to the EOF Count Room to perform any required analysis in the backup countroom, as necessary.
- (7) Maintain communications with the offsite survey teams. Based on current meteorological data, release data and survey team results, dispatch the survey teams in the affected areas of the plume.
- (8) Ensure that all Radiation Survey Team Members (onsite & offsite) are informed of the current plant status including status of releases and meteorological conditions and are informed of any emergency condition changes.
- (9) When the Radiation Survey Teams forward survey results to the TSC, log the data and supervise the development of the plume map.

- (10) If the wind is from the East or West such that the plume is traveling towards the Minnesota or Wisconsin bluffs, consider that plume diversion is likely to occur. Deploy the survey teams to conduct a plume search both beyond the bluffs and up and down the valley, where plume diversion is likely to occur.
- (11) Direct the activities of the onsite radiation survey teams, (i.e., samples required, surveys required, analysis, etc.).
- (12) Based on the meteorological data, release data, and surveys (onsite and offsite), determine the necessary radiation protection for the various segments of the plant emergency organization.
- (13) Monitor the habitability of the Auxiliary Building. If the radiation levels exceed 100 mR/hr or based on Rad Prot Group survey results, recommend to the Emergency Director that the Auxiliary Building Operators be evacuated to the OSC. All entries to the Aux Building shall be controlled thru the OSC.
- (14) Verify that the Radiation Protection Status Board is periodically update.
- (15) Based on offsite dose projections and offsite survey results, provide the Emergency Director with recommendations for Protective Actions in accordance with F3-8, "Recommendations For Offsite Protective Actions".
- (16) Periodically update the Minnesota Department of Health and the Wisconsin Section of Radiation Protection with information required by Figure 6 (F3-5) "Emergency Notification Followup Message" (PINGP #582).

NOTE: When the EOF is activated, this responsibility will be transferred to the Radiation Protection Support Supervisor (RPSS).

(17) Once the RPSS has arrived at the EOF, designate an individual to proceed to the EOF to perform dose assessment functions on the EOF MIDAS System.

- (18) When the Near-Site EOF is activated, transfer control of the offsite survey teams to the Radiation Protection Support Supervisor (RPSS).
- (19) Periodically or as requested, update the NRC, via the HPN phone, with release data, dose projections and meteorological data, as contained on Figure 6 (F3-5) "Emergency Notification Followup Message" (PINGP #582), or as otherwise requested.
- 6.11 Radiation Protection Group
 - The Shift Radiation Protection Specialist shall provide assistance (e.g., sampling, chemistry, radio-chemistry, surveys, or dose assessment) as requested by the Emergency Director.
 - (2) The Radiation Survey Teams shall be dispatched to initiate offsite surveys as directed per F3-15 and/or F3-16.
 - (3) All other Radiation Survey Team members shall report to the plant site for further instructions. The Radiation Survey Team members reporting to the plant site shall:
 - (a) Proceed to the Operational Support Center and wait for further instructions, unless otherwise directed by the Emergency Director or Radiological Emergency Coordinator.
 - (b) Supervise any checks for personnel contamination and direct decontamination at the assembly point.
 - (c) Provide recommendations to the Emergency Director regarding radiation exposure control to ensure that applicable limits are not exceeded.
 - (d) Provide radiation protection coverage for:
 - (1) Damage control and repair teams
 - (2) First aid
 - (3) Search and Rescue Teams
 - (4) Reentry Teams
 - (e) Perform emergency sampling (air and liquid), chemistry, radio-chemistry, surveys, etc., as directed by the Emergency Director or the Radiological Emergency Coordinator.

6.12 Security Group

- The Supervisor Security and Services or designee shall report to the Technical Support Center (TSC). The Supervisor Security and Services shall:
 - (a) Assume responsibility for personnel accountability following a plant evacuation and continuing accountability throughout the duration of the emergency. See procedure F3-10.
 - (b) Coordinate security control throughout the duration of the emergency situation.
 - (c) Evaluate aspects concerning acts or attempted acts of sabotage.
- (2) The Security Force shall:
 - (a) Continue with normal duties unless otherwise notified.
 - (b) During off-normal work hours, designate a Security Force Member to control the telephone switchboard in the TSC, when requested by the Shift Emergency Communicator (SEC).
 - (c) When the evacuation alarm sounds, all Security Officers, with the exception of the SAS operator, evacuate to the guardhouse for further instructions.

NOTE: The SAS operator should evacuate when directed by the Emergency Director.

(d) Assist with the evacuation of personnel to the designated assembly point which should normally be the Construction Office Building, in accordance with F3-29, "Emergency Security Procedures".

- NOTE: (1) It should be necessary for personnel to exit quickly thru the portal monitor and turnstile. Collect all I.D.'s and process badges so an Employee Onsite List of personnel inside Protected Area can be obtained.
 - (2) To speed evacuation from the Protected Area, it may be beneficial to open the vehicle gates and allow personnel to exit there.
 - (3) The Security Force shall ensure that all personnel onsite, within the protected area, have heard the evacuation alarm.
- (e) Perform a check of all areas immediately surrounding the Protected Area so that all personnel are notified of the evacuation in progress.

NOTE: The owner Controlled Area will be checked when directed by the Emergency Director.

- (f) Control access to Protected area per instructions from the Emergency Director. Be prepared to obtain a printout for an accountability check in accordance with F3-10, "Personnel Accountability".
- (g) Assist the Radiation Protection Group in establishing a secondary access control point when directed by the Emergency Director.
- (h) Station a Security Force Member, with dosimetry, at the plant entrance, if conditions permit, to control access to the plant site.

6.13 Logistic Support Group

The Logistic Support Group includes the Administrative Services Group, Purchasing & Inventory Control Group and the Document Control Group.

During emergency conditions, the Logistics Support Group shall:

- (1) Continue with normal duties unless directed otherwise.
- (2) Immediately vacate any emergency operating center (Control Room, OSC, or TSC) when an emergency is declared.
- (3) Remain clear of any areas, as announced over the public address system.
- (4) When requested by the Shift Emergency Communicator (SEC), the office staff shall transfer control of the telephone switchboard to the TSC.

NOTE: The switchboard operator should report to the TSC to control the switchboard from the TSC until relieved by an alternate communicator.

- (5) When the evacuation alarm sounds, proceed to the designated assembly point.
- (6) Follow instructions from the Assembly Point Coordinator for either reentry into the plant or departure from the site property.

6.14 Instrument & Control Group

- The I&C Supervisor and Coordinators shall report to the Operational Support Center (OSC) to provide support for:
 - (a) Repair and corrective actions for instrument and control systems, and;
 - (b) Search and rescue efforts.

- (2) The I&C Specialists shall:
 - (a) Continue with normal duties unless directed otherwise.
 - (b) Immediately vacate any emergency operating center (Control Room, OSC or TSC) when an emergency is declared.
 - (c) Remain clear of any areas, as announced over the public address system.
 - (d) When the evacuation alarm sounds, proceed to the designated assembly point.
 - (e) Follow instructions from the Assembly Point Coordinator for either reentry into the plant or departure from the site property.

6.15 Maintenance Group

The maintenance group consists of all maintenance personnel, plant electricians and plant helpers.

- The Maintenance Supervisors (Mechanical and Electrical), and designated electricians shall report to the OSC to provide support for:
 - (a) Repair and corrective actions for mechanical and electrical systems and;
 - (b) Search and rescue efforts.
- (2) All other maintenance personnel, electricians and plant helpers shall:
 - (a) Continue with normal duties unless directed otherwise.
 - (b) Immediately vacate any emergency operating center (Control Room, OSC, or TSC) when an emergency is declared.
 - (c) Remain clear of any areas, as announced over the public address system.
 - (d) When the evacuation alarm sounds, proceed to the designated assembly point.
 - (e) Follow instructions from the Assembly Point Coordinator for either reentry into the plant or departure from the site property.

6.16 Engineering Group

- All Superintendents, lead engineers and system experts (as requested by their supervisor) shall report to the Technical Support Center (TSC). The Engineering Group shall:
 - (a) Provide technical support for emergency repairs and corrective action on electrical and mechanical systems.
 - (b) Provide technical & engineering support for plant systems.
 - (c) Provide technical & engineering cupport for operating radioactive waste systems.
 - (d) Provide technical & engineering support on core parameter analysis.
- (2) All other engineers (unless specifically requested to remain in the TSC) shall:
 - (a) Continue with normal duties unless directed otherwise.
 - (b) Immediately vacate any emergency operating center (Control Room, OSC, or TSC) when an emergency is declared.
 - (c) Remain clear of any areas, as announced over the public address system.
 - (d) When the evacuation alarm sounds, proceed to the designated assembly point.
 - (e) Follow instructions from the Assembly Point Coordinator for either reentry into the plant or departure from the site property.
- 6.17 Contact, Temporary Personnel and Visitors
 - (1) Continue with normal duties unless directed otherwise.
 - (2) Immediately vacate any emergency operating center (Control Room, OSC, or TSC) when an emergency is declared.
 - (3) Remain clear of any areas, as announced over the public address system.
 - (4) When the evacuation alarm sounds, proceed to the designated assembly point.
 - (5) Follow instructions from the Assembly Point Coordinator for either reentry into the plant or departure from the site property.

	Page 27
PINGP #571, Re Page 1 of 2	ev. 3 ATTACHMENT A
Retention: Li	ifetime
	EMERGENCY DIRECTOR CHECKLIST
INIT	
(1)	Determine Plant Status
(2)	Announce Emergency Class over PA System
(3)	Contact STA & SEC to report to Control Room
(4)	Assist SEC & sign notification report. Direct SEC to:
	 (a) Notify offsite authorities (F3-5) (b) Augment onsite emergency organization (F3-5)
(5)	If the first notification of a supergency is a General Emergency, call the County Sheriff immediately and recommend:
	 (a) Activation of Phylic Verification Statem, and; (b) Sheltering within 2 the badies for plant and 5 miles downwind.
(6)	Assure communications established & maintained with NRC.
(7)	Direct Shift RPS to polotic
	a) conduct onsite specifing, as necessary. b) perform dose carculations, if R-50 in alarm mode.
(8)	Direct RPS/Plant Operations to conduct onsite/in-plant surveys, as necessary.
(9)	Determine need to evacuate nonessential personnel (F3-9)
(10)	If evacuation is necessary, designate assembly point.
	 (a) Designate assembly point coordinator (b) Complete accountability within 30 minutes after evacuation (F3-10)
	(c) Determine habitability of assembly area
(11)	Monitor Aux Building habitability and direct evacuation of Aux Operators to OSC if:
	(a) General area rad levels >100 mR/hr; or(b) Based on Rad Protection Group recommendations
(12)	The Shift Supervisor of the <u>unaffected</u> unit should complete a turnover to the designated Emergency Director at this point. Ensure that both Shift Supervisors are aware that a turnover of Emergency Director responsibilities has occurred. If the designated Emergency Director is not available, proceed with the checklist.

IBM

(

PINGP #571, Rev. 3 Page 2

ATTACHMENT A (Cont'd)

EMERGENCY DIRECTOR CHECKLIST

- (13) Direct activation of TSC & OSC (F3-6 & F3-7) and assign the responsibility for TSC Coordinator, OSC Coordinator and REC to appropriate individuals.
- (14) Update TSC personnel of plant status
- (15) Ensure communication links are established between onsite emergency centers. Designation TSC Coordinator to assume control of the Emergency Director phones.
- (16) Dispatch offsite survey terms as negotiating (F3-15 & F3-16)
- (17) Direct offsite as as a set that ies (F3-13)
- (18) Authorize protective action recommendations (F3-8). This authority may not be deligned.
- (19) Provide continuing the to State EOC's
- (20) Periodically, represent TSC personnel to provide status reports to allow updating all TSC personnel of current plant status.
- (21) Authorize overexposures as necessary (F3-12)
 - (22) Establish communications with EOF
 - (23) Transfer offsite responsibilities to EOF
- (24) Determine long-term manning requirements
 - (25) Escalate/downgrade emergency class, as appropriate
 - (26) Review Emergency Director's responsibilities to ensure all required actions are complete.

Emergency Director

Date/Time

PINGP 572, Rev. 4 Page 1 of 2 Retention: Lifetime

ATTACHMENT B

RADIOLOGICAL EMERGENCY COORDINATOR CHECKLIST

INIT

	(1)	Determine Plant Status
	(2)	Determine additional TSC support required for accident assessment functions & assign, as necessary.
<u></u>	(3)	Designate Rad Protection Coordinator for OSC
	(4)	Determine if releases are occurring
	(5)	Obtain meteorological data (3-13) & radiation monitor readings
<u></u>	(6)	Direct offsite dose projection calculations (F3-13)
<u></u>	(7)	Recommend protective ct in recommendations for Emergency Director (F3-8)
	(8)	Instruct, ditbatch & coordinate offsite radiation survey teams, as incessary in orderdance with the following:
		(a) F3-15 Airborne (1997) - Team #1 Plume Search & Sampling
	or	 (b) F3-15 Liquid Release - Team #1 Eisenhower Bridge Sampling Team #2 Intake/Discharge Canal & Lock & Dam Sampling
	(9)	Ensure an RPS is designated to operate the EOF countroom facility and perform the required analysis, as necessary.
	(10)	Consider plume diversion along valley if plume is traveling towards Minnesota or Wisconsin bluffs and instruct Survey Teams appropriately.
	(11)	Instruct, dispatch & coordinate onsite radiation survey teams, as necessary (F3-14)
	(12)	Monitor the habitability of the Auxiliary Building. Recommend to the Emergency Director that the Aux Operators evacuate to the OSC if the general area rad levels are >100 mR/hr or based on Rad Protection Group surveys.
	(13)	Determine RPS sampling priorities per F3-23 (number in order) and specify protective clothing/respiratory protection require- ments for sampling team.
		Primary Sample - Pressurized/Unpressurized
		Secondary Sample
		Shield Building Stack Sample

IBM

PINGP 572, Rev. 4 Page 2

RADIOLOGICAL EMERGENCY COORDINATOR CHECKLIST

Containment Air Samp	21	4
----------------------	----	---

_ Liquid

-] Filtered Gas
-] Unfiltered Gas
-] Iodine/Particulate
-] Other

INIT

- (14) Periodically, update offsite and onside survey teams with updates on plant status, release information, meteorological information, and emergence classifications, as necessary.
- (15) Evaluate survey data (prevelop plume map
- (16) Request alternate meteorological data and weather forecast information as necessary (F3-13 Figure 4)
- (17) Recommend overexposure limits to Emergency Director (F3-12)
- (18) Update the Radiation Protection Status Board
- (19) Provide periodic updates to the Emergency Director & TSC Staff
- (20) Update the State Health Departments (Minn & Wisc)
- (21) Establish/Maintain communications with the RPSS
 - (22) Designate an individual to operate the MIDAS System at the E.O.F.
 - (23) Turnover the offsite survey responsibilities to the RPSS
- (24) Acknowledge the HPN phone and update the NRC as appropriate.
 - (25) Review the REC responsiblities (F3-4 Section 6.10) to ensure all required actions are complete

Radiological Emergency Coordinator

Date/Time

IBM

PINGP 573, (FRONT) Rev. 5 Retention: Lifetime

ATTACHMENT C

TECHNICAL SUPPORT CENTER COORDINATOR CHECKLIST

INIT


- (1) Coordinate the activities of plant and non-plant personnel located in the TSC.
- (2) Designate the following positions:
 - Record Keeper: a.
 - b. Control Room Technical Communicator PLE
 - TSC Technical Communicator: с.
 - Event Status Board Recorde d.
 - e. Computer Operator:
- Shut TSC Door and Start TSC Clean] (3)
 - (4) Designate an individual(s) to sh communication between TSC, OSC & Control Room.
- (5) Assume responsibility of the Emergency Director Phones.
- (6) Establish radiological monitoring of the TSC environment utilizing the CAM and VAMP (F3-6, Section 4.2)
- (7) Issue dosimetry to all TSC personnel.
- (8) During a plant evacuation, assist the Emergency Director in overall plant accountability (F3-10). May be designated to the Supervisor Security and Services.
- (9) Determine additional TSC staffing required and request SEC to to make notifications.
- (10) Update TSC personnel with plant status updates as requested by the Emergency Director.
- (11) Provide technical assistance and guidance to the Emergency Director and Control Room.
 - (12) Evacuate all unnecessary personnel, as requested by the Emergency Director.
 - (13) Control use of equipment located in Emergency Locker
 - (14) Establish appropriate office space for Emergency Personnel
- BM

PINGP 573, (BACK) Rev. 5

- (15) Establish routine sampling & monitoring for the TSC as necessary.
- (16) When the Near-Site EOF has been activated, ensure that communications are established between the TSC and EOF.
 - (17) Review F3-4 & F3-6

TSC Coordinator

Date/Time



PINGP 574, Rev. 3
 Page 1 of 1
 Retention: Lifetime

ATTACHMENT D

OPERATION SUPPORT CENTER COORDINATOR CHECKLIST

INIT

	(1)	Determine plant status and update OSC personnel.
	(2)	Coordinate activities of plant personnel in the OSC.
	(3)	Designate an individual(s) to establish communication between OSC, TSC and Control Room.
	(4)	4.2.1)
	(5)	Activate & verify property in of the Control Room CAM (F3-7, Section Article Color CAM)
-	(6)	Issue dosimetry OSC and the rol off Susonnel.
	(7)	Designate an individual (s) to control use of equipment in Emergency Lockers.
	(8)	When a plant even of occurs,
		 (a) Ensure all OSC personnel insert their badges into the OSC card reader. Inform the Emergency Director upon completion. (b) Designate an individual to perform a Control Room accountability and transfer accountability sheet to the Emergency Director.
1	(9)	Evacuate all unnecessary personnel.
	(10)	Control use of food in OSC until directed by Radiation Protection Group.
	(11)	Establish a routine sampling and monitoring of OSC and Control Room as necessary.
	(12)	Periodically update Status Board and Personnel.
	(13)	Review F3-4 & F3-7.

Date/Time

	PAG	GE 1 OF 43	
PRAIRIE ISLAND NUCLEAR	EMERGENCY PLAN IMPLEMENTING PROCEDURES		
GENERATING PLANT NORTHERN STATES POWER COMPANY	 Number: F3-5	Rev: 10	
0.0	 Retention Time:	History Copy Lifetime	
Reviewed By: A.A. Schuelke Supt. Rad Protection	TITLE:		
Approved By: Quat Plant Managor	EMERGENCY NOTIFICATIONS		
O.C. Date: 9-25-84	1		

1.0 PURPOSE

This instruction delineates the notification procedures to be used during emergency conditions, defines the various emergency communications systems available at the plant, (primary and backup), and provides the necessary operating instructions for their proper use.

2.0 APPLICABILITY

This instruction SHALL apply to all Radiological Emergency Coordinators, Shift Supervisors, Emergency Directors and Shift Emergency Communicators.

3.0 PRECAUTIONS

- 3.1 Always speak in a clear, distinct voice.
- 3.2 Make messages as short and concise as possible.
- 3.3 Always have the information repeated if it was not completely understood.

4.0 PROCEDURE

- 4.1 The Shift Emergency Communicator (SEC) Shall:
 - 4.1.1 Report to the Control Room
 - 4.1.2 Complete the "Emergency Notification Report Form", Figure 1, (PINGP #577) with assistance from the Emergency Director or Shift Supervisor.
 - 4.1.3 Upon completion of the "Emergency Notification Report Form", (PINGP #577) report to the communications area of the Technical Support Center.

4.1.4 Request the telephone switchboard operator to transfer control of the switchboard to the TSC and request that individual to report to the TSC to control the switchboard until relieved by a backup communicator, or the emergency situation is terminated.

> NOTE: Refer to the Nuclear Emergency Preparedness Telephone Directory for specific telephone locations and numbers.

4.1.5 Initiate and complete the notifications of state, local, and NSP personnel as listed on the Emergency Notification Call Lists, as follows:

- (a) For a Notification of Unusual Event, use Figure 3, PINGP #579.
- (b) For an Alert, Site Area, or General Emergency, use Figure 4, PINGP #580.
- 4.1.6 Request local offsite support as deemed necessary. Coordinate these notifications with the control room. (Refer to the Nuclear Emergency Preparedness Telephone Directory for local support telephone numbers.)
- 4.1.7 If the emergency has been reclassified, (i.e., escalated, down-graded, or terminated) complete the Emergency Classification Change, Figure 2, PINGP #578 and complete the notifications of offsite authorities as follows:
 - (a) For a termination from a Notification of Unusual Event, use Figure 3, PINGP #579.
 - (b) For any classification change, use Figure 4, PINGP #580.
- 4.1.8 When the EOF becomes activated, transfer control of Offsite Notifications to the EOF.
- 4.2 The Radiological Emergency Coordinator (REC) Shall:
 - 4.2.1 Complete the Emergency Notification Followup Message Form, Figure 6, PINGP #582.

NOTE: This form does not need to be completed in its entirety prior to transmitting data to offsite authorities. 4.2.2 Periodically update the Minnesota Department of Health and the Wisconsin Division of Radiation Protection with the information as recorded on Figure 6, PINGP #582 the "Emergency Notification Followup Message".

> NOTE: When the Nearsite EOF is activated, updates to the Minnesota Department of Health and Wisconsin Division of Radiation Protection will be handled by EOF personnel.

4.2.3 Acknowledge the HPN phone when it rings and periodically, update the NRC with the information as recorded on Figure 6, PINGP #582 the "Emergency Notification Followup Message".

> NOTE: Be prepared to provide continuous updates to the NRC, as requested over the HPN phone.

PINGP #577, Rev. 1

FIGURE 1 INITIAL EMERGENCY NOTIFICATION REPORT

Verify that the organization/person called is correct prior to relaying emergency information.

THIS IS , SHIFT EMERGENCY COMMUNICATOR AT THE (Name) PRAIRIE ISLAND NUCLEAR GENERATING PLANT. AT WE HAVE DECLARED A(N) HOURS. (Time) (Emergency Class) Pick one of the following: WE HAVE NOT HAD A RADIOACTIV QACTIVE RELEASE. WE HAVE HAD A(N) rborne) ATMOSPHERIC CONDITIONS AT THE PRESENT NOLLOWS: WIND DIRECTION IS FRO AT MPH. (Speed THE AFFECTED SECTOR(S) IS(ARE Sist sector(s) by letter designation) THE PROTECTIVE ACTION RECOMMENDED AT THIS TIME IS: NONE SHELTER IN SECTORS OUT TO MILES EVACUATE IN SECTORS OUT TO MILES ACTIVATE THE PUBLIC NOTIFICATION SYSTEM Give a brief description of the emergency. PLEASE RELAY THIS INFORMATION TO YOUR EMERGENCY ORGANIZATION PERSONNEL. Emergency Director Approval Name/Date Shift Emergency Communicator Name/Date

PINGP #578, Rev. 1

FIGURE 2 EMERGENCY CLASSIFICATION CHANGE

Verify that the organization/person called is correct prior to relaying emergency information.

THIS IS , SHIFT EMERGENCY COMMUNICATOR AT THE (Name) PRAIRIE ISLAND NUCLEAR GENERATING PLANT. WE HAVE RE-CLASSIFIED THE EVENT AND Escalated Down-graded Etalt May Be Terminated The Wheed is ches TO A(N): (Pick one below if escalated or down Notification of Unusual Even Alert Site Area Emer General Emergence AT HOURS (Time) Atmospheric Conditions at the Present Time Are as Follows: Wind Direction is From the MPH. (Direction) (Speed) The Affected Sector(s) is(are) (List Sector(s) by Letter Designation) Form of Precipitation (if applicable) Give a brief description of the emergency: PLEASE RELAY THIS INFORMATION TO YOUR EMERGENCY ORGANIZATION PERSONNEL.

Emergency Director

Name/Date

Shift Emergency Communicator

Name/Date

PINGP 579 Rev. 8 Page 1 of 7 Retention: Life

EMERGENCY NOTIFICATION CALL LIST FOR A NOTIFICATION OF UNUSUAL EVENT

GENERAL INSTRUCTIONS

- The Shift Emergency Communicator SHALL make notifications to the individuals and organizations listed on this Emergency Call List.
- (2) Contact each organization or individual using the contact information listed in this Attachment.
- (3) For those notifications made by telephone, make the call as follows:

NOTE: All primary contacts contained to this checklist have pre-programed telephone numbers on the Tour static dialers. Alternate or both telephone products must be manually dialed.

- a. When the party answers read the terr of the Initial Notification Report Form.
- b. Note the name of the individe Montacted and the time of the contact.
- (4) For those notifications made by AWAS, transmit only the information as specified in this procedure. Specific plant data, as specified on the Initial Notification Report Form, will be available to those authorities when they call back for a verification.
- (5) Proceed to the next party on the call-list.
- (6) If a party cannot be contacted in two attempts, use alternate or backup communication channels. If a party still cannot be reached, consider other means such as dispatching a courier, relay through another party or similar actions.
- (7) The Wisconsin Division of Emergency Government (DEG) and the Minnesota Division of Emergency Services (DES) are required to call back for verification and/or request further information. Other emergency organizations, e.g., Minnesota and Wisconsin Health Departments may call the plant for more information. Update these organizations, as appropriate. Use the Contact Report Log, PINGP #597 or the verification signoffs in this checklist to note the time and the names of the individuals calling.
- (8) If a party not specified on the call list requests information, refer the party to the NSP Communications Department or to the local emergency services organization in his/her community, as appropriate.

I 3M

PINGP 579 Rev. 8 Page 2 of 7

N

SHIFT EM	ERGEN	CY COMMUNICATOR		DATE
EMERGENC	Y CLA	SS/TIME DECLARED		
FICATIONS				
Request by eithe	the to r:	elephone switchboard	operator to report	to the TSC,
swi	mal We tchboa tchboa	orkday () - ard operator to repo ard.	Dial 0 and request rt to the TSC to co	the assigned ontrol the
			* Jha	Time/SEC Initials
(b). Off: guar	shift rd to	- Call the CAS open report to the TSS	for t Ext. 318 oppontrol the	request a board.
		-XAM	ASIS CEMISUC	Time/SEC Initials
NOTE:	the	switchboard operate	king immediately.	DO NOT wait for
I	ne Min	mesota Divicio	Shoarrive in the	TLS.
Notify th	ne Min	mesota Divicio	Emergency Services.	The telephone Officer) Verification
Notify the number is Contact	ne Min	mesota Division day.	Emergency Services. (Ask for the Duty Initial Notification- SEC INITIALS	TCS. The telephone Officer) Verification Time/SEC Initials
Notify th number is Contact Person	(1)	Inesota Division operation of day.	Emergency Services. (Ask for the Duty Initial Notification- SEC INITIALS shall be made within emergency class.	TCS. The telephone Officer) Verification Time/SEC Initials n 15 minutes

PINGP 579 Rev. 8 Page 3 of 7


EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

- Using the NAWAS network, notify the Wisconsin authorities in accordance with the following procedure:
 - (a). Pick up the NAWAS set, press the talk button and say:

"THIS IS PRAIRIE ISLAND NUCLEAR PLANT CALLING WISCONSIN WARNING CENTER ONE, WEST CENTRAL WARNING CENTER AND PIERCE COUNTY WARNING CENTER, ACKNOWLEDGE."

(b). When warning center one, west central warning center and Pierce County warning centers acknowledge, press the talk switch and say:

PRAIRIE ISLAND NUCLEAR PLANT IS (Pick correct classification):




IBM

PINGP 579 Rev. 8 Page 4 of 7

EMERGENCY NOTIFICATION CALL LIST FOR A NOTIFICATION OF UNUSUAL EVENT

4. Notify the local authorities by telephone as follows:

(a) GOODHUE COUNTY SHERIFF AT



5. Notify the Plant Manager (or designee) if not already done so, to inform him of the situation (notify one of the following in the order shown):

Name

Home Phone

	1	
Time	/ SEC Initial	s
Time	/ SEC Initial	s
Time	/ SEC Initial	s
Time	/ SEC Initial	s

SEC Initials

PINGP 579 Rev. 8 Page 5 of 7

EMERGENCY NOTIFICATION CALL LIST FOR A NOTIFICATION OF UNUSUAL EVENT

NOTE: The Plant Manager pager number is . The pager should be used as a backup means of notifying the Plant Manager. The pager is passed down the line of succession when the Plant Manager is unavailable.

6. Notify the NSP System Dispatcher (Telephone No.). Inform him of the situation, give him the name of the acting Emergency Director (or Shift Supervisor) and the number where he can be reached (Control Room, , or TSC,).

NOTE: Alternate means to communicate with the NSP stem D patcher should be attempted in the following order (1) Telephone: (2) Telephone: (3) Control Room Hotline (4) Channel 7 - Radio Conso 7. Notify ONE of the NRC Resident Inspectors: · Plant Ext. - Home # 07 /SEC Initials Time - Plant Ext. - Home #

Time SEC Initials

 Contact the NSP District Manager, or designee, to inform him of the emergency situation (Notity ONE of the following, in the order shown):

Work :

Home # SEC Initials Time Time SEC Initials Time SEC Initials

Time.

Supervisor on Duty

(24 hour number)

F3-5 Rev. 10 PAGE 11

PINGP 579 Rev. 8 Page 6 of 7

EMERGENCY NOTIFICATION CALL LIST FOR A NOTIFICATION OF UNUSUAL EVENT

- 9. Update the Radio Alert Monitor System Message Cassette as follows:
 - (a) Insert a blank tape into the tape recording unit.
 - (b) Make sure that the remote control unit 'Mike Enable' & 'Transmit Enable' key switches are both off (Green).
 - (c) Set tape unit selector switch to 'Record Announcement' insert microphone in tape unit mike jack.
 - (d) Press tape unit 'Start' switch and record the prepared message.
 - NOTE: (1) Information to be recorded should have the date, time and unit status.
 (2) When recording the message, sheak slowly and clearly, about 3 inches from the microphone.
 - (e) Set tape unit selector switch to the Annothermore Poress 'Start' switch and listen to recording. "adjust volume to destred level with tape unit 'Monitor Volume' Control.) If satisfy fory, proceed with (f).

Time

Time

SEC Initials

SEC Initials

- (f) Now, remove the message cassette from the fair unit and insert it into the telephone answering unit.
- Notify or verify the Control Room has established notification of the NRC Emergency Response Center via the ENS Hotline.

NOTES:	Notification of NRC required to be made with one hour of event declaration. If the ENS Network should become disabled, th Operations Center may be contacted at any of following numbers, in the order shown:	ne NRC
	(a) (Via Bethesda Central Office)	
	(b) (Via Silver Spring Central Office).	
	(c) (Via Bethesda Central Office)	
	(d) (Via Health Physics Network)	
	(via NRC Operator at Bethesda Central Office)	

IBM

F3-5 Rev. 10 PAGE 12

0.

PINGP 579 Rev. 8 Page 7 of 7

4.90

EMERGENCY NOTIFICATION CALL LIST FOR A NOTIFICATION OF UNUSUAL EVENT

11. Inform the Shift Supervisor of the completion of the notifications.

Time /SEC Initials

CALL LIST COMPLETE: TIME	DATE
SHIFT EMERGENCY COMMUNICATOR	Alle
	apte on anoth
ć	KASSON USE REMISUS
	alent har
	BUCallon

lotification

PINGP 580 Rev. 9 Page 1 of 10 Retention: Lifetime

EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

GENERAL INSTRUCTIONS

- The Shift Emergency Communicator SHALL make notifications to the individuals and organizations listed on this Emergency Call List.
- (2) Contact each organization or individual using the contact information listed in this Attachment.
- (3) For those notifications made by telephone, make the call as follows:

NOTE: All primary contacts contained in this specialist have pre-programed telephone numbers on the specialist have dialers. Alternate or backup telephone numbers must be manually dialed.

- a. When the party answers, Report Form.
- b. Note the name of the individual contocide and the time of the contact.
- (4) For those notifications made by Market transmit only the information as specified in this procedure. Specific plant data, as specified on the Initial Notification Report Form, will be available to those authorities when they call back for a verification.
- (5) Proceed to the next party on the call-list.
- (a) if a party cannot be contacted in two attempts, use alternate or backup communication channels. If a party still cannot be reached, consider other means such as dispatching a courier, relay through another party or similar actions.
- (7) The Wisconsin Division of Emergency Government (DEG) and the Minnesota Division of Emergency Services (DES) are required to call back for verification and/or request further information. Other emergency organizations, e.g., Minnesota and Wisconsin Health Departments may call the plant for more information. Update these organizations, as appropriate. Use the Contact Report Log, PINGP #597 or the verification signoffs in this checklist to note the time and the names of the individuals calling.
- (8) If a party not specified on the call list requests information, refer the party to the NSP Communications Department or to the local emergency services organization in his/her community, as appropriate.

PINGP 580 Rev. 9 Page 2 of 10

EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

SHIFT EMERGENCY COMMUNICATOR

DATE

EMERGENCY CLASS/TIME DECLARED

NOTIFICATIONS

- Request the telephone switchboard operator to report to the TSC, by either:
 - (a). Normal Workday () Dial 0 and request the assigned switchboard operator to report to the TSC to control the switchboard.

Time/SEC Initials

(b). Offshift - Call the CAS operator 318 and request a guard to report to the TSC to contist the switchboard.

Mime/SEC Initials

NOTE: Continue with this checklish Immediately. DO NOT wait for the switchboard operator securive in the TSC.

2. Notify the Minnesota Division of Emergency Services. The telephone number is , night of day. (Ask for the Duty Officer)

Contact	Time	Initial	Verification	
Person		Notification- SEC INITIALS	Time/SEC Initials	5

- NOTE: (1) This notification shall be made within 15 minutes of declaration of emergency class.
 - (2) If NO verification is received within 30 minutes, contact the state again.
 - (3) Alternate means to contact the DES Duty Officer is via Capitol Security (telephone no.). Request Capitol Security to connect you directly to the Duty Officer or request Capitol Security to contact the Duty Officer and have the Duty Officer call the Prairie Island Plant immediately.

PINGP 580 Rev. 9 Page 3 of 10

EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

- 3. Using the NAWAS network, notify the Wisconsin authorities in accordance with the following procedure:
 - (a) Pick up the NAWAS set, press the talk button and say:

"THIS IS PRAIRIE ISLAND NUCLEAR PLANT CALLING WISCONSIN WARNING CENTER ONE, WEST CENTRAL WARNING CENTER AND PIERCE COUNTY WARNING CENTER, ACKNOWLEDGE."

. .

(b) When Warning Center One, West Central Warning Center and Pierce County Warning Centers acknowledge, press the talk switch and say:

"PRAIRI correct	E ISLAN class	ND NUCLEAR):	PLANT IS I	EXPERIENCING ACC	(Fick the
		1_1	ALERT, or	OLE	an
		11	SITE ARE	Elegander Hand	MELler
		1_1	GENERAL	MERGENCY OFT	130-
RELAY T	HIS INF	FORMATION 7	O EMERGENO	CY GOVERNORE IMM	EDIATELY."
Warning	Center	r I		alligue	
			Time ((Delitial	Verification
				Notification-	Time/SEC Initial
Went Ca				SEC Initials	
West Ce	ntrai v	arning	Time		
Ce	nter		lime	Initial Notification-	
				SEC Initials	
Pierce	County	Warning		SEC INTEL AIS	
	Center		Time	Initial	
				Notification-	
				SEC Initials	
I NOTE	: (1)			MALL be made wit	
	103			ion of emergency	
1	(2)			arning centers d	
1				sin Warning Cent	
1				e circuit and re ate warning cent	
1	(3)			should become d	
i	(5)			f notification t	
i i				be attempted, as	
1				elephone	
1				arning Center	Telephone
		(c) Pier	ce County	Telephone	,
			Padia	- Channel 1	
			Radio	snamer 1	and a second second

PINGP 580 Rev. 9 Page 4 of 10

EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

4. Notify the local authorities by telephone as follows:

(a) GOODHUE COUNTY SHERIFF AT

Contact Contact	itials
(2) Alternate means to communicate att County Sheriff is the Radio of the DAKOTA COUNTY SHERIFF AT Contact NOTES: (1) This notificate of the State of the made with minutes of declaration of emergency	Contraction and the second second second
County Sheriff is the Radio of the DAKOTA COUNTY SHERIFF AT Contact NOTES: (1) This notificat-off Could be made with minutes of decontrion of emergency	
Contact NOTES: (1) This notification of emergency	- Channel 1
NOTES: (1) This notificate will will be made with minutes of de interior of emergency	Lings
NOTES: (1) This notification of emergency	ial ation-
(2) Alternate means to communicate with	chin 15 class.
County Sheriff is the Radio System	
	-
NOTE: IF THE EMERGENCY RESPONSE ORGANIZATION HA BEEN ACTIVATED BY THIS CHECKLIST, THE FOI NEED NOT BE CONPLETED FOR FURTHER ESCALAT	LOWING STEP
	THEFT

Name

shown):

5

Home Phone

Time	7	SEC	Initials
Time	7	SEC	Initials
Time	-1'	SEC	Initials
Time		SEC	Initiale

SEC Initials

Time

PINGP 580 Rev. 9 Page 5 of 10

> EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

NOTE: The Plant Manager pager number is . The pager should be used as a backup means of notifying the Plant Manager. The pager is passed down the line of succession when the Plant Manager is unavailable.

6. Notify the NSP System Dispatcher (Telephone No.). Inform him of the situation, give him the name of the acting Emergency Director (or Shift Supervisor) and the number where he can be reached (Control Room, , or TSC,).

NOTE: Alternate means to communicate with the NSE m Dispatcher should be attempted in the followin der: (1) Telephone: (2) Telephone: (3) Control Room Hotline (4) Channel 7 - Radio Conso 7. Notify ONE of the NRC Resident Inspectors: - Plant Ext. Home # Time /SEC Initials or - Plant Ext. - Home # Time SEC Initials 8. Activate the Emergency Response Organization as follows:

- (a) Normal Work Hours
 - (1) Verify announcement to report to emergency response centers is made over public address system.

(2) Contact the PI Training Center by telephone (

request them to report to the EOF.

Time/SEC Initials

), inform them of the emergency classification and

Time/SEC Initials

IBM

PINGP 580 Rev. 9 Page 6 of 10

> EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

NOTE: Alternate numbers should be attempted in the following order:

(3) Contact the Nuclear Technical Services Group by telephone (Ext. or Ext.), inform them of the emergency classification and request them to report to the EOF.

Time/SEC inicials

NE OHALY

THE

NOTE: Alternate numbers should be attempted in the following order:

(b) Off-Normal Work Hours

NOTE: NSP personnel and Civil De SHALL be activated by chile off-normal work hours.

- Insert the pre-recorded tape of gnated "ERO Callout" into the tape unit.
- (2) Set the tape unit selector switch to "Answer".
- (3) Turn the message transmitter control unit "Transmit Enable" key switch to the ON position. The red "XMIT" lamp should light.
- (4) Enter Code 04 on the encoder unit and press "P". As soon as the tones are completed, enter Code 06 and then press "P".

NOTE: Several seconds after the last tone is heard, the tape will be transmitted 3 times - then the unit will shut off.

PINGP 580 Rev. 9 Page 7 of 10

- (5) Verify proper operation of the radio alert monitor system by acknowledging that the TSC Radio Alert Monitor did activate. If not, repeat steps (1) through (4).
- (6) If the radio alert system failed to function after 2 attempts, use the Emergency Organization Call List, PINCP #581 and call all Emergency Organization Members by telephone.
- (7) When the transmission has ended, turn the "Thensmit Enable" key switch to the OFF position
- '9. Notify the Local Residents as for
 - (a) Insert the pre-recorded tape designated?
 - (b) Set the tape unit selector switch to "Answer".
 - (c) Turn the message transmitter control unit "Transmit Enable" key switch to the ON position. The red "XMIT" lamp should light.
 - (d) Enter Code 01 on the encoder unit and press "P".

heard, the tape will be transmitted 3 times - then the unit will shot off.

(e) Verify proper operation of the radio alert monitor system by acknowledging that the TSC Radio Alert Monitor did activate. If not, repeat steps (a) through (d).

EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

PINGP 580 Rev. 9 Page 8 of 10

EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

- (f) If the Radio Alert System failed to function after 2 attempts, proceed with Step (g).
- (g) When the transmission has ended, turn the "Transmit Enable" key switch to the OFF position.
- (h) Remove the message cassette from the tape unit and insert it into the telephone answering unit.
- 10. Contact the NSP District Manager, or designee, to the aim of the emergency situation (Notify ONE of the following, which order shown):

Work # Work # Supervisor on Duty (24 hours, REQUEST THE NSP INDIVIDUAL, CONTACTED ABOVE, TO REPORT TO THE NSP RED WING SERVICE CENTER TO UNLOCK THE FACITLITIES FOR THE NSP RADIATION SURVEY TEAMS.

 Notify or verify the Control Room has established notification of the NRC Emergency Response Center via the ENS Hotline.

Time /SEC Initials

Rev. 10 Page 20

Time/SEC Initials

PINGP 580 Rev. 9 Page 9 of 10

EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

12 12 12 12	one	ification of NRC requi- hour of event declaration of the ENS Notwork should	tion.	
	Oper	the ENS Network should rations Center may be lowing numbers, in the	contacted at any of th	
	(a)	(Via Bethesda Centra)	l Office)	
	(b)	(Via Silver Spring Co	entral Office)	
	(c)	(Via Bethesda Central	l Office)	
	(d)	(Via Health Physics M	Network)	
	(e)	(Via NRC Operator at Central Office)	BeOHL	
	. Where	cated othe city will n an area coust ther the the office and home.	phone numbers are area nan is shown, it	a cod
app] 	. Where	the office and home.	an is shown, it	a co
	. Where	an area coup other th	phone numbers are area nan is shown, it <u>Office</u>	a co
app] 	. Where lies to	the office and home.	an is shown, it	a co
Title 'ita Service: Operating Pla	. Where lies to Pepres	Name entative	an is shown, it	a co
Title Title Title Services Operating Pla Manager	. Where lies to Repres ant Regi	Name entative	an is shown, it	a co
Title 'ite Service: Operating Pla Manager 'st Alternate	. Where lies to Repres ant Regi e	Name entative	an is shown, it	a co
Title Title Title Services Operating Pla Manager	. Where lies to Repres ant Regi e	Name entative	an is shown, it	a co
Title 'ite Service: Operating Pla Manager 'st Alternate	. Where lies to Repres ant Regi e	<u>Name</u> Name entative onal	an is shown, it	a co
Title Title Title Cperating Pla Manager St Alternate Service Responses Ist Alternate	. Where lies to Pepres ant Regi e onse Man	<u>Name</u> Name entative onal	an is shown, it	a co
Title Title Title Title Title Title Cperating Pla Manager St Alternate 2nd Alternate Service Respo	. Where lies to Pepres ant Regi e onse Man	<u>Name</u> Name entative onal	an is shown, it	a co
Title Title Title Cperating Pla Manager St Alternate Service Responses Ist Alternate	. Where lies to Repres ant Regi e e onse Man	<u>Name</u> Name entative onal	an is shown, it	a co
Title Title Title Title Title Title Title Cperating Pla Manager St Alternate 2nd Alternate 2nd Alternate Emergency Res	. Where lies to Repres ant Regi e onse Man e sponse D	<u>Name</u> Name entative onal	an is shown, it	a co
Title Title Title Title Title Title Title Title Cperating Pla Manager St Alternate Service Responses Service Response Service Response Service Responses Service Response Service Respon	. Where lies to Repres ant Regi e onse Man e sponse D	<u>Name</u> Name entative onal	an is shown, it	a co
Title Title 'ita Service Operating Pla Manager 'st Alternate 2nd Alternate 2nd Alternate 2nd Alternate Emergency Res Emergency Res Director	. Where lies to Pepres ant Regi e onse Man e sponse D sponse D	<u>Name</u> Name entative onal	an is shown, it	
Title Cite Service Derating Pla Manager St Alternate Ind Alternate Service Respondent Service Respondent Service Respondent End Alternate End Alternate Emergency Respondent Emergency Res	. Where lies to Pepres ant Regi e onse Man e sponse D sponse D	<u>Name</u> Name entative onal	an is shown, it	ac

F3-5 Rev. 10 · Page 21

PINGP 580 Rev. 9 Page 10 of 10

EMERGENCY NOTIFICATION CALL LIST FOR AN ALERT, SITE AREA, OR GENERAL EMERGENCY

 Notify American Nuclear Insurers (ANI) by Telephone -(24-Hour Number)

Time /SEC Initials

/SEC Initials

Time /SEC Initials

ime

- NOTES: (1) During Normal Office Hours (8:00 a.m. 4:00 p.m.), this number will be answered by a receptionist who will transfer the call to an appropriate individual.
 - (2) During Off Normal Office Hours, an answering machine will intercept the call and notify a designated ANI Staff Member. Please leave your name, company, and telephone number. The ANI member will return the call to obtain further information.
- 14. Notify INPO by telephone at Inform INPO of plant status and that Nave Veadouarter Emergency Center will contact them is the state of the necessary.

NOTES: (1) Alternate emergency contractioner is

- (2) After hours, an automatic dialing system will answer and request the following information:
 - your name, telephone number and plant
 - is this an actual emergency or drill
 - how can INPO help
 - repeat your area code and telephone number.
- 15. Inform the Emergency Director of the completion of the notifications.

CALL LIST COMPLETE:	TIME	DATE	-
SHIFT EMERGENCY COMMUN	ICATOR		_

PINGP 581, Rev. 5 Page 1 of 3 Retention: Life

FIGURE 5 EMERGENCY ORGANIZATION CALL LIST

INSTRUCTIONS

-a

1

- (1) This call list SHALL be used to activate the ONSITE Emergency Response Organization during off-normal work hours, should the Radio Alert Monitor System Fail.
- (2) Use the following notification guidelines:
 - (a) Contact each individual in the order shown;
 - (b) When the individual answers, request that individual to report to the plant;
 - (c) Proceed to the next individual on the call list;
 - (d) If an individual cannot be contacted in two attempts, bypass that individual and proceed down the list. After the other notifications are complete, re-attempt to consist any bypassed individuals. <u>NONS</u> agement (OC Members) PLANS MUNIGER that individual and proceed down the list. After the other

NOTIFICATIONS

Plant Management (OC Members)

PLANT AGER PLT SUPT ENGR & RAD PRAN PLT SUPT OPER SA SUPT RAD FROTENCE SUPT MAINT SUPT OF PALENCE SUPT OF PALENCE SUPT OF PALENCE SUPT QUALITY ENGR SUPT TECH ENGR SUPT NUC ENGR

Radiation Protection Group

RAD PROT SPEC RAD PROT SPEC RAD PROT SPEC RAD PROT SPEC RAD PROT COORD CHEMIST RAD PROT SPEC RAD PROT SPEC RAD PROT SUPV TRAINING INSTRUCTOR RADIO-CHEMISTRY SUPV RAD PROT SPEC RAD PROT SPEC RAD PROT SPFC RAD PROT COORD RAD PROT SPEC RAD PROT SPEC RAD PROT SPEC


PINGP 581, Rev. 5 Page 2 of 3

FIGURE 5 (Continued) EMERGENCY ORGANIZATION CALL LIST

Radiation Protection Group (Continued)

RAD	PROT	SPEC
QUAL	ITY S	PEC
RAD	PROT	SPEC
PRIN	PROD	ENGR

Maintenance/Electricians



1 & C Group

Engineers

ENGINEER ASSOC PROD ENGR ASSOC PROD ENGR LEAD PROD ENGR ASST PROD ENGR ASSOC PROD ENGR ASSOC PROD ENGR LEAD PROD ENGR LEAD PROD ENGR

EOF Coordinator

SOFF TRAINING LEAD PROD ENGR PROD ENGR

r5-5 Rev. 10 Page 25

PINGP 581, Rev. 5 Page 3 of 3

> FIGURE 5 (Continued) EMERGENCY ORGANIZATION CALL LIST

> > 10

SIMULATOR SUPERVISOR SUPT NUC TECH SERVICES TECH SUPPORT SUPV LEAD PROD ENGR

EXAMPLE ONLY USE ONLY COCOCIENT COEVISION

COMPLETED: DATE

TIME _____

SHIFT EMERGENCY COMMUNICATOR

PIN	GP	582.	Rev.	2

FIGURE 6 EMERGENCY NOTIFICATION FOLLOWUP MESSAGE*

<pre>TimeAM/PM 1. Location of incident: Prairie Island 2. Class of emergency:</pre>	Date					
2. Class of emergency:	Time		AM/P	1		
3. Type of release () actual or () potential: () aitborne () waterborne () surface spill 4. Current release data: Time:hours am/pm Release rate:µCi/sec Height of release-Ground level Relative% Quantity:% ParticulatesUCI/sec Estimated quantity of radioactive material leased or being released:WINDELEASE or 5. Meteorological Conditions: Wind Velocitymph . Wind Direction (from):degrees TemperatureoC Atmospheric Stability ClassForm of precipitation 6. Release is expected to continue forhours. 7. Dose Projections based on a release rate ofµCi/sec athours am/pm. Whole Body Thyroid Sectors Affected Projected dose rate S.Bmrem/hr at: 2 milesmrem/hr at: 2 milesmrem/hr mrem/hr mrem/hr integrated 2 milesmremmrem Do sel so contended on mrem integrated 2 milesmremmrem	1.	Locat	ion of incide	ent: Prairie Isl	and	
<pre>() airborne () waterborne () surface spill 4. Current release data: Time:hours am/pm Release rate:µCi/sec Height of release-Ground level Relative%</pre>	2.	Class	of emergency	/:		
4. <u>Current release data:</u> Time: hours am/pm Release rate: µCi/sec Relative % Quantity: % Relative % Particulates uCi/sec Unity: % Particulates uCi/sec Unity: % Particulates uCi/sec Uci/sec uCi/sec Durines uCi/sec Uci/sec uCi/sec Particulates uCi/sec Ding released: mph State mph Wind Direction (from): degrees Temperature °C Atmospheric Stability Class Form of precipitation 6. Release is expected to continue for hours. 7. Dose Projections based on a release rate of µCi/sec at hours am/pm. whole Body Thyroid Sectors Affected mem/hr mrem/hr mrem/hr dose rate S.8. mrem/hr mrem/hr mrem 10 miles mrem/hr mrem mrem mrem	3.	Туре	of release () actual or ()	potential:	
Time: hours am/pm Release rate: µCi/sec Height of release-Ground level uCi/sec Quantity: % % Particulates % Modescate % Modescate % Mole Body % mrem/hr <td></td> <td></td> <td>() airborne</td> <td>e () wate</td> <td>rborne () sur</td> <td>face spill</td>			() airborne	e () wate	rborne () sur	face spill
Relative %<	4.	Curre	<u>nt</u> release da	ita:	200	V. 3
Quantity:		Rel	ease rate:	µCi/	sec PLE ON	anon
Estimated quantity of radioactive mathematical problems of the properties of the problem of the properties of the problem of the properties of the propertie			and the second s			US uCi/sec
. Wind Direction (from): degrees Temperature °C Atmospheric Stability Class Form of precipitation 6. Release is expected to continue for hours. 7. Dose Projections based on a release rate of µCi/sec at hours am/pm. Whole Body Thyroid Sectors Affected Projected dose rate S.B mrem/hr mrem/hr at: 2 miles mrem/hr mrem/hr IO miles mrem/hr mrem/hr Projected S.B mrem/hr mrem/hr IO miles mrem mrem/hr integrated 2 miles mrem mrem dose at: 5 miles mrem mrem	5.	being	released:		SARAM	
Atmospheric Stability Class Form of precipitation 6. Release is expected to continue forhours. 7. Dose Projections based on a release rate ofµCi/sec athours am/pm. Whole Body Thyroid Sectors Affected dose rate S.Bmrem/hr at: 2 milesmrem/hr 5 milesmrem/hr mrem/hr 10 milesmrem/hr mrem/hr Projected S.Bmrem/hr 10 milesmrem/hr mrem/hr integrated 2 milesmrem 10 milesmrem mrem integrated 2 milesmrem 10 milesmrem mrem 10 milesmrem mrem 10 milesmrem mrem						
6. Release is expected to continue forhours. 7. Dose Projections based on a release rate ofµCi/sec athours am/pm. Whole Body Thyroid Sectors Affected dose rate S.B. mrem/hr mrem/hr at: 2 miles mrem/hr mrem/hr mrem/hr mrem/hr nomen/hr mrem/hr						
at	6.					
Projected S.B. mrem/hr mrem/hr at: 2 miles mrem/hr mrem/hr 5 miles mrem/hr mrem/hr 10 miles mrem/hr mrem/hr Projected S.B. mrem integrated 2 miles mrem dose at: 5 miles mrem	7.	Dose F at	rojections b	ased on a release rs am/pm.	rate of	µCi/sec
dose rate S.B. mrem/hr mrem/hr at: 2 miles mrem/hr mrem/hr 5 miles mrem/hr mrem/hr 10 miles mrem/hr mrem/hr Projected S.B. mrem integrated 2 miles mrem dose at: 5 miles mrem			Wh	ole Body	Thyroid	Sectors Affected
at: 2 miles mrem/nr mrem/hr 5 miles mrem/hr mrem/hr 10 miles mrem/hr mrem/hr Projected S.B. mrem integrated 2 miles mrem dose at: 5 miles mrem						
at: 2 miles mrem/ar mrem/hr 5 miles mrem/hr mrem/hr 10 miles mrem/hr mrem/hr Projected S.B. mrem integrated 2 miles mrem dose at: 5 miles mrem		rate	the second se	mrem/hr	mrem/hr	
5 miles mrem/hr mrem/hr 10 miles mrem/hr mrem/hr Projected S.B. mrem mrem integrated 2 miles mrem mrem dose at: 5 miles mrem mrem	at:		2 miles	mrem/ar	the second se	
Projected S.B. mrem mrem integrated 2 miles mrem mrem dose at: 5 miles mrem mrem			5 miles	mrem/hr	mrem/hr	
Projected S.B. mrem mrem integrated 2 miles mrem mrem dose at: 5 miles mrem mrem			10 miles	mrem/hr	mrem/hr	
integrated 2 miles mrem mrem mrem	Proje	cted	S.B.	mrom		
dose at: 5 milesmremmrem			August Law	the second se	In the second seco	
			the second se	Control of the second se	C - C - C - C - C - C - C - C - C - C -	
				and the second	arem	

*Complete as much of the form as information availability and time allows. All blanks need not be completed.

PINGP 582, Rev. 2

FIGURE 6 (Continued) EMERGENCY NOTIFICATION FOLLOWUP MESSAGE*

	urvey Results TIME	SURVEY POINT	READING	
1 1 1 1		-vP	MPLE ONLY MSE MSION	
Es	stimate of any surf	CRI	allanger light	n/100 cm
	nemical and physica			
Fo	or liquid release t ctivity and estimat	o the river, ed time for	estimate release volume, rele concentration to reach public	ase water:
Re	ecommended emergenc	y actions, i	ncluding protective actions:	
Re	equest for any need	ed support b	y offsite organizations:	

Emergency Director

ATTACHMENT A

TELEPHONE COMMUNICATIONS NETWORK

I. SITE TELEPHONE COMMUNICATIONS

1. Dimension 2000 PBX

Normal communications are provided by a Dimension 2000 PBX. Three separate Dimension PBX attendent consoles are used in the system. All have identical functions and only one can be operational at a time. For normal business hours, all incoming calls are answered by the receptionist located on the 5th floor of the Administration Building. During backshifts and weekends, the console at the secondary alarm station is activated. The third console, located in the Technical Support Center Communications area, shall be activated during emergency plan implementation.

The Dimension System controls approximately 265 main stations and 75 extensions. It is designed with a high degree of fault detection and diagnostic capabilities. Additional reliability is provided by a backup duplicate common control unit. If there are certain PBX failures or power failure, all stations would normally be inoperative. However, automatic operation of transfer relays in the emergency transfer panels bridge preassigned stations directly to the trunk lines. Assigned stations are located in control rooms, shift supervisors office, access control, administrative office, and technical support center. A key switch to manually cut over these preassigned stations is located within the telephone equipment room if the need exists.

Terminated within the Dimension System are 7 trunk lines and 7 tie lines. The trunk lines are 388-1121 through 1127, of which 388-1121 is incoming only, while 1122 through 1127 have incoming and outgoing capabilities. The seven two-way tie lines connect the Dimension 2000 PBX to the general office exchange via the NSP microwave relay system.

Normal power for the system is provided by an instrument inverter which in turn is supplied by a diesel backed 480 VAC safeguards motor control center and a 125 VDC station battery. An alternate source is provided by a 5KVA 480/120V transformer supplied by the 480 VAC diesel backed safeguards motor control center.

2. Gai-Tronics Page System

Gai-Tronics paging system is also available and is used to call personnel over the plant and yard speakers as well as to issue plantwide instructions from GTC stations located throughout the plant. This system is tied to the Dimension 2000 PBX, making access to the paging system possible from all telephone

F3-5 Rev. 10 Page 29

stations on site. Any one station tying up access to the paging system can be overridden with the executive override function from the operators console or the plant manager's office.

3. Phillips M100 Intercom System

Additional communication capability is provided by the Phillips M100 Intercom System. Stations are installed throughout the plant with a two digit number identifying its location.

4. Sound Powered Phone System

Sound powered phones are available for use within the plant and are primarily used for operations and maintenance coordination. Phone jacks are located throughout the Containment, Auxiliary Building, Turbine Building and Control Room.

II. TECHNICAL SUPPORT CENTER (TSC) TELEPHONE COMMUNICATIONS

1. Touch-A-Matic Dialer

The TSC Communications area is equipped with two automatic dialers. They function as a 31 name and number directory with an automatic memory. Numbers are programmed into the memory as labeled on the face plate. Both Touch-A-Matics are connected directly to an outside line. The memory button needs only to be depressed once to automatically dial the complete number.

Unit #1 has numbers preprogrammed for all the State and County Agencies, plus the EOF Coordinators and Engineers, Maintenance, Electrical, and I&C personnel required for notification procedures. Unit #2 is programmed for Operations Committee members and all the Health Physics personnel.

The last number manually dialed is autom ...cally recorded into the last number dialed position of the directory. Each number in this position is automatically replaced by the number previously manually dialed.

2. Dimension PBX Attendant Console

Located in the communications area, the console once activated has complete control of all incoming communications. The console is activated by calling the console in operation and instructing them to unplug the handset receiver.

Operating Console on backshifts and weekends - Secondary Alarm Station

Operating Console during normal working hours - Receptionist in Administration Bldg.

The TSC console is then made operational by plugging its handset into the board. At no time should two consoles be operated at the same time.

3. Stations, Extensions, and Hot Lines

Individual telephone communication from the TSC is provided for by fifteen separate plant stations with two extensions of these stations, four General Office extensions, and four Eau Clair FX lines. Three separate dedicated circuits (auto ringdown), are also available with points of connection as follows:

- TSC St. Paul State Capital EOC (REC Minn. Health Department)
- 2. TSC EOF (ED to EM)

3. TSC - EOF - (REC - RPSS)

The auto ring down is initiated by picking up the receiver. Ringing ceases when one other point picks up the line.

4. Phillips M100 Intercom

Two stations of the Phillips M100 intercom station are located in the TSC. One is in the Radiation Protection Area while the other is in the communications area.

5. Emergency Notification System (ENS)

The ENS is a leased private line between Prairie Island and the NRC Incident Response Center. The ENS is the primary means for reporting emergencies and other significant events to the NRC/IC Headquarters. When the NRC Operations Center is activated, the ENS becomes the dedicated line to the NRC for the transmission of operational data.

The ENS Red Phone, labeled (GPO 1504) is located in the Control Room, with extensions in the Technical Support Center, the near-site EOF and the NRC resident inspector's office. To activate the ENS line, proceed as follows:

 Lift receiver. This causes the telephone console in the Operation Center in Bethesda, Maryland to ring automatically.

F3-5 Rev. 10 Page 31

- (2) The NRC Duty Officer will answer.
- (3) Calmly identify yourself and give the NRC Duty Officer the required information.
- (4) Designate an individual to maintain continuous communication with the NRC staff member in the Operations Center until the NRC decides that the event has been successfully terminated or additional communication is unnecessary.
 - NOTE: If the incident has little potential for impacting the public health and safety, the NRC Duty Officer may only collect relevent information and then terminate the conversation. However, if the event is of a more serious nature, the Duty Officer will maintain an open and continuous line with the site until the matter is resolved.

6. Health Physics Network (HPN)

The Health Physics Network (HPN) is a leased, private line system which connects all the nuclear power plants, the NRC Operations Center, and the NRC Regional Office (Glen Ellyn).

It is primarily intended for use during emergencies and will function as the dedicated line between the Health Physics personnel, the Operations Center in Bethesda, MD and the NRC Regional Office.

In the event of a site emergency, the NRC will activate the HPN. Before NRC Health Physics specialists arrive on site, the NRC Operations Center communicator may request information from plant personnel.

NOTE: The HPN is a restricted network and may not be used by nongovernment employees at any time unless a significant event has to be reported and both the ENS and the commercial telephone lines are out of service.

F3-5 Rev. 10 Page 32

Extensions for the HPN are at the following locations:

- (1) HP Office
- (2) Technical Support Center
- (3) NRC Resident Inspector's Office

If necessary to use the HPN phone:

- (1) Lift receiver. NO DIAL TONE 1S HEARD.
- (2) Dial the required number:
 - 22 NRC Operations Center23 Region III Office

NOTE: a. There will be audible ringing signal dial tone after dialing the desired code. Ringing is heard at the called station to indicate an incoming call. This ring stops when the telephone is answered or at the end of thirty seconds. You may dial again if the call has not been answered in approximately 30 seconds.

> b. An automatic time-out period of six seconds is provided on the HPN to prevent a tie-up if only one digit has been dialed. This means that the desired code must be dialed within six seconds or the call will not complete.

7. National Warning System (NAWAS)

The National Warning System (NAWAS) is a private wire system provided by the Federal Government to disseminate emergency information of a National or International nature. The National Primary input location is the North American Air Defense (NORAD) Command Center in the Cheyenne Mountains, Colorado. There are over 2000 terminals on this system in federal, military and state designated locations.

The Wisconsin Division of Emergency Government (DEG) is responsible for maintaining a 24-hour statewide warning system as part of the National Warning System (NAWAS). The Prairie Island NAWAS is part of the Wisconsin State National Warning System. In Wisconsin, there are three (3) state warning centers. These warning centers have operational control over all terminals serving Wisconsin (including Prairie Island). This system is so designated that only the State Warning Point can communicate with terminals outside of Wisconsin. All terminals within Wisconsin

F3-5 Rev. 10 Page 33

are on a "Party Line" basis, in that any terminal talking on the circuit is heard by all other terminals on the Wisconsin circuit. In Wisconsin, NAWAS terminals are located at all seven district State Patrol Headquarters radio dispatch rooms and Area Emergency Government EOC's, 26 county warning centers, the five nuclear power plants and six U.S. Weather Station Offices. The State Patrol and county warning centers relay to and from the other 46 county non-NAWAS centers by radio.

The Prairie Island NAWAS talks directly to the State Warning Centers, the Weather Station Offices, and to the county sheriffs. The State Warning Centers and the county sheriffs further disseminate information to emergency organizations and personnel by other communications systems.

The state-wide emergency telephone number 608-266-3232 is the alternate communications backup for notification to the Wisconsin Division of Emergency Government.

THE FOLLOWING WILL BE USED IN THE EVENT AN INCIDENT AT PRAIRIE ISLAND REQUIRES A RESPONSE FROM STATE AND LOCAL AGENCIES:


- (1) DETERMINE THE CLASS OF EMERGENCY.
- (2) PICK UP THE NAWAS SET, PRESS TALK BUTTON AND SAY: "THIS IS PRAIRIE ISLAND NUCLEAR PLANT CALLING WISCONSIN WARNING CENTER ONE, WEST CENTRAL AREA WARNING CENTER AND PIERCE COUNTY WARNING CENTER, ACKNOWLEDGE."
- (3) WHEN WARNING CENTER ONE, WEST CENTRAL AREA AND PIERCE COUNTY WARNING CENTERS ACKNOWLEDGE, PRESS TALK SWITCH AND SAY: "PRAIRIE ISLAND NUCLEAR POWER PLANT IS EXPERIENCING A:

"NOTIFICATION OF UNUSUAL EVENT" (least serious); OR "ALERT"; OR "SITE AREA EMERGENCY"; OR "GENERAL EMERGENCY" (most serious) "RELAY THIS INFORMATION TO EMERGENCY GOVERNMENT IMMEDIATELY."

- NOTES: a) IF AREA OR COUNTY WARNING CENTERS DO NOT ACKNOWLEDGE, WISCONSIN WARNING CENTERS I, II, OR III WILL RING ON THE CIRCUIT AND RELAY THE MESSAGE TO APPROPRIATE WARNING CENTERS.
 - b) DUTY OFFICERS AND EMERGENCY GOVERNMENT OFFICIALS AT STATE AND LOCAL AGENCIES WILL INITIATE RESPONSE IN ACCORDANCE WITH CURRENT PLANS AND SOP'S.

NATIONAL WARNING SYSTEM


(NAWAS)



TELETYPE (TIME)

(ALL POINTS, EXCEPT MOBILES, INTERCONNECTED BY COMMERCIAL TELEPHONE)

F3-5 Rev. 10 Page 35



SUMMARY OF PRAIRIE ISLAND HOTLINE NETWORK

Number	Name	Station
1	Emergency Notification System (ENS)	Primary means for reporting emergencies and other significant events to the NRC Head- quarters in Bethesda, Maryland. The ENS phone is located in the Control Room with extensions in the TSC and EOF.
2	TSC - EOF(ED-EM)	2 point auto ring between the TSC and EOF. Either station can activate the circuit.
3	TSC-EOF (REC-RPSS)	2 point auto ring between the TSC and EOF. Each station can activate the circuit.
4	TSC - Minn State EOC	2 point ring on demand between the TSC and State EOC. Each station can activate the circuit.
5	Health Physics Network (HPN)	Multiple station line between the NRC and the plant. Extensions of the HPN are located in the TSC, at Access Control, and the EOF. This is a two digit ring telephone.
6	TSC - National Warning System (NAWAS)	Dedicated Line to Wisc. Warning Center I, II, and III, Regional Warning Center, and County Warning Center.

0

ATTACHMENT B RADIO COMMUNICATIONS NETWORK

I. MOTOROLA RADIO SYSTEM

This radio system is capable of being operated in either a normal (clear-uncoded) mode or in a private (Coded-digital voice protection) mode.

In the clear mode, all communications can be monitored by scanner receivers. In the coded mode, a standard receiver or scanner cannot monitor communications. In the coded mode, the audio quality is degraded due to the encoding/decoding process. This is a normal condition.

1. Motorola Radio Console


Three radio consoles provide the heart of the radio system. They are all identical with respect to function but not appearance. The consoles are located in the Control Room, TSC, and EOF. All contain the same channels and have an intercom feature between the consoles. Indication lights on the face of the console give the status of the transmitter/receiver mode, coded or clear operation.

Check the status lamp located beside the clear/coded switch on the control units. Operate it as necessary to put the system into the clear or coded mode.


All consoles are able to monitor the selected channel as well as the unselected channels. Independent volume controls are provided for both. Frequency 1 and frequency 2 are banded together and are one in the same. Call lights on the verticle portion of the console indicate which channel information is being received on. The second row of channel selection buttons on the TSC console are not connected.



.



CH1 (60 watt Simplex) Goodhue County EOC - Goodhue County Sheriff's office, Red Wing, MN Dakota County EOC - Dakota County Sheriff's office, Hastings, MN Pierce County EOC - Pierce County Sheriff's office, Ellsworth, WI CH2 (100 watt repeater) - 10 radiation monitoring team portables -F1 or F2. CH3 (100 watt repeater) - 10 plant portables - F1. CH4 (60 watt Simplex) - 20 security portables - F1 (primary freq) CH5 (60 watt Simplex) - 20 security portables - F2 (secondary freq) CH6 (60 watt Simplex) - Yard Portables CH7 - (60 Watt Simplex) - System Dispatcher (proposed) CH8 (12 watt Simplex) - Auxiliary Building F2 of the plant portables.



IBM

2. Motorola Portable Handie-Talkie (Model MX350)


- A. Special Instructions
 - (1) Do not separate battery pack from radio. This separation could cause loss of DVP feature and it would have to be recoded. The encoder and instructions are located in the communications area of the TSC if needed.
 - (2) Radios may be left in charger after full charge signal (green light) is on. You may leave volume turned "on" in charger; however, you must <u>never</u> transmit while radio is in the charger.
 - (3) External antenna jack located on "press to talk" switch side near the top of the radio provides an extended range when an antenna is used with this set. All Radiation Monitoring Team radios are provided with external antennas.
 - (4) A compatable headset is available for use with this portable. When connected to the headphone plug (on top of set) the headset earphones and microphone displaces the built in speaker and microphone. This accessory provides noise control when required.
- B. Radio Operation
 - (1) Knob on top marked F1 and F2 is a frequency selector switch. On the plant portables F1 works on CH3 of radio console and should be used in the Turbine Bldg and outplant areas. F2 works on CH8 of the radio console and should be used in the Auxiliary Bldg. The radiation monitoring portables have F1 and F2 banded together.
 - (2) -M_V- is the squelch control it should be positioned to just remove extraneous receiving noises.
 - (3) The knob marked Q (A) O provides a choice of the coded position (left), private line position (center) and clear position (right). To protect your messages, always use the coded position. <u>NEVER USE THE CENTER</u> <u>POSITION!</u>
 - (4) The red light on top will be on during transmitting. It is also a check for battery status. (Weak indicates low battery power.)
 - (5) Operate radio similar to other portables, using the 2" distance between mouth and the microphone grill, speak clearly, and say when your transmission is complete. Use reasonable volume and squelch.

IBM

ATTACHMENT B (Continued)

F3-5 Rev. 10 Page 39

ILLUSTRATION MOTOROLA PORTABLE HANDIE TALKIE MODEL MX350




.

0

F3-5 Rev. 10 Page 40

II. LOW BAND PAGING SYSTEM




PROCEDURE

 To contact the System Dispatcher: Select channel 7, key .ne microphone, and say: "PRAIRIE ISLAND TO SYSTEM DISPATCHER."

2. To contact the Minn. State EOC (See Note f): Select channel 7, key the microphone, and say: "PRAIRIE ISLAND TO EMERGENCY OPERATIONS CENTER."

NOTES: (a) The System Dispatcher can activate the receivers at the plant. Light alongside channel 7 will light and remain lit until reset.
(b) The plant can activate the receiver at the System Dispatcher and the HQEC (when connected).
(c) The state can activate the Prairie Island receiver.
(d) Each station can monitor each channel.
(e) The HQEC can activate the receiver at the plant.
(f) The State EOC must first be manned and the radio phone activated by the Duty Officer.

F3-5 Rev. 10 Page 41



GENERAL

The Radio Alert Monitor System is a one-way radio transmission system from the plant to the receiver. The transmitter is located in the onsite Technical Support Center with receivers installed in the homes and/or offices of the following three groups:

- 1. Local Residents
- 2. Civil Defense
- 3. Prairie Island Emergency Organization Personnel

The transmitter unit consists of: (a) message recorder; (b) message transmitter; (c) microphone; (d) telephone answering unit; (e) telephone; and (f) code selector.

When the Radio Alert Monitor System is activated, a tone will be heard by the receiver. The pre-recorded message will then be automatically played three times by the Alert Ridio Message Unit. Upon completion of the transmission, the pre-recorded tape is then placed into the telephone answering unit. If an individual is not home when the unit is activated, a red light on the receiver will indicate that a message has been transmitted via the Radio Alert System. That individual may then call the number indicated on his receiver (388-1233) and the pre-recorded tape will play the message over the phone.

Rev. 10 Page 42

F3-5

The microphone will allow plant personnel to transmit messages which are not detailed and pre-recorded.

The code numbers for the various receiver groups are:

- 1. Local Residents 01
- 2. Civil Defense 04
- 3. Prairie Island Emergency Organization Personnel 06

INSTRUCTIONS

The following details some of the various specific operating instructions:

- A. To Record a Message Cassette:
 - Make sure that the remote control unit 'Mike Enable' and 'Transmit Enable' key switches are both off (Green).
 - (2) Set tape unit selector switch to 'Record Announcement' insert microphone in tape unit mike jack.
 - (3) Press tape unit 'Start' switch and record the prepared message.
 - (4) When recording the message, speak slowly and clearly about 3 inches from the microphone.
 - (5) Set tape unit selector switch to 'Check Announcemenc' press 'Start' switch and listen to recording. (Adjust volume to desired level with tape unit 'Monitor Volume' Control) - if satisfactory, proceed.
- B. To Test Entire Alert Sequence:
 - (1) Insert proper recorded cassette in tape unit.
 - (2) Set tape unit selector switch to 'Answer'.
 - (3) Set up the desired two-digit group code on encoder Press 'P' (Page) button. Tones will be heard on the remote control unit. Adjust its volume control to the desired level.
 - (4) 18 seconds after the 2nd tone is heard, the 45 second recorded message will be heard 3 times. Then the unit will shut off.
- C. To Transmit an Alert Message:
 - Insert the proper recorded message cassette into the tape unit.

IBM

ATTACHMENT B (Continued)

F3-5 Rev. 10 Page 43

- (2) Set the tape unit selector switch to 'Answer'.
- (3) Turn the remote control unit 'Transmit Enable' key switch on. (Red 'XMIT' lamp will light.)
- (4) Set up the desired iwo-digit group code on encoder press 'P' (Page) button. If other groups are to be alerted to receive the same message, enter the next code or codes as soon as the preceeding tones have finished.

The rest of the sequence is automatic - several seconds after the last tone has been transmitted, the recorded message will be transmitted 3 times - then the system will shut off.

- (5) Now, remove the message cassette from the tape unit and insert it into the telephone answering unit.
- D. To Send a Live Microphone Transmission:
 - Turn the remote control unit 'Mike Enable' and 'Transmit Enable' key switches both on. (Red lamps will light.)
 - (2) Press 'Transmit' paddle on microphone and transmit desired message.
 - NOTE: (1) Any message sequence, recorded or live, can be aborted at any time simply by turning the remote control unit 'Transmit Enable' key switch off. (Green 'Test' lamp will light.)
 - (2) None of the volume controls on any of the units affect the volume of the transmitted message. They are for your convenience in monitoring the message.
 - (3) In case the automatic alert sequence has been inadvertantly started without a tape in the message unit, simply press the blue 'Reset' button on the alert radio message unit - insert the proper tape message, and start the sequence over.

	PAGE 1 OF 12		
PRAIRIE ISLAND NUCLEAR	EMERGENCY PLAN IMPLEMENTING PROCEDURES		
GENERATING PLANT NORTHERN STATES POWER COMPANY	Number: F3-6 Rev:		
	Retention Time: Lifetin		
Reviewed By: A. Schuelke Supt Rad Protection	TITLE:		
Approved By: Plant Manager	ACTIVATION AND OPERATION OF TECHNICAL SUPPORT CENTER		
OC Date: 9-25-84			

1.0 PURPOSE

The third floor of the Administration Building (First Floor Office Annex), is designated as the onsite Technical Support Center (TSC) and shall be used by plant management, technical and engineering groups, and NRC representatives as a center outside the main control room from which support for emergency operating conditions can be provided. The TSC shall be activated when an Alert, Site Area, or General Emergency is declared.

The purpose of this instruction is to describe the activation, staffing and monitoring requirements of the Technical Support Cencer.

2.0 APPLICABILITY

This instruction shall apply to all Shift Supervisors, Emergency Directors and all members of the technical staff.

- 3.0 PRECAUTIONS
 - All unnecessary personnel shall be evacuated from the Technical Support Center when the Technical Support Center has been activated.
 - (2) Monitoring of the Technical Support Center for direct radiation and airborne radioactive materials (particulate and iodine) shall be performed to ensure the habitability of the Technical Support Center.
 - (3) Protective actions for individuals located in the Technical Support Center shall be taken at the prescribed levels of direct radiation or airborne radioactivity.

F3-6 Rev. 4 Page 2

4.0 PROCEDURE

- 4.1 Activation & Operation of TSC
 - 4.1.1 Activation of the Technical Support Center shall occur whenever an Alert, Site Area or General Emergency is declared. Activation of the TSC may occur during normal work hours or during off-normal work hours:
 - (a) During normal work hours, the Technical Support Center shall automatically be activated whenever an Alert, Site Area, or General Emergency is declared, as announced over the public address system. All members of the Operations Committee and other designated engineers and staff members shall report to the TSC; or
 - (b) If activation of the Technical Support Center occurs during the off normal hours of the plant technical staff, the Emergency Director shall designate the Shift Emergency Communicator (SEC) to contact all Emergency Organization personnel, in accordance with F3-5.
 - 4.1.2 All non-essential personnel shall evacuate the TSC area, when the TSC has been activated.
 - 4.1.3 The Technical Support Center Coordinator shall:
 - (a) Designate an individual to establish monitoring of the TSC environment and take appropriate protective actions as specified in Section 4.2
 - (b) Designate an individual to maintain the Emergency Director's Log.
 - (c) Assume control of the Emergency Director phones.
 - (d) Ensure that the TSC doors are closed and initiate the TSC cleanup system, in accordance with Section 4.3.
 - (e) Issue, or designate an individual to issue dosimetry to all personnel in the TSC. Request all individuals to log their name, TLD # and dosimeter reading on PINGP #652, (Figure 3) Emergency Center Activation Exposure Record.

- F3-6 Rev. 4 Page 3
- (f) Designate engineers to establish telephone links at the TSC plant status board and in the Control Room, for purposes of plant status information transfer. The TSC communicator shall use Figure 4 (PINGP #653) to log plant status information.

NOTE: Telephone extensions, dedicated for the Control Room communicator are behind each respective unit computer console, at the corner of the SS Office.

- (g) Ensure that communications have been established between all on site emergency operating centers (Control Room, OSC and TSC area).
- (h) Designate an individual to operate the Data Recall System, as per F3-26.
- (i) Perform or designate an individual to assist the Emergency Director in the overall plant personnel accountability check, in accordance with F3-10. This should be delegated to the Supervisor Security and Services.
- (j) Establish appropriate office space in the TSC for all emergency organization personnel (NSP and non-NSP representatives). See Figure 2.
- (k) Interface with the non-NSP representatives located in the Technical Support Center and lend assistance where necessary.
- Inform the Radiological Emergency Coordinator of any significant changes in radiation levels or airborne activity. If habitability is of concern, request radiological surveys of the TSC. The REC should assume responsibility for establishing a routine sampling and monitoring program, as conditions permit.
- (m) Control the use of emergency equipment in the TSC emergency locker (protective clothing, respiratory equipment, dosimeters, potassium iodide pills, etc.).
- (n) Upon the Emergency Directors request, ensure key areas (e.g. Event Status, REC, etc) are prepared to conduct periodic briefings to update all personnel in the TSC of the current plant status.

(o) Update the TSC Status boards as necessary.

F3-6 Rev. 4 Page 4

- (p) When the Near-Site EOF has been activated, establish communications between the TSC and the EOF.
- 4.1.4 Additional personnel should be notified and requested to report to the Technical Support Center as deemed necessary.
- 4.1.5 As the emergency proceeds from the initial phase, (the period immediately following the emergency initiation) into the recovery phase, all Protective Actions for radiological hazards in the Technical Support Center shall be consistent with the plant Radiation Protection Program.
- 4.1.6 The Technical Support Center shall remain activated until the emergency situation has been terminated or as otherwise directed by the Emergency Director.
- 4.2 Radiological Monitoring
 - 4.2.1 Verify proper operation of the VAMP in the Technical Support Center:
 - (a) Verify the VAMP in the Tech Support Center.
 - (b) Verify or plug the VAMP in.
 - (c) Verify the white power light is on.
 - (d) If the VAMP fails (power loss, incorrect reading, etc.), contact the Radiation Protection Group for additional radiation monitors.
 - 4.2.2 The CAM is in a hot standby condition with the electronics energized and the blower, chart, and filter paper off.
 - (a) Turn the blower switch to the ON position (located next to the recorder) to start the blower, strip chart recorder, and the filter paper drive.
 - (b) Adjust the blower flow rate to 3 SCFM using the toggle switch located on the right side of the CAM.
 - (c) Verify the CAM is in operation (i.e., verify the blower, filter, strip charts are operating; meters are on scale, etc.).
 - (d) If the CAM fails to operate properly, contact the Radiation Protection Group for additional sampling.

- F3-6 Rev. 4 Page 5
- 4.2.3 Routinely monitor the VAMP and the CAM for direct radiation levels and airborne particulate and iodine activity.
- 4.2.4 Take the following Protective Actions based on readings from the VAMP or CAM.
 - (a) VAMP
 - (1) at about 15mR/hr consider evacuating all non-essential personnel from the Tech Support Center
 - (2) at 1 R/hr evacuation to the Control Room is recommended.
 - (b) CAM particulate
 - (1) $\langle 1 \times 10^{-9} \mu Ci/cc no protective action necessary$
 - (2) > 1 x 10⁻⁹ but < 1 x 10⁻⁶ µCi/cc consider use of respiratory protection and evacuation of all unnecessary personnel.
 (3) > 1 x 10⁻⁶ µCi/cc evacuation to the
 - Control Room is recommended.
 - (c) CAM Iodine (See Figure 1)
 - (1) at 40 MPC hours consider evacuation of all unnecessary personnel
 - (2) at 200 MPC hours consider evacuation to the Control Room

NOTE: The Radiological Emergency Coordinator (REC) should recommend the use of potassium iodide pills (thyroid blocking agent) if the projected thyroid exposure approaches 25 Rem.

F3-6 Rev. 4

Page 6

4.3 TSC Ventilation System

- 4.3.1 System Startup
 - (a) Close or ensure the TSC doors are closed.
 - (b) At the TSC Control Panel, turn ES-82601 from "NORMAL" to "EMERGENCY".
 - (c) Check the following indications at the TSC Control Panel (refer to Figure 5, TSC Clean-up System):
 - (1) Filter Unit Trouble Light (Red light should be OFF).
 - (2) The TSC Return Fan Stops and the Clean Up Unit Fan should start (Red "ON" Light should be lit).
 - (3) Outside Air Isolation Damper (MD-34602) should close (Green "CLOSE" light should be lit).
 - (4) Return Fan Isolation Damper (MD-34603) should close (Green "CLOSE" light should be lit).
 - (5) Outside Air Volume Control Damper (MD-34604) should modulate open (Red "MODULATE" light should be lit).
 - (6) Clean Up Unit Volume Control Damper (MD-34605) should modulate open (Red "MODULATE" light should be lit).
 - (7) In the "EMERGENCY" mode, the TSC should be at a positive pressure of approximately 0.125 inches W.G. as indicated by TSC Positive Pressure Gauge 82608.
 - (d) The TSC air temperature may rise for a period of time following startup. Several hours are necessary to cool the system down and subsequently again cool the TSC.

4.3.2 Trouble Alarm

- (a) The Filter Unit Red Trouble light will be lit if the following occurs:
 - TSC Cleanup Unit Fan Differential Pressure Lo (DPIS-82321).
 - Prefilter Differential Pressure Hi (DPIS-82331).

0

- (3) 1st HEPA Filter Differential Pressure Hi (DPIS-82332).
- (4) Charcoal Filter Differential Pressure Hi (DPIS-82333).
- (5) 2nd HEPA Filter Differential Pressure Hi (DPIS-82334).


IBM

F3-0 Rev. 4 Page 7

(B) If the above alarm should be lit, investigate the local dp filter indications. The filters may require changing.

4.3.3 System Shutdown

- (a) At the TSC Control Panel, turn ES-82601 from "EMERGENCY" to "NORMAL".
- (b) Check the following indications at the TSC Control Panel (refer to Figure 5, TSC Clean-up System):
 - Filter Unit Trouble Light (Red light should be OFF).
 - (2) The TSC Return Fan Stops and the Clean Up Unit Fan should start (Green "OFF" light should be lit).
 - (3) Outside Air Isolation Damper (MD-34602) should open (Red "OPEN" light should be lit).
 - (4) Return Fan Isolation Damper (MD-34603) should open (Red "OPEN" light should be lit).
 - (5) Outside Air Volume Control Damper (MD-34604) should close (Green "CLOSE" light should be lit).
 - (6) Clean up Unit Volume Control Damper (MD-34605) should close (Green "CLOSE" light should be lit).






FIGURE 2

Rev. 4 Page 9

TECHNICAL SUPPORT CENTER

100

F3-6 Rev. 4 Page 10

-

PINGP 652, Rev. 0 Page 1 of 1 Retention: Lifetime

1

FIGURE 3


NAME	I TLD NO.	DOSIMETER READINGS	NET
			-
		OHLY	
	- AMPLE	ONLY STOL	
	E day (1)	AT BIES	
	Collin	 	
			-

EMERGENCY CENTER ACTIVATION EXPOSURE RECORDS

		EVEN	NT STAT.		PINGP é Rev. 1 Page 1 Retenti		
PRA	RIE ISLAND UNIT #	TIME	-	NOTE:Indicate	s Parameter Not	Updated	
RCS	PARAMETERS		NSSS	LOOP PARAMETERS		LOOP	
					A	В	
1.	RCS Pressure	psi;	g 1.	Wide Range T _h (^o F)			
2.	Trend	UP/DOWN/STABLE	2.	Wide Range T _c (^o F)			
3.	Pressurizer Level	%	▲ ^{3.}	Incore Thermocouples (^o			
4.	Trend	UP/DOWN/STABLE	C4 4.	Subcooling Margin (^o F/p	si)		
5.	Pressurizer Heaters	ON/OB	90	RCP Status (ON/OFF)			
RCS	MAKE UP FLOW STATUS	(je)	190	S.G. Pressure (psig)			
1.	SI, Flowrate	ON/OFF,	n	Trend (UP/DOWN/STABLE)			[;
2.	RHR, Flowrate	ON/OFF,	A R	S.G. Level, Wide Range	(%)	_	
3.	RWST Level	%	a fra	Level, Narrow Rang	e (%)		
4.	Normal Charging, Flowrat	te ON/OFF,gpm <	12 10.	Tree (UP/DOWN/STABLE)			
5.	Letdown, Flowrate	ISOLATED,gpm	50011.	MSIV Status (OPEN/CLOSE	.D)		
6.	Accumulators	psig	B	AUX Feedwater Flow (gpm	ı)		
CONT	CAINMENT PARAMETERS		· Le	Condensate Storage Tank	Lv1 (%)		
1.	Containment Press/Temp	psig°F	MM	PARAMETERS			
2.	Containment Rad Level		1.	Diesel Generators	ON/OFF		
3.	Sump B Level	%	2.	Offsite Power	YES/NO		
4.	Hydrogen Concentration	%	3.	CC Normal	YES/NO		
5.	Containment Spray	ON/OFF, gpm	4.	CL Normal	YES/NO		
6.	FCU	ON/OFF			TRAIN A	TRAIN B	Rev. Page
COMP	TENTS		5.	Shield Building Vent	ON/OFF	ON/OFF	e 11
			6.	AUX Building Special	ON/OFF	ON/OFF	-
			7.	Control Room Special	ON/OFF	ON/OFF	
			8.	Spent Fuel Special	ON/OFF	ON/OFF	

FIGURE 4

F3-6



a month

	PAG	E 1 OF 9	
PRAIRIE ISLAND NUCLEAR	EMERGENCY PLAN IMPLEMENTING PROCEDURES		
GENERATING PLANT NORTHERN STATES POWER COMPANY	 Number: F3-10	Rev: 5	
	Retention Time:	History Copy Lifetime	
Reviewed By: D.A. Schuelk	TITLE:		
Approved By: Plant Manager	PERSONNEL ACCOUNTABILITY		
O.C. Date: 9-25-84			

1.0 PURPOSE

The Instruction SHALL delineate the procedure to perform the personnel accountability check within the Protected Area, following a plant evacuation.

2.0 SUMMARY

0

In the event of a plant evacuation, the personnel accountability check within the Protected Area should be completed within thirty (30) minutes following the evacuation to allow an orderly search for missing personnel. The Emergency Director is responsible for the completion of this personnel accountability and may delegate this authority to the Guard Force and the respective Coordinators at each of the emergency operating centers. All personnel accountability results SHALL be forwarded to the Emergency Director.

3.0 APPLICABILITY

THIS INSTRUCTION SHALL APPLY TO ALL PLANT PERSONNEL.

4.0 PRECAUTIONS

- All individuals remaining in the Protected area following a plant evacuation SHALL be verified by a direct contact (either in person or verbally) and their location, name and badge # recorded on the personnel accountability sheet Figure 1 (PINGP #601).
- (2) The Emergency Director should ensure that this instruction is completed.

- (3) When the initial accountability is completed, access to the Protected Area shall require coordination between the Emergency Director, Radiation Protection Group, and the Supervisor Security and Services to ensure an ongoing personnel accountability exists throughout the duration of the emergency situation.
- (4) To ensure a continuous personnel accountability, an accountability check should be completed once per shift (every 8 hours) or when requested by the Emergency Director (See Step 5.12).

5.0 PROCEDURE

- 5.1 During an evacuation, all nonessential personnel SHALL proceed to the designated assembly area.
 - NOTE: The designated assembly area may be either the Screenhouse or the Construction Office Building. Listen for instructions over the public address address system prior to evacuating.
- 5.2 As soon as the evacuation alarm sounds, the CAS operator SHALL type EEV (Emergency Evacuation) into the security computer to activate the OSC, TSC and the Screenhouse accountability card readers.
- 5.3 As soon as the evacuation alarm sounds, all personnel in the TSC and OSC SHALL insert or ensure that their badges are inserted into the TSC or OSC card readers.
- 5.4 As soon as all OSC personnel have inserted their badges into the OSC card reader, the OSC Coordinator should inform the Supervisor Security and Services in the TSC.
- 5.5 When it has been verified that all badges (OSC and TSC) have been inserted into the card readers, the Supervisor Security and Services shall then cause the accountability report to be run.
- 5.6 The OSC Coordinator should:
 - 5.6.1 Designate an individual to perform a Control Room Accountability, listing all Control Room Personnel and out plant operators on Figure 1 (PINGP #601).
 - 5.6.2 Ensure that the Control Room Accountability sheet, PINGP #601 is transferred to the Supervisor Security and Services in the TSC, as soon as it is completed.

IBM

- 5.7 Actions Of Personnel Evacuating The Plant Shall Be As Follows:
 - 5.7.1 If the Construction Office Building is the designated assembly point:
 - All Personnel Shall evacuate via the Guard House or as designated by the Security Force.
 - (2) All Personnel Shall give their badge to the Security Force member as they exit the protected area.
 - (3) All Personnel Shall proceed to the Construction Office Building and assemble in the designated areas, as indicated (See Figure 2).
 - 5.7.2 If The Screenhouse Is The Designated Assembly Point:
 - All Personnel Shall evacuate the plant and enter the Screenhouse through the east door.
 - (2) All Personnel Shall file through the Screenhouse, as indicated on Figure 3, and insert their badge into the Screenhouse Accountability Card Reader.

CAUTION: Do not insert badge into the card reader outside the Screenhouse east door.

(3) After each badge has been inserted into the Screenhouse Accountability Card Reader, all Personnel Shall follow the assembly route (See Figure 3) and proceed to the Accountability Holding Area.

CAUTION: Do not exit the Screenhouse until instructed.

F3-10 Rev. 5 Page 4

5.8 The Security Force action SHALL be as follows:

- 5.8.1 If the Construction Office Building is the designated assembly point, the Security Force action SHALL be as follows:
 - (a) The Security Force shall collect all badges from personnel as they leave the protected area via the Guard House.

NOTE: Evacuating personnel need not stop at the Portal Monitor in the Guard House or at Access Control.

- b. The Security Force SHALL insert all badges into the two (2) Guard House exit card readers as soon as possible.
- c. As soon as all badges (evacuated personnel, OSC personnel and TSC personnel) have been inserted into the card readers, the Security Shift Supervisor should obtain a list of unaccounted personnel from the security computer by typing in EVACNT (Evacuation Accountability).
- NOTE: This unaccounted personnel list includes missing personnel and those who have not inserted their badges into the card readers, e.g., Control Room Operators | and out plant operators.
 - (d) As soon as the "Unaccounted Personnel List" is generated, the Security Force SHALL bring this list to the Supervisor Security and Services in the TSC.
- 5.8.2 If the Screenhouse is the designated assembly point, the Guard Force action SHALL be as follows:
 - (a) The Security Force SHALL proceed to the Screenhouse to assist in the evacuation and accountability.
 - (b) The Security Force SHALL ensure that all personnel evacuating insert their badges into the accountability card reader.
 - (c) The Security Force SHALL ensure all personnel proceed to the accountability holding area.

F3-10 Rev. 5 Page 5

- (d) As soon as all badges have been inserted into the screenhouse accountability card reader, the Security Officer posted at the screenhouse assembly point Shall notify the security shift supervisor (Ext. 324).
- (e) As soon as all badges (evacuated personnel, OSC personnel and TSC personnel) have been inserted into the card readers, the security shift supervisor should obtain a list of unaccounted personnel from the security computer by typing in EVACNT (Evacuation Accountability).

NOTE: This unaccounted personnel list | includes missing personnel and those | who have not inserted their badges into the card readers, e.g., Control Room Operators | and out plant operators.

- (f) As soon as the "Unaccounted Personnel List" is generated, the Security Force SHALL bring this list to the Supervisor Security and Services in the TSC.
- 5.9 The Supervisor Security and Services, or designee shall then compare the "Unaccounted Personnel List" with the "Emergency Operating Center Personnel Accountability Check", Figure 1 (PINGP Form #601), to determine if all personnel are accounted for.
- 5.10 If all personnel are not accounted for, re-check all Emergency Operating Centers, the Guard House and the applicable assembly point for missing personnel.
- 5.11 If all personnel cannot be accounted for, the Emergency Director SHALL initiate a search for missing personnel, in accordance with F3-11, "Search and Rescue".
- 5.12 Once each shift (every 8 hours) or when requested by the Emergency Director, a personnel accountability check onsite should be conducted as follows:
 - 5.12.1 The Supervisor Security and Services shall request the CAS Operator (Ext. 318) to activate the OSC and TSC card readers. The CAS operator SHALL then type EEV (Emergency Evacuation) into the security computer.
 - 5.12.2 All personnel in the TSC and OSC SHALL then insert their badges into the TSC and OSC card readers.


- 5.12.3 As soon as all OSC personnel have inserted their badges into the OSC card reader, the OSC Coordinator should inform the Supervisor Security and Services in the TSC.
- 5.12.4 When it has been verified that all badges (OSC & TSC) have been inserted into the card readers, the Supervisor Security and Services shall then cause the accountability report to be run.
- 5.12.5 The OSC Coordinator should:
 - (a) Designate an individual to perform a Control Room Accountability, listing all Control Room. Personnel and out plant operators on Figure 1 (PINGP #601).
 - (b) Ensure that the Control Room Accountability Sheet, PINGP #601, is transferred to the Supervisor Security and Services in the TSC, as soon as it is completed.
- 5.12.6 As soon as all OSC and TSC personnel have inserted their badges into the card readers, the Security Shift Supervisor should obtain a list of unaccounted personnel from the security computer by typing in EVACNT (Evacuation Accountability).
 - NOTE: This unaccounted personnel list includes missing personnel and those who have not inserted their badges into the card readers, e.g., Control Room operators and out plant operators.
- 5.12.7 As soon as the "Unaccounted Personnel List" is generated, the Security Force SHALL bring this list to the Supervisor Security and Services in the TSC.
- 5.12.8 The Supervisor Security and Services or designee shall then compare the "Unaccounted Personnel List" with the "Emergency Operating Center Personnel Accountability Check", Figure 1 (PINGP Form #601), to determine if all personnel are accounted for.
- 5.12.9 If all personnel are not accounted for, re-check all Emergency Operating Centers and the applicable assembly point for missing personnel.
- 5.12.10 If all personnel cannot be accounted for, the Emergency Director SHALL initiate a search for missing personnel, in accordance with F3-11, "Search and Rescue".

IBM


F3-10 Rev. 5 Page 7

PINGP #601, Rev. 0

FIGURE 1



Completed by :



and there are a service

CONSTRUCTION OFFICE BUILDING EVACUATION ASSEMBLY POINT PLAN

FIGURE 2

₽N

in the stands in the

IBM

the state of

F3-10 Rev. 5 Page 8


۴

F3-10 Rev. 5 Page 9

f.

ŧ

1.4 . .



(

	PAG	E 1 OF 3	
PRAIRIE ISLAND NUCLEAR	EMERGENCY PLAN IMPLEMENTING PROCEDURES		
GENERATING PLANT NORTHERN STATES POWER COMPANY	 Number: F3-29	Rev: 2	
	 Retention Time:	History Copy Lifetime	
Reviewed By: D.A. Schuelke	- TITLE:		
Approved By: Plant Manager	EMERGENCY SECURITY PROCEDURES		
OC Date: 9-25-84	-		

1.0 PURPOSE

The purpose of this instruction is to delineate the responsibilities of the Security Force during emergency conditions at Prairie Island.

2.0 APPLICABILITY

This instruction shall apply to all members of the plant Security Force.

3.0 DISCUSSION

All security requirements shall be in accordance with the Prairie Island Nuclear Generating Plant Security Plan and the Guard Force Section Work Instructions.

4.0 PRECAUTIONS

- 4.1 Prairie Island security officers shall not make any information releases to members of the news media or the public. All inquiries by the news media shall be directed to the NSP Communications Department at NSP Headquarters or at the Joint Public Information Center (JPIC) located at the Minnesota State Capitol in St. Paul.
- 4.2 Various plant personnel are required to report to Onsite Emergency Operating Centers during plant emergencies. Due regard for plant conditions as well as maintaining security of the plant should be considered to expedite allowing these key personnel entrance to the Protected Area and Vital areas during emergencies.
- 4.3 All Security Force members shall obtain and zero a O-1R dosimeter at the beginning of each shift. During emergency conditions, the Security Officers should periodically, or when requested, read their dosimeters.

5.0 PROCEDURE

- 5.1 During an emergency, all Security Officers shall continue with their normal duties, unless directed otherwise.
- 5.2 When requested by the Shift Emergency Communicator (SEC), a Security Force member shall be designated to proceed to the Technical Support Center (TSC) to control the telephone switchboard. This Security Officer shall control the switchboard until relieved by a backup communicator or the emergency situation is terminated.
- 5.3 When the evacuation alarm sounds:
 - 5.3.1 All Security Officers, with the exception of the SAS Operator shall evacuate to the guardhouse for further instructions.

NOTE: The SAS Operator should evacuate when directed by the Emergency Director.

- 5.3.2 The Security Force shall assist in the evacuation of personnel to the designated assembly point, which will normally be the Construction Office Building.
 - NOTES: (1) To speed evacuation from the Protected Area, it may be beneficial to open the vehicle gates and allow personnel to exit there.
 - (2) It will not be necessary to require personnel to stop at the portal monitors. Collect all ID badges and process badges so an early printout of personnel remaining within the Protected Area can be obtained.
- 5.3.3 If the evacuation of personnel is via some route other than through the guardhouse, instruct personnel of the designated evacuation point and control access via this exit as per the Guard Force Section Work Instructions.
- 5.3.4 Perform a check of all areas immediately surrounding the Protected Area so that all personnel are notified of the evacuation in progress by having the patrol guards:

F3-29 Rev. 2 Page 3

- Make continuous inside rounds with the patrol vehicle, especially on the South and East side of the plant, using the loudspeaker in the patrol vehicle, if necessary, to ensure all people are following directions of the Emergency Director; and
- (2) Survey all trailers, warehouses and out buildings, to ascertain that all persons are aware of and follow the directions of the Emergency Director.
- 5.4 The Security Force shall assist in the personnel accountability, as per F3-10, "PERSONNEL ACCOUNTABILITY", and the Guard Force Section Work Instructions.
- 5.5 When the initial accountability is complete, access to the Protected Area shall require coordination between the Emergency Director, Radiation Protection Group and the Supervisor Security and Services or designee to ensure an ongoing personnel accountability exists throughout the duration of the emergency condition.
- 5.6 An accountability check should be completed once per shift (every 8 hours) to ensure a continuous personnel accountability, or when requested by the Emergency Director.
- 5.7 The Security Force shall make all attempts to expedite entrance to the Protected Area by Emergency Organization personnel.

NOTE: The Security Force shall consider plant conditions as well as plant security.

- 5.8 When requested by the Emergency Director or the Radiation Protection Group, the Security Force should assist the Radiation Protection Group in establishing and controlling a Secondary Access Control Point, in accordance with F3-21, "Establishment of a Secondary Access Control Point".
- 5.9 The Security Force should assist the Assembly Point Coordinator in personnel accountability, crowd control, and traffic control.
- 5.10 During an Alert, Site Area, or General Emergency, the Security vehicle should be positioned at the plant entrance, if conditions permit, or at an alternate location, to control access to the plant site.

Jim Melhight - No Decemons REQUIRED -- NONE REGRESTED Apoument Comrol -Cleanit give for and me for the