Monthly Operations Report May, 1984 Page Five

(SRDCO 84-33)

.

D. CHANGES, TESTS AND EXPERIMENTS CARRIED OUT WITHOUT COMMISSION APPROVAL (Continued)

System Acceptance Committee Packages for May, 1984: (Continued)

Package Description/Analysis

EEAR FC-83-159 Steam Generator A Rim Cut No. 8 Support Plate. (SRDC0 84-32)

> This modification provided for removing the outer rim and lugs of the No. 8 drilled tube support plates in the steam generator. Such a design change would provide stress relief for the plates such that cracking of the plates in the peripheral (rim) region will be prevented. This modification has been reviewed by the NSSS supplier. This modification has no adverse effect on the safety analysis.

EEAR FC-83-159 Steam Generator B Rim Cut No. 8 Support Plate.

This modification provided for removing the outer rim and lugs of the No. 8 drilled tube support plates in the steam generator. Such a design change would provide stress relief for the plates such that cracking of the plates in the peripheral (rim) region will be prevented. This modification has been reviewed by the NSSS supplier. This modification has no adverse effect on the safety analysis.

EEAR FC-81-99 Installation of Heated Junction Thermocouple (HJTC) Part 14 Handling Canister Mounting Bracket and Assembly of HJTC Handling Canisters.

> This modification provided for the assembly and installation of the HJTC handling canister mounting bracket and handling canisters. This modification has no adverse effect on the safety analysis.

EEAR FC-82-96 Auxiliary Building Room 4A Ventilation.

This modification provided for additional ventilation duct in Room 4A. This modification has no adverse effect on the safety analysis.

8502210236 850213 PDR ADOCK 05000285 R PDR