

Jersey Central Power & Light Company



MADISON AVENUE AT PUNCH BOWL ROAD • MORRISTOWN, N. J. 07960 • 201-539-6111

MEMBER OF THE

General



Public Utilities Corporation

November 1, 1974

Mr. Walter G. Martin, Chief
Materials and Plant Protection Branch
Directorate of Regulatory Operations
Region 1
United States Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Martin:

Subject: Oyster Creek Station
Docket No. 50-219
Inspection No. 74-15

On September 26 and 27, 1974, Mr. Partlow conducted an inspection of the program for control of special nuclear material at the Oyster Creek Nuclear Generating Station. He found that approximately twelve (12) fuel pins, each containing SNM, had not been inventoried since January 5, 1973. This is in violation of 10 CFR 70.51 (d) which requires that the inventory intervals not exceed twelve months.

There were thirteen (13) fuel pins that had not been inventoried since January 5, 1973. This situation was corrected by completing an inventory of these pins on October 24, 1974. Documentation of this inventory has been filed.

To avoid future violations, the failed pin storage baskets at the New Fuel Storage Vault will be included on the fuel pool inventory map to insure that these locations are not overlooked during the inventory.

Very truly yours,

Donald A. Ross
Manager, Generating Stations-Nuclear

CS