



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION 1
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

yellow
V-2 P

JUN 13 1974

Memo to Docket
File 50-219-Oyster Creek

TELEPHONE CALL TO KARL SEYFRIT, HEADQUARTERS (DAN POMEROY)

I telephoned Karl Seyfrit who was on vacation and being relieved by Dan Pomeroy, to discuss the transfer of the lead responsibility to Licensing concerning the problem at Oyster Creek, a leak at an instrument penetration in the reactor bottom head. Mr. Pomeroy stated that the transfer of lead responsibility had been made to Licensing. Upon further questioning it was determined that Licensing had not signed the copy of the transfer responsibility. Mr. Pomeroy subsequently pursued the matter and called back at about 1:30 p.m. to confirm that Licensing had not received the transfer of lead responsibility for the subject matter. Mr. Pomeroy read the document that he had and the RO recommendations listed were discussed. Eased on this discussion, Mr. Pomeroy agreed to revise the Item 1 of the recommendations that he had and proceed to discuss the changes with Mr. Goller in the Directorate of Licensing. Mr. Pomeroy further agreed to call me back and state the conclusions of the discussions and provide a status of the transfer.

D. L. Capton
Senior Reactor Inspector
Facilities Operation Branch

cc: E. J. Brunner

B/S 11