FEB 2 0 1985

DOCKET/LICENSE: 50-219/DPR-16

GPU Nuclea Corporation ATTN: Mr. P.B. Fiedler

Vice President and Director

Oyster Creek Nuclear Generating Station

P. O. Box 388

Forked River, New Jersey 08731

Gentlemen:

Subject: Inspection 50-219/84-34

This refers to the routine resident safety inspection by Messrs. W. Bateman and J. Wechselberger on Nov. 18 - Dec. 31, 1984 at the Oyster Creek Nuclear Generating Station, Forked River, New Jersey. The inspection consisted of document reviews, interviews, and observation of activities. The findings were discussed with you and other members of your staff at the conclusion of the inspection.

As a result of a drywell entry on November 23, it became apparent that the Oyster Creek operating and radiological control procedures did not adequately address the plant conditions necessary to conduct the entry in that the prerequisites needed to safely and effectively conduct the plant evolution were not clearly specified and the procedure that specifically governs plant evolutions was not appropriately referenced. This apparent violation of NRC requirements is cited in Appendix A and categorized under the NRC Enforcement Policy 10 CFR 2 Appendix C (49 FR 8583, March 8, 1984). A reply is required and should be prepared in accordance with Appendix A.

Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:

Harry B. Kister, Chief Projects Branch No. 1 Division of Reactor Projects

Enclosure:

1. NRC Region I Report 50-219/84-34

8502250653 850220 PDR ADOCK 05000219

> 50-219/84-34 - 0001.0.0 02/15/85

cc w/encl:
BWR Licensing Manager
Licensing Manager, Oyster Creek
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of New Jersey

bcc w/encl:
Region 1 Docket Room (with concurrences)
Senior Operations Officer (w/o encl)
Director, DRS
Director, DRSS
DRP Section Chief

RI: DRP V: Bar demonstration 2/6/85 RI-DRP E. Confident 2/15/85 RI:DRP H.Kister 2//5/85

OFFICIAL RECORD COPY

50-219/84-34 - 0002.0.0 02/15/85