APPENDIX A

NOTICE OF VIOLATION

GPU Nuclear Corporation
Oyster Creek Nuclear Generating Station

Docket No. 50-219 License No. DPR-16

As a result of the inspection conducted on Nov. 18 - Dec. 31, 1984, and in accordance with the revised NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 8, 1984 (49 FR 8583), the following violation was identified:

Paragraph 6.8.1 of the Oyster Creek Technical Specifications requires that written procedures shall be established, implemented, and maintained.

Paragraph 3.12 of Oyster Creek Radiological Control Procedure 902.5 states that prior to making a containment entry, sufficient control rods shall be inserted so that the GSS can verify the reactor is subcritical and power level is decreasing.

Contrary to the above, on November 23, 1984, a containment entry was made without first inserting control rods to make the reactor subcritical and verify decreasing power level.

This is a Severity Level IV Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, GPU Nuclear Corporation is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending your response time.