

SUPPLEMENTAL REPORT TO DIR/LER

DVR NO.
STA UNIT YEAR NO.
D- 12 - 2 - 83 - 121

PART 1	TITLE OF EVENT	OCCURRED	
	Inboard MSIV 203-1B Double Indication	<u>8-30-83</u>	<u>0040</u>
		DATE	TIME
REASON FOR SUPPLEMENTAL REPORT			
Supplemental report issued to document actions taken when final repairs were implemented.			
PART 2			
	ACCEPTANCE BY STATION REVIEW	<u>J. Brunner, M. Allen</u>	
	DATE	<u>2/4/85</u>	<u>2/4/85</u>
	SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas Scott</u>	<u>2/4/85</u>
		STATION SUPERINTENDENT	DATE



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

February 4, 1985

DJS Ltr. #85-124

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #83-63/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation. This supplemental report is being submitted to delineate actions taken when final repairs were implemented.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJSjmt

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

IE22
1/4