

POST OFFICE BOX 2951 · BEAUMONT, TEXAS 77704


AREA CODE 713 838 6631

October 24, 1984 RBG- 19260 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-218



An interim or final status report concerning the piston rods in Brown Boveri Electric type SHK circuit breaker will be provided by December 13, 1984.

Sincerely,

fu J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PDD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8411120100 841024 PDR ADDCK 05000458 PDR IE-27 10