

UNITED STATES NUCLEAR REGULATORY COMMISSION

luber

REGION III 801 WARRENVILLE ROAD USLE, ILLINOIS 60532-4351 April 9, 1996

Mr. E. Watzl, Vice President Nuclear Generation Northern States Power Company 414 Nicollet Mall Minneapolis, MN 55002

SUBJECT: NRC INTEGRATED INSPECTION REPORT NO. 50-263/96002(DRP)

Dear Mr. Watzl:

Enclosed are the results of our inspection conducted by A.M. Stone and others of this office on January 17 through February 26, 1996. The inspectors reviewed activities authorized for your Monticello Nuclear Station. The purpose of the inspection was to determine whether activities authorized by your licenses were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the inspectors discussed their findings with members of your staff.

You should note that this inspection report represents an integrated product of a number of diverse inspections that were conducted during the inspection period. The summary contained in the report provides an overview of our assessment of your performance in the four functional areas (Operations, Maintenance, Engineering, and Plant Support) in which inspections were performed.

No violations of NRC requirements were identified. Operations personnel performed well during infrequent evolutions. Maintenance activities were conducted well with one exception where a breached security barrier was unattended. Engineering personnel identified a discrepancy in the Updated Safety Analysis Report with regards to the fuel pool cooling requirements. Management support to emergency preparedness was evident.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

250014

9604250255 960409 PDR ADOCK 05000263 Q PDR E. Watzl

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Solling

M. J. Jordan, Chief Reactor Projects Branch 7

-

Docket No. 50-263

Enclosure: Inspection Report No. 50-263/96002(DRP)

cc w/encl: Plant Manager, Monticello John W. Ferman, Ph.D., Nuclear Engineer, MPCA State Liaison Officer, State of Minnesota April 9, 1996

Mr. E. Watzl, Vice President Nuclear Generation Northern States Power Company 414 Nicollet Mall Minneapolis, MN 55401

SUBJECT: NRC INTEGRATED INSPECTION REPORT NO. 50-263/96002(DRP)

Dear Mr. Watzl:

Enclosed are the results of our inspection conducted by A.M. Stone and others of this office on January 17 through February 26, 1996. The inspectors reviewed activities authorized for your Monticello Nuclear Station. The purpose of the inspection was to determine whether activities authorized by your licenses were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the inspectors discussed their findings with members of your staff.

You should note that this inspection report represents an integrated product of a number of diverse inspections that were conducted during the inspection period. The summary contained in the report provides an overview of our assessment of your performance in the four functional areas (Operations, Maintenance, Engineering, and Plant Support) in which inspections were performed.

No violations of NRC requirements were identified. Operations personnel performed well during infrequent evolutions. Maintenance activities were conducted well with one exception where a breached security barrier was unattended. Engineering personnel identified a discrepancy in the Updated Safety Analysis Report with regards to the fuel pool cooling requirements. Management support to emergency preparedness was evident.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

E. Watzl

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

/s/Stevie DuPont for

M. J. Jordan, Chief Reactor Projects Branch 7

Docket No. 50-263

Enclosure: Inspection Report No. 50-263/96002(DRP)

cc w/encl: Plant Manager, Monticello John W. Ferman, Ph.D., Nuclear Engineer, MPCA State Liaison Officer, State of Minnesota

Distribution: Docket File w/encl PUBLIC IE-01 w/encl OC/LFDCB w/encl SRI Monticello, Prairie Island w/encl A. B. Beach, w/encl

DRP w/encl RIII PRR w/encl Project Manager, NRR w/encl IPAS (E-Mail) w/encl RMB/FEES w/o encl H. J. Miller, w/encl

(See attached concurrence) R:\insprpts\powers\mont\mon96002.drp To receive a copy of this document. indicate in the box "C" = Copy without attach/enc1 "E" = Copy with attach/enc1 "N" =

OFFICE	RIII	RIII	RIII	RIII É	BILI N	RIII C
NAME	O'Dwyer/ dp	Gardner (2.1.', 2.3, 5.1, and 4.1)	Caniano/K (4.1) for	(4.2,) mails		Jordan SQD far
DATE	04/ /96	C4/ /96	04/5/96	04/4/96	04/ /96	04/8/96

E. Watzl

-2-

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

M. J. Jordan, Chief Reactor Projects Branch 7

Docket No. 50-263

Enclosure: Inspection Report No. 50-263/96002(DRP)

cc w/encl: Plant Manager, Monticello John W. Ferman, Ph.D., Nuclear Engineer, MPCA State Liaison Officer, State of Minnesota

Distribution: Docket File w/encl PUBLIC IE-01 w/encl OC/LFDCB w/encl SRI Monticello, Prairie Island w/encl A. B. Beach, w/encl

DRP w/encl RIII PRR w/encl Project Manager, NRR w/encl IPAS (E-Mail) w/encl RMB/FEES w/o encl H. J. Miller, w/encl

R:\insprpts\powers\mont\mon96002.drp To receive a copy of this document, indicate in the box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" =

OFFICE	RIII	N	RIII	N	RIII		RIII
NAME	0'Dwyer/dp		Gardner (2.1.1, 2.3, 3.1, and 4.1)		Caniano (4.1)	Creed (4.1, 4.3)	Jordan
DATE	04/4/9	96	04/4/96		04/ /96	04/ /96	04/ /96

OFFICIAL RECORD COPY