DMB





P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

February 20, 1985

MURRAY R. EDELMAN VICE PRESIDENT NUCLEAR Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

> RE: Perry Nuclear Power Plant Docket Nos. 50-440; 50-441 Power Lead Gland Assemblies Supplied by Conax [RDC 114(84)]

Dear Mr. Keppler:

This letter serves as our next interim report pursuant to 10CFR50.55(e) concerning power lead gland assemblies furnished by Conax which may suffer from a loss of electrical continuity. Previously submitted correspondence on this subject was transmitted October 10, 1984.

Conax has conducted a series of tests on forty power lead gland assemblies that had been returned to them for evaluation of the parameters that may cause this potential defect. Conax is expecting to complete their evaluation and submit results to CEI on February 28, 1985. Following our receipt and review of the evaluation, we will submit our final report on this subject by March 28, 1985.

Please call if there are any additional questions.

Sincerely,

muna / Edelmen

Murray R. Edelman Vice President Nuclear Group

MRE:pab

cc: Mr. J. A. Grobe USNRC, Site Office (SBB50)

> Mr. D. E. Keating USNRC, Site Office (SBB50)

Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

U.S. Nuclear Regulatory Commission c/o Document Management Branch Washington, D.C. 20555

Records Center, SEE-IN Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

8502280111 8502 PDR ADOCK 0500 00440

FEB 2 5 1985 10 16,2